


PayComplete

Machine	SDS-500	Type	Gen 2
Part no.	5006950-XX2Y	Freq.	50/60Hz
Made in		Volt.	100-240VAC
2023	China	Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS500N
FCC ID: 2BAML-SDS5X0
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)

PayComplete

Machine	SDS-500	Type	Gen 2
Part no.	5006950-XX2Y	Freq.	50/60Hz
Made in		Volt.	100-240VAC
2023	China	Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS500RN
Contains FCC ID: 2AKQD-D100-1
FCC ID: 2BAML-SDS5X0
Contains IC: 30184-D100
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)



PayComplete

Machine	SDS-520	Type	Gen 2
Part no.	5006952-XX2Y	Freq.	50/60Hz
Made in	2023 China	Volt.	100-240VAC
		Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS520N
FCC ID: 2BAML-SDS5X0
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)

PayComplete

Machine	SDS-520	Type	Gen 2
Part no.	5006952-XX2Y	Freq.	50/60Hz
Made in	2023 China	Volt.	100-240VAC
		Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS520RN
Contains FCC ID: 2AKQD-D100-1
FCC ID: 2BAML-SDS5X0
Contains IC: 30184-D100
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)



Label
Location

PayComplete

Machine	SDS-550	Type	Gen 2
Part no.	5006955-XX2Y	Freq.	50/60Hz
Made in	2023 China	Volt.	100-240VAC
		Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS550N
FCC ID: 2BAML-SDS5X0
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)

PayComplete

Machine	SDS-550	Type	Gen 2
Part no.	5006955-XX2Y	Freq.	50/60Hz
Made in	2023 China	Volt.	100-240VAC
		Curr.	2.5A Max



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



S/N 1234567890

HVIN: SDS550RN
Contains FCC ID: 2AKQD-D100-1
FCC ID: 2BAML-SDS5X0
Contains IC: 30184-D100
IC: 30854-SDS5X0
CAN ICES-3(A)/NMB-3(A)

