



## 8. Appendix A


11A\_Ant1\_5180




11A\_Ant1\_5200




11A\_Ant1\_5240




11A\_Ant1\_5260




11A\_Ant1\_5280




11A\_Ant1\_5320




11A\_Ant1\_5500




11A\_Ant1\_5580




11A\_Ant1\_5700




11A\_Ant1\_5745




11A\_Ant1\_5785




11A\_Ant1\_5825




11N20SISO\_Ant1\_5180




11N20SISO\_Ant1\_5200




11N20SISO\_Ant1\_5240




11N20SISO\_Ant1\_5260




11N20SISO\_Ant1\_5280




11N20SISO\_Ant1\_5320




11N20SISO\_Ant1\_5500




11N20SISO\_Ant1\_5580




11N20SISO\_Ant1\_5700




11N20SISO\_Ant1\_5745




11N20SISO\_Ant1\_5785




11N20SISO\_Ant1\_5825




11N40SISO\_Ant1\_5190




11N40SISO\_Ant1\_5230




11N40SISO\_Ant1\_5270




11N40SISO\_Ant1\_5310




11N40SISO\_Ant1\_5510




11N40SISO\_Ant1\_5550




11N40SISO\_Ant1\_5670




11N40SISO\_Ant1\_5755




11N40SISO\_Ant1\_5795




11AC20SISO\_Ant1\_5180




11AC20SISO\_Ant1\_5200




11AC20SISO\_Ant1\_5240




11AC20SISO\_Ant1\_5260




11AC20SISO\_Ant1\_5280




11AC20SISO\_Ant1\_5320




11AC20SISO\_Ant1\_5500




11AC20SISO\_Ant1\_5580




11AC20SISO\_Ant1\_5700




11AC20SISO\_Ant1\_5745




11AC20SISO\_Ant1\_5785




11AC20SISO\_Ant1\_5825




11AC40SISO\_Ant1\_5190




11AC40SISO\_Ant1\_5230




11AC40SISO\_Ant1\_5270




11AC40SISO\_Ant1\_5310




11AC40SISO\_Ant1\_5510




11AC40SISO\_Ant1\_5550




11AC40SISO\_Ant1\_5670




11AC40SISO\_Ant1\_5755




11AC40SISO\_Ant1\_5795




11AC80SISO\_Ant1\_5210



11AC80SISO\_Ant1\_5290




11AC80SISO\_Ant1\_5530



11AC80SISO\_Ant1\_5610



11AC80SISO\_Ant1\_5775



## 9. CONCLUSION

The data collected relate only the item(s) tested and show that the **Motorcycle Media Players** is in compliance with Part 15E of the FCC Rules.

\_\_\_\_\_ The End \_\_\_\_\_