







12B QPSK PCC BW=5MHz Ch=5048 RB=25@0,SCC
BW=10MHz Ch=5120 RB=50@0




12B 16QAM PCC BW=5MHz Ch=5048 RB=25@0,SCC
BW=10MHz Ch=5120 RB=50@0




12B 64QAM PCC BW=5MHz Ch=5048 RB=25@0,SCC
BW=10MHz Ch=5120 RB=50@0




12B 256QAM PCC BW=5MHz Ch=5048 RB=25@0,SCC
BW=10MHz Ch=5120 RB=50@0




12B QPSK PCC BW=5MHz Ch=5107 RB=25@0,SCC
BW=5MHz Ch=5155 RB=25@0




12B 16QAM PCC BW=5MHz Ch=5107 RB=25@0,SCC
BW=5MHz Ch=5155 RB=25@0




12B 64QAM PCC BW=5MHz Ch=5107 RB=25@0,SCC
 BW=5MHz Ch=5155 RB=25@0




12B 256QAM PCC BW=5MHz Ch=5107 RB=25@0,SCC
 BW=5MHz Ch=5155 RB=25@0




12B QPSK PCC BW=5MHz Ch=5058 RB=25@0,SCC
 BW=10MHz Ch=5130 RB=50@0




12B 16QAM PCC BW=5MHz Ch=5058 RB=25@0,SCC
 BW=10MHz Ch=5130 RB=50@0




12B 64QAM PCC BW=5MHz Ch=5058 RB=25@0,SCC
 BW=10MHz Ch=5130 RB=50@0




12B 256QAM PCC BW=5MHz Ch=5058 RB=25@0,SCC
 BW=10MHz Ch=5130 RB=50@0




38C QPSK PCC BW=15MHz Ch=37825 RB=75@0,SCC
 BW=15MHz Ch=37975 RB=75@0




38C 16QAM PCC BW=15MHz Ch=37825 RB=75@0,SCC
 BW=15MHz Ch=37975 RB=75@0




38C 64QAM PCC BW=15MHz Ch=37825 RB=75@0,SCC
 BW=15MHz Ch=37975 RB=75@0




38C 256QAM PCC BW=15MHz Ch=37825 RB=75@0,SCC
 BW=15MHz Ch=37975 RB=75@0



38C QPSK PCC BW=20MHz Ch=37850 RB=100@0,SCC
 BW=20MHz Ch=38048 RB=100@0




38C 16QAM PCC BW=20MHz Ch=37850 RB=100@0,SCC
 BW=20MHz Ch=38048 RB=100@0




Date: 9.JAN.2026 15:54:42

38C 64QAM PCC BW=20MHz Ch=37850 RB=100@0,SCC
BW=20MHz Ch=38048 RB=100@0




Date: 9.JAN.2026 15:54:46

38C 256QAM PCC BW=20MHz Ch=37850 RB=100@0,SCC
BW=20MHz Ch=38048 RB=100@0




Date: 9.JAN.2026 15:54:52

38C QPSK PCC BW=15MHz Ch=37925 RB=75@0,SCC
BW=15MHz Ch=38075 RB=75@0




Date: 9.JAN.2026 15:54:56

38C 16QAM PCC BW=15MHz Ch=37925 RB=75@0,SCC
BW=15MHz Ch=38075 RB=75@0




Date: 9.JAN.2026 15:55:00

38C 64QAM PCC BW=15MHz Ch=37925 RB=75@0,SCC
BW=15MHz Ch=38075 RB=75@0




Date: 9.JAN.2026 15:55:04


38C 256QAM PCC BW=15MHz Ch=37925 RB=75@0,SCC
BW=15MHz Ch=38075 RB=75@0




38C QPSK PCC BW=20MHz Ch=37901 RB=100@0,SCC
 BW=20MHz Ch=38099 RB=100@0




38C 16QAM PCC BW=20MHz Ch=37901 RB=100@0,SCC
 BW=20MHz Ch=38099 RB=100@0




38C 64QAM PCC BW=20MHz Ch=37901 RB=100@0,SCC
 BW=20MHz Ch=38099 RB=100@0




38C 256QAM PCC BW=20MHz Ch=37901 RB=100@0,SCC
 BW=20MHz Ch=38099 RB=100@0




38C QPSK PCC BW=15MHz Ch=38025 RB=75@0,SCC
 BW=15MHz Ch=38175 RB=75@0




38C 16QAM PCC BW=15MHz Ch=38025 RB=75@0,SCC
 BW=15MHz Ch=38175 RB=75@0




38C 64QAM PCC BW=15MHz Ch=38025 RB=75@0,SCC
 BW=15MHz Ch=38175 RB=75@0




38C 256QAM PCC BW=15MHz Ch=38025 RB=75@0,SCC
 BW=15MHz Ch=38175 RB=75@0




38C QPSK PCC BW=20MHz Ch=37952 RB=100@0,SCC
 BW=20MHz Ch=38150 RB=100@0



38C 16QAM PCC BW=20MHz Ch=37952 RB=100@0,SCC
 BW=20MHz Ch=38150 RB=100@0



38C 64QAM PCC BW=20MHz Ch=37952 RB=100@0,SCC
 BW=20MHz Ch=38150 RB=100@0



38C 256QAM PCC BW=20MHz Ch=37952 RB=100@0,SCC
 BW=20MHz Ch=38150 RB=100@0