

n66 SCS=15kHz CP_256QAM BW=20MHz Channel=344000 RB=106@0 NVNT



n66 SCS=15kHz DFT_BPSK BW=20MHz Channel=349000 RB=100@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz DFT_QPSK BW=20MHz Channel=349000 RB=100@0 NVNT



n66 SCS=15kHz DFT_16QAM BW=20MHz Channel=349000 RB=100@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz DFT_64QAM BW=20MHz Channel=349000 RB=100@0 NVNT



n66 SCS=15kHz DFT_256QAM BW=20MHz Channel=349000 RB=100@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz CP_QPSK BW=20MHz Channel=349000 RB=106@0 NVNT



n66 SCS=15kHz CP_16QAM BW=20MHz Channel=349000 RB=106@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz CP_64QAM BW=20MHz Channel=349000 RB=106@0 NVNT



n66 SCS=15kHz CP_256QAM BW=20MHz Channel=349000 RB=106@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz DFT_BPSK BW=20MHz Channel=354000 RB=100@0 NVNT



n66 SCS=15kHz DFT_QPSK BW=20MHz Channel=354000 RB=100@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz DFT_16QAM BW=20MHz Channel=354000 RB=100@0 NVNT



n66 SCS=15kHz DFT_64QAM BW=20MHz Channel=354000 RB=100@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz DFT_256QAM BW=20MHz Channel=354000 RB=100@0 NVNT



n66 SCS=15kHz CP_QPSK BW=20MHz Channel=354000 RB=106@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz CP_16QAM BW=20MHz Channel=354000 RB=106@0 NVNT



n66 SCS=15kHz CP_64QAM BW=20MHz Channel=354000 RB=106@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n66 SCS=15kHz CP_256QAM BW=20MHz Channel=354000 RB=106@0 NVNT



n71 SCS=15kHz DFT_BPSK BW=5MHz Channel=133100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_QPSK BW=5MHz Channel=133100 RB=25@0 NVNT



n71 SCS=15kHz DFT_16QAM BW=5MHz Channel=133100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_64QAM BW=5MHz Channel=133100 RB=25@0 NVNT



n71 SCS=15kHz DFT_256QAM BW=5MHz Channel=133100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz CP_QPSK BW=5MHz Channel=133100 RB=25@0 NVNT



n71 SCS=15kHz CP_16QAM BW=5MHz Channel=133100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz CP_64QAM BW=5MHz Channel=133100 RB=25@0 NVNT



n71 SCS=15kHz CP_256QAM BW=5MHz Channel=133100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_BPSK BW=5MHz Channel=136100 RB=25@0 NVNT



n71 SCS=15kHz DFT_QPSK BW=5MHz Channel=136100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_16QAM BW=5MHz Channel=136100 RB=25@0 NVNT



n71 SCS=15kHz DFT_64QAM BW=5MHz Channel=136100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_256QAM BW=5MHz Channel=136100 RB=25@0 NVNT



n71 SCS=15kHz CP_QPSK BW=5MHz Channel=136100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz CP_16QAM BW=5MHz Channel=136100 RB=25@0 NVNT



n71 SCS=15kHz CP_64QAM BW=5MHz Channel=136100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz CP_256QAM BW=5MHz Channel=136100 RB=25@0 NVNT



n71 SCS=15kHz DFT_BPSK BW=5MHz Channel=139100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_QPSK BW=5MHz Channel=139100 RB=25@0 NVNT



n71 SCS=15kHz DFT_16QAM BW=5MHz Channel=139100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



n71 SCS=15kHz DFT_64QAM BW=5MHz Channel=139100 RB=25@0 NVNT



n71 SCS=15kHz DFT_256QAM BW=5MHz Channel=139100 RB=25@0 NVNT

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.