

CEREVO TECHNOLOGY LIMITED.


July 28, 2023

Subject: Tuning and Adjustment of Signal booster, FCC ID : 2BB6MT5-A, IC: 31014-T5A

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Esson Diao

A handwritten signature in black ink that reads "Esson Diao". The signature is written in a cursive, flowing style.