


QUICK START GUIDE




T1M UTILITY
DIGITAL TAPE MEASURE

NOTE: Appearances, features, and functionality may differ from the written instructions due to updates to the device software. For the latest information and additional details, please visit our website.

SETUP


STEP 1

LIFT UP THE USB-C PORT COVER AND INSERT THE PROVIDED CABLE TO CHARGE THE T1M FOR APPROXIMATELY TWO HOURS BEFORE FIRST USE.




STEP 2

PRESS ANY BUTTON ONCE TO WAKE UP YOUR T1M AND BEGIN MEASURING.



STEP 3

USE THE CAPTURE BUTTON TO SAVE MEASUREMENTS TO YOUR T1M AND THE ROCK JOBSITE APP (IF CONNECTED).



BUTTON GUIDE



- CAPTURE & EXIT:**
- Saves measurement to the saved measurements list and the ROCK Jobsite App (if connected).
 - Pressing this in the menu will always bring you to the live view display.



- QUICK ACTIONS MENU & CONFIRM**
- Select from various measuring functions and additional settings.
 - Pressing this in the menu will to enter options as well as confirm them.



- CURSOR UP/DOWN & SAVED MEASUREMENT LIST**
- After selecting the Quick Actions menu, use the arrow to move the cursor up and down.
 - When in Live View display, use either arrow to enter saved measurements list.




ONLINE TUTORIALS

Unlock the full potential of your new tool with our comprehensive online tutorials! Scan the QR code to access step-by-step guides, expert tips, and helpful videos designed to enhance your understanding and efficiency. Get started today and see how our tools can make your work easier and more accurate.

QUESTIONS? E-mail us at contact@reekon.tools

ROCK JOBSITE APP

Upgrade your projects with the ROCK Jobsite App. Compile all your measurements in an organized location. Use English or Metric units and set your desired tolerance. Easily organize measurements by tags, locations, types, and more. Add details like mitered edges, who recorded each measurement, and additional notes to stay on top of your work.



Download on the
App Store

GET IT ON
Google Play




Scan the code to connect your new device for optimized cutting, organized notes, and a seamless workflow.
Or visit: www.reekon.xyz/rock

AUTOLOCK


By default, the tape blade will remain extended and will not retract unless the Autolock button is pressed.

To enable or disable the Autolock feature, use the Autolock selection slider. Press the Autolock button, then slide the selection slider to the left to enable Autolock or to the right to disable it, as shown in the diagram.



USB-C CHARGING

To charge your T1M, locate the USB-C port cover on the side of the device and gently lift it to access the charging port. Insert the provided USB-C cable into the port, then connect the other end to a compatible power source. Check to make sure the charge icon "⚡" appears on the LCD display. Allow approximately two hours for a full charge before using the device. Once charging is complete, disconnect the cable and securely replace the port cover to protect the device.



MAINTENANCE

The T1M includes several serviceable and replaceable parts to maintain functionality and extend the tool's lifespan. For a complete list of replaceable parts and step-by-step instructions on how to replace them, please visit: support.reekon.tools



LIVE VIEW

The Live View displays all real-time information, including measurements, units, Bluetooth connection status, charging status, battery level, "light" and "heavy" measurements, as well as any active modes set by the user. This screen ensures you have all the critical data you need at a glance while using the TIM Utility.

DASHING ON SCREEN

Dashing on the display is a built-in feature of the TIM Utility designed to prevent incorrect measurements from appearing on the screen. Seeing dashes is a normal part of TIM operation and reflects the robust error-checking and redundancy features of its encoding system.



Dashing may occur during initial startup, routine use, or other conditions. To recalibrate the position, extend and retract the tape measure blade. The TIM will quickly determine its position and display the correct measurement on the screen.

LIGHT AND HEAVY MEASUREMENTS

"Light" and "heavy" measurements on a tape measure refer to measurements without markings on the tape blade.

There is a compromise between speed and accuracy displayed; it is easier to read in 1/16s than in 1/64s. To help capture the best of both speed and accuracy, an "X" marker has been added to help show how close a measurement is to the given fractional unit.

The X Indicates measurements that have markings, while arrows < > in either direction indicates the direction of travel to hit the mark.



NOTE: Slowly extend and/or retract the tape measure blade to allow the TIM to locate its position.



NOTE: This feature is only present in fractional modes.

MAIN MENU

For detailed instructions on how to use each of the menu options, including C1 Mode, Beeping Sound, Offset Change, Bluetooth Status, Bluetooth Mode, Keyboard Ending, Keyboard Local, Blade Setup, and Factory Reset, please scan the qr code on the front or visit: www.support.reekon.tools


Here you'll find comprehensive guides and troubleshooting tips to help you get the most out of your TIM.



BLADE HOOK

When measuring the outside of a surface, hook the metal end over the edge. The hook will slide away from the case, creating a gap equal to the hook's thickness, which is 0.05 of an inch. This gap means you don't need to count the hook's thickness in your measurement.


When measuring the inside of a surface, push the hook against the inside of the material. The hook will move towards the case, becoming part of the measurement.



QUICK ACTIONS

- 1. Press [F1] until you see the Quick Action Menu popup on the display.
- 2. Using the [Left] [Right] arrows, highlight the quick action you would like to use.
- 3. Press [F1] to make your selection and exit.

NOTE: You can select multiple Quick Actions to use simultaneously. To turn off a recently used Quick Action, repeat steps 1-3. To turn off all Quick Actions, select the "CLEAR" option.



Note: Active Quick Actions are represented by the rectangle to the left of the option.

MEASURE FRONT/BACK

Measure either from the front reference surface or from the back of the device. Measuring from the back allows the TIM to capture internal measurements effortlessly.

MEASURE RELATIVE

Users select a "0" position at any point along the tape measure, creating a custom starting point. This allows for easy calculation of distances relative to that reference.

SHOW CENTER

Display the center of any given measurement, removing the mental math from the equation.

MARKING SQUARE

The TIM features a detachable, metal-reinforced Marking Square for enhanced alignment and scribing. Stored within the tool, it can be attached in multiple positions to extend the front alignment surface, allowing for precise marking and scribing.

PUSH TAB SLIDE DOWN

Press the tab located at the bottom of the TIM, and slide the Marking Square out of its position.

ALIGN PUSH IN

Decide on the orientation you would like to attach the square to the front of the TIM by pressing into the groove to lock in place.

Once attached, flip the TIM over, take your measurements, and mark your lines.

ALIGN TOP LEFT


ALIGN TOP RIGHT

ALIGN SIDE RIGHT

ALIGN SIDE LEFT


UNITS

- 1. Press [F1] until the Quick Action Menu pops up on the display.
- 2. Using the [Left] [Right] arrows, highlight the Units menu.
- 3. Press [F1] to enter the menu selection.
- 4. Using the [Left] [Right] arrows, highlight the unit you would like to use.
- 5. Press [F1] to save and exit.




SAVED MEASUREMENT LIST

- 1. Press [Left] or [Right] until the Saved Measurement List pops up on the display.
- 2. Using the [Left] [Right] arrows, highlight the measurement would like to view.
- 3. Press [F1] to exit.



DELETE MEASUREMENTS

- 1. Press [F1] on the highlighted measurement.
- 2. Using the [Left] [Right] arrows, scroll to the delete or delete all button.
- 3. Press [F1] to confirm the selection.



USER SAFETY

⚠ **WARNING:** To reduce the risk of injury, the user must carefully read the TIM QUICK START GUIDE. The person responsible for the TIM must ensure that all users understand and comply with the instructions.

⚠ **WARNING:** Tape blade is electrically conductive. Do not use near bare wires.

INTENDED USE
DO NOT use under wet conditions or in the presence of flammable liquids or gases. DO NOT replace any component of the TIM Utility with a component that is not supplied by REECON Tools. DO NOT store or use the tool in locations where the temperature may exceed 140 °F (60 °C) or drop below -4 °F (-20 °C). Best use in relative humidity conditions of 8% to 80% non-condensing and altitudes no higher than 9,842ft (3,000 m). For best performance operation of the device should take place in cool, dry conditions.

FCC COMPLIANCE
This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Any Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. The device has been evaluated to meet general RF exposure requirement. The device can be used without restriction between the radiator and your body.

ISED CANADA COMPLIANCE
This radio transmitter has been approved by ISED Canada. This Class B digital apparatus complies with Canadian standard ICES-003. This device complies with ISED Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference, that may cause undesired operation of the device.

This equipment complies with ISED radiation exposure limits set forth for an uncontrolled environment. The device has been evaluated to meet general RF exposure requirement. The device can be used without restriction between the radiator and your body.

Le présent appareil est conforme aux CNR d'ISDE Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

L'appareil a été évalué pour répondre aux exigences générales d'exposition aux RF. L'appareil peut être utilisé sans restriction entre le radiateur et votre corps.

TECHNICAL ASSISTANCE & REPAIR
For questions about applications, technical support, repair or more information, please see our website: <https://www.reekon.tools>



The product specifications are subject to change without notice. REECON Tools, Inc. reserves all rights to final interpretation. All trademarks, product images, and technical specifications are the property of REECON Tools, Inc. All rights reserved.

Product of Thailand | Finished in China



✉ contact@reekon.tools
🌐 www.reekon.tools

This user manual is applicable for the following model numbers :
RKN-TIM-16-001, RKN-TIM-16-002,
RKN-TIM-16-003, RKN-TIM-25-001,
RKN-TIM-25-002, RKN-TIM-25-003