


Tx. Spurious NVNT g 2462MHz Ant4 Emission



Tx. Spurious NVNT n20 2412MHz Ant3 Ref




Tx. Spurious NVNT n20 2412MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2412MHz Ant4 Ref



Tx. Spurious NVNT n20 2412MHz Ant4 Emission




Tx. Spurious NVNT n20 2417MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2417MHz Ant3 Emission



Tx. Spurious NVNT n20 2417MHz Ant4 Ref




Tx. Spurious NVNT n20 2417MHz Ant4 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2437MHz Ant3 Ref



Tx. Spurious NVNT n20 2437MHz Ant3 Emission




Tx. Spurious NVNT n20 2437MHz Ant4 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2437MHz Ant4 Emission



Tx. Spurious NVNT n20 2457MHz Ant3 Ref




Tx. Spurious NVNT n20 2457MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2457MHz Ant4 Ref



Tx. Spurious NVNT n20 2457MHz Ant4 Emission




Tx. Spurious NVNT n20 2462MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n20 2462MHz Ant3 Emission



Tx. Spurious NVNT n20 2462MHz Ant4 Ref




Tx. Spurious NVNT n20 2462MHz Ant4 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2422MHz Ant3 Ref



Tx. Spurious NVNT n40 2422MHz Ant3 Emission




Tx. Spurious NVNT n40 2422MHz Ant4 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2422MHz Ant4 Emission



Tx. Spurious NVNT n40 2427MHz Ant3 Ref




Tx. Spurious NVNT n40 2427MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2427MHz Ant4 Ref



Tx. Spurious NVNT n40 2427MHz Ant4 Emission




Tx. Spurious NVNT n40 2437MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2437MHz Ant3 Emission



Tx. Spurious NVNT n40 2437MHz Ant4 Ref




Tx. Spurious NVNT n40 2437MHz Ant4 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2447MHz Ant3 Ref



Tx. Spurious NVNT n40 2447MHz Ant3 Emission




Tx. Spurious NVNT n40 2447MHz Ant4 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2447MHz Ant4 Emission



Tx. Spurious NVNT n40 2452MHz Ant3 Ref




Tx. Spurious NVNT n40 2452MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT n40 2452MHz Ant4 Ref



Tx. Spurious NVNT n40 2452MHz Ant4 Emission




Tx. Spurious NVNT ax20 2412MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2412MHz Ant3 Emission




	Mode	Trace	Scale	X	Y	Function	Function Width	Function Value
1	N	1	f	2.418 5 GHz	7.012 dBm			
2	N	1	f	26.342 1 GHz	-37.36 dBm			
3	N	1	f	5.007 2 GHz	-40.06 dBm			
4	N	1	f	7.287 2 GHz	-41.45 dBm			
5	N	1	f	9.734 8 GHz	-41.47 dBm			
6								

Tx. Spurious NVNT ax20 2412MHz Ant4 Ref




Tx. Spurious NVNT ax20 2412MHz Ant4 Emission




	Mode	Trace	Scale	X	Y	Function	Function Width	Function Value
1	N	1	f	2.409 7 GHz	7.886 dBm			
2	N	1	f	26.179 7 GHz	-37.92 dBm			
3	N	1	f	4.872 2 GHz	-41.22 dBm			
4	N	1	f	7.377 2 GHz	-41.71 dBm			
5	N	1	f	9.823 0 GHz	-42.37 dBm			
6								

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2417MHz Ant3 Ref



Tx. Spurious NVNT ax20 2417MHz Ant3 Emission




Tx. Spurious NVNT ax20 2417MHz Ant4 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2417MHz Ant4 Emission



Tx. Spurious NVNT ax20 2437MHz Ant3 Ref




Tx. Spurious NVNT ax20 2437MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2437MHz Ant4 Ref



Tx. Spurious NVNT ax20 2437MHz Ant4 Emission




Tx. Spurious NVNT ax20 2457MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2457MHz Ant3 Emission



Tx. Spurious NVNT ax20 2457MHz Ant4 Ref




Tx. Spurious NVNT ax20 2457MHz Ant4 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2462MHz Ant3 Ref



Tx. Spurious NVNT ax20 2462MHz Ant3 Emission




Tx. Spurious NVNT ax20 2462MHz Ant4 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax20 2462MHz Ant4 Emission



Tx. Spurious NVNT ax40 2422MHz Ant3 Ref




Tx. Spurious NVNT ax40 2422MHz Ant3 Emission




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax40 2422MHz Ant4 Ref



Tx. Spurious NVNT ax40 2422MHz Ant4 Emission




Tx. Spurious NVNT ax40 2427MHz Ant3 Ref




This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Tx. Spurious NVNT ax40 2427MHz Ant3 Emission



Tx. Spurious NVNT ax40 2427MHz Ant4 Ref



Tx. Spurious NVNT ax40 2427MHz Ant4 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.