






Date: 13.JUN.2024 21:05:41

11N40SISO_Ant1_5190




Date: 13.JUN.2024 21:53:43

11N40SISO_Ant1_5230




Date: 14.JUN.2024 08:44:15


11N40SISO_Ant1_5755




11N40SISO_Ant1_5795



11AC20SISO_Ant1_5180




11AC20SISO_Ant1_5200




Date: 13.JUN.2024 21:14:50

11AC20SISO_Ant1_5240




Date: 13.JUN.2024 21:17:54

11AC20SISO_Ant1_5745




Date: 13.JUN.2024 21:21:46

11AC20SISO_Ant1_5785




Date: 13.JUN.2024 21:25:39

11AC20SISO_Ant1_5825




Date: 13.JUN.2024 21:28:12

11AC40SISO_Ant1_5190




Date: 14.JUN.2024 09:30:20

11AC40SISO_Ant1_5230




Date: 14.JUN.2024 09:34:23

11AC40SISO_Ant1_5755




Date: 14.JUN.2024 09:05:51

11AC40SISO_Ant1_5795




Date: 14.JUN.2024 09:13:25


11AX20SISO_Ant1_5180




11AX20SISO_Ant1_5200



11AX20SISO_Ant1_5240




11AX20SISO_Ant1_5745




Date: 13.JUN.2024 21:41:56

11AX20SISO_Ant1_5785




Date: 13.JUN.2024 21:45:50

11AX20SISO_Ant1_5825




Date: 13.JUN.2024 21:49:13

11AX40SISO_Ant1_5190




Date: 14.JUN.2024 09:38:29

11AX40SISO_Ant1_5230




Date: 14.JUN.2024 09:44:27

11AX40SISO_Ant1_5755



Date: 14.JUN.2024 09:18:37

11AX40SISO_Ant1_5795



-----End of the report-----