LABEL AND LOCATION

FCC ID: 2BDSV24230

Part 15.19 warning label