

MURPHY'S BOWL LLC
10400 NE 4th Street, Suite 3000
Bellevue, Washington 98004

April 7, 2024

Nemko North America, Inc.
303 River Road, Ottawa, ON K1V 1H2 Canada
Attn: Director of Certification

FCC ID: 2BE69-MBAP01
Models: MBAP v1.0, MBAP nUWB v1.0

Family Certification request letter

We hereby request Family Certification for the above mentioned HVINs/Models based on them being electrically, and physically identical apart from model 'MBAP nUWB 1.0'.

For model 'MBAP nUWB v1.0', the Ultra-Wide Band (UWB) radio (FCC ID VPYLB2BP) is not being populated on the PCBA - the models are electrically identical otherwise. With this exception, circuitry, components, layout, enclosure and assembly are otherwise identical between the models.

The included antennas and their gains in model 'MBAP nUWB v1.0' are identical as well, except for the UWB antenna not being actively driven due to the associated radio not being stuffed on the PCBA.

Sincerely,

Signed by:

DocuSigned by:
Brandt Vaughan
FECB38767E40422...
Signature

Brandt Vaughan

Print name

President - Corporate

Title

+1 (425) 242-6391

Phone

Murphy's Bowl LLC

Company Name