




Freq. Stability 30C 12V ac160 5250MHz Ant1 0 Minutes




Freq. Stability 40C 12V ac160 5250MHz Ant1 0 Minutes




Freq. Stability 50C 12V ac160 5250MHz Ant1 0 Minutes




Freq. Stability 20C 10.2V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 13.8V ac160 5570MHz Ant1 0 Minutes




Freq. Stability -20C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability -10C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 0C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 10C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 30C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 40C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 50C 12V ac160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 10.2V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 13.8V ac160 5250MHz Ant2 0 Minutes



Freq. Stability -20C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability -10C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 0C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 10C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 30C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 40C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 50C 12V ac160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 10.2V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 13.8V ac160 5570MHz Ant2 0 Minutes




Freq. Stability -20C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability -10C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 0C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 10C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 30C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 40C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 50C 12V ac160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 10.2V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 13.8V ac160 5250MHz Ant3 0 Minutes




Freq. Stability -20C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability -10C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 0C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 10C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 30C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 40C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 50C 12V ac160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 10.2V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 20C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 20C 13.8V ac160 5570MHz Ant3 0 Minutes




Freq. Stability -20C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability -10C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 0C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 10C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 30C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 40C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 50C 12V ac160 5570MHz Ant3 0 Minutes




Freq. Stability 20C 10.2V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 20C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 20C 13.8V ax160 5250MHz Ant1 0 Minutes




Freq. Stability -20C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability -10C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 0C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 10C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 30C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 40C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 50C 12V ax160 5250MHz Ant1 0 Minutes




Freq. Stability 20C 10.2V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 13.8V ax160 5570MHz Ant1 0 Minutes




Freq. Stability -20C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability -10C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 0C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 10C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 30C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 40C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 50C 12V ax160 5570MHz Ant1 0 Minutes




Freq. Stability 20C 10.2V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 13.8V ax160 5250MHz Ant2 0 Minutes




Freq. Stability -20C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability -10C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 0C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 10C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 30C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 40C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 50C 12V ax160 5250MHz Ant2 0 Minutes




Freq. Stability 20C 10.2V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 13.8V ax160 5570MHz Ant2 0 Minutes




Freq. Stability -20C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability -10C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 0C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 10C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 30C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 40C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 50C 12V ax160 5570MHz Ant2 0 Minutes




Freq. Stability 20C 10.2V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 13.8V ax160 5250MHz Ant3 0 Minutes




Freq. Stability -20C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability -10C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 0C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 10C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 30C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 40C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 50C 12V ax160 5250MHz Ant3 0 Minutes




Freq. Stability 20C 10.2V ax160 5570MHz Ant3 0 Minutes




Freq. Stability 20C 12V ax160 5570MHz Ant3 0 Minutes




Freq. Stability 20C 13.8V ax160 5570MHz Ant3 0 Minutes




Freq. Stability -20C 12V ax160 5570MHz Ant3 0 Minutes



Freq. Stability -10C 12V ax160 5570MHz Ant3 0 Minutes



Freq. Stability 0C 12V ax160 5570MHz Ant3 0 Minutes



Freq. Stability 10C 12V ax160 5570MHz Ant3 0 Minutes

