








NTNV-11AC40MIMO-Ant1-5190




NTNV-11AC40MIMO-Ant2-5190


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40MIMO-Ant1-5230




NTNV-11AC40MIMO-Ant2-5230

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix C: Maximum Conducted Output Power

Test Result Channel Power

Test Mode	Antenna	Frequency[MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	5180	13.96	≤23.98	PASS
11A	Ant2	5180	14.32	≤23.98	PASS
11A	Ant1	5200	14.03	≤23.98	PASS
11A	Ant2	5200	14.34	≤23.98	PASS
11A	Ant1	5240	13.94	≤23.98	PASS
11A	Ant2	5240	14.10	≤23.98	PASS
11A	Ant1	5745	13.95	≤30.00	PASS
11A	Ant2	5745	14.18	≤30.00	PASS
11A	Ant1	5785	13.76	≤30.00	PASS
11A	Ant2	5785	13.86	≤30.00	PASS
11A	Ant1	5825	13.26	≤30.00	PASS
11A	Ant2	5825	13.40	≤30.00	PASS
11N20MIMO	Ant1	5180	13.76	≤23.09	PASS
11N20MIMO	Ant2	5180	13.75	≤23.09	PASS
11N20MIMO	total	5180	16.77	≤23.09	PASS
11N20MIMO	Ant1	5200	13.83	≤23.09	PASS
11N20MIMO	Ant2	5200	13.83	≤23.09	PASS
11N20MIMO	total	5200	16.84	≤23.09	PASS
11N20MIMO	Ant1	5240	13.58	≤23.09	PASS
11N20MIMO	Ant2	5240	13.57	≤23.09	PASS
11N20MIMO	total	5240	16.59	≤23.09	PASS
11N20MIMO	Ant1	5745	13.49	≤28.62	PASS
11N20MIMO	Ant2	5745	13.48	≤28.62	PASS
11N20MIMO	total	5745	16.50	≤28.62	PASS
11N20MIMO	Ant1	5785	13.30	≤28.62	PASS
11N20MIMO	Ant2	5785	13.29	≤28.62	PASS
11N20MIMO	total	5785	16.31	≤28.62	PASS
11N20MIMO	Ant1	5825	12.81	≤28.62	PASS
11N20MIMO	Ant2	5825	12.81	≤28.62	PASS
11N20MIMO	total	5825	15.82	≤28.62	PASS
11N40MIMO	Ant1	5190	13.38	≤23.09	PASS
11N40MIMO	Ant2	5190	13.38	≤23.09	PASS
11N40MIMO	total	5190	16.39	≤23.09	PASS
11N40MIMO	Ant1	5230	13.19	≤23.09	PASS
11N40MIMO	Ant2	5230	13.19	≤23.09	PASS
11N40MIMO	total	5230	16.20	≤23.09	PASS
11N40MIMO	Ant1	5755	13.09	≤28.62	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11N40MIMO	Ant2	5755	13.15	≤28.62	PASS
11N40MIMO	total	5755	16.13	≤28.62	PASS
11N40MIMO	Ant1	5795	12.93	≤28.62	PASS
11N40MIMO	Ant2	5795	12.79	≤28.62	PASS
11N40MIMO	total	5795	15.87	≤28.62	PASS
11AC20MIMO	Ant1	5180	14.06	≤23.09	PASS
11AC20MIMO	Ant2	5180	14.06	≤23.09	PASS
11AC20MIMO	total	5180	17.07	≤23.09	PASS
11AC20MIMO	Ant1	5200	14.10	≤23.09	PASS
11AC20MIMO	Ant2	5200	14.03	≤23.09	PASS
11AC20MIMO	total	5200	17.08	≤23.09	PASS
11AC20MIMO	Ant1	5240	13.89	≤23.09	PASS
11AC20MIMO	Ant2	5240	13.89	≤23.09	PASS
11AC20MIMO	total	5240	16.90	≤23.09	PASS
11AC20MIMO	Ant1	5745	13.82	≤28.62	PASS
11AC20MIMO	Ant2	5745	13.83	≤28.62	PASS
11AC20MIMO	total	5745	16.84	≤28.62	PASS
11AC20MIMO	Ant1	5785	13.62	≤28.62	PASS
11AC20MIMO	Ant2	5785	13.62	≤28.62	PASS
11AC20MIMO	total	5785	16.63	≤28.62	PASS
11AC20MIMO	Ant1	5825	13.63	≤28.62	PASS
11AC20MIMO	Ant2	5825	13.62	≤28.62	PASS
11AC20MIMO	total	5825	16.64	≤28.62	PASS
11AC40MIMO	Ant1	5190	14.25	≤23.09	PASS
11AC40MIMO	Ant2	5190	14.26	≤23.09	PASS
11AC40MIMO	total	5190	17.27	≤23.09	PASS
11AC40MIMO	Ant1	5230	13.96	≤23.09	PASS
11AC40MIMO	Ant2	5230	13.96	≤23.09	PASS
11AC40MIMO	total	5230	16.97	≤23.09	PASS
11AC40MIMO	Ant1	5755	13.76	≤28.62	PASS
11AC40MIMO	Ant2	5755	13.71	≤28.62	PASS
11AC40MIMO	total	5755	16.75	≤28.62	PASS
11AC40MIMO	Ant1	5795	13.48	≤28.62	PASS
11AC40MIMO	Ant2	5795	13.48	≤28.62	PASS
11AC40MIMO	total	5795	16.49	≤28.62	PASS
11AC80MIMO	Ant1	5210	13.58	≤23.09	PASS
11AC80MIMO	Ant2	5210	13.52	≤23.09	PASS
11AC80MIMO	total	5210	16.56	≤23.09	PASS
11AC80MIMO	Ant1	5775	13.20	≤28.62	PASS
11AC80MIMO	Ant2	5775	13.21	≤28.62	PASS
11AC80MIMO	total	5775	16.22	≤28.62	PASS


Note: 1.The cable loss are compensated in the graph.


Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Test Graphs Channel Power









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





















Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Appendix D: Maximum Power Spectral Density

Test Result B1

Test Mode	Antenna	Frequency[MHz]	Result [dBm/MHz]	Limit[dBm/MHz]	Verdict
11A	Ant1	5180	4.45	≤11.00	PASS
11A	Ant2	5180	4.36	≤11.00	PASS
11A	Ant1	5200	3.91	≤11.00	PASS
11A	Ant2	5200	4.53	≤11.00	PASS
11A	Ant1	5240	3.92	≤11.00	PASS
11A	Ant2	5240	4.09	≤11.00	PASS
11N20MIMO	Ant1	5180	4.32	≤10.11	PASS
11N20MIMO	Ant2	5180	3.93	≤10.11	PASS
11N20MIMO	total	5180	7.14	≤10.11	PASS
11N20MIMO	Ant1	5200	4.08	≤10.11	PASS
11N20MIMO	Ant2	5200	4.03	≤10.11	PASS
11N20MIMO	total	5200	7.07	≤10.11	PASS
11N20MIMO	Ant1	5240	3.90	≤10.11	PASS
11N20MIMO	Ant2	5240	3.47	≤10.11	PASS
11N20MIMO	total	5240	6.70	≤10.11	PASS
11N40MIMO	Ant1	5190	1.03	≤10.11	PASS
11N40MIMO	Ant2	5190	1.05	≤10.11	PASS
11N40MIMO	total	5190	4.05	≤10.11	PASS
11N40MIMO	Ant1	5230	1.17	≤10.11	PASS
11N40MIMO	Ant2	5230	1.57	≤10.11	PASS
11N40MIMO	total	5230	4.38	≤10.11	PASS
11AC20MIMO	Ant1	5180	4.33	≤10.11	PASS
11AC20MIMO	Ant2	5180	4.17	≤10.11	PASS
11AC20MIMO	total	5180	7.26	≤10.11	PASS
11AC20MIMO	Ant1	5200	3.86	≤10.11	PASS
11AC20MIMO	Ant2	5200	4.15	≤10.11	PASS
11AC20MIMO	total	5200	7.02	≤10.11	PASS
11AC20MIMO	Ant1	5240	3.70	≤10.11	PASS
11AC20MIMO	Ant2	5240	4.25	≤10.11	PASS
11AC20MIMO	total	5240	6.99	≤10.11	PASS
11AC40MIMO	Ant1	5190	1.12	≤10.11	PASS
11AC40MIMO	Ant2	5190	1.16	≤10.11	PASS
11AC40MIMO	total	5190	4.15	≤10.11	PASS
11AC40MIMO	Ant1	5230	1.78	≤10.11	PASS
11AC40MIMO	Ant2	5230	1.11	≤10.11	PASS
11AC40MIMO	total	5230	4.47	≤10.11	PASS
11AC80MIMO	Ant1	5210	-2.32	≤10.11	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC80MIMO	Ant2	5210	-2.73	≤ 10.11	PASS
11AC80MIMO	total	5210	0.49	≤ 10.11	PASS

Note: 1.The cable loss are compensated in the graph.

Test Result B4

Test Mode	Antenna	Frequency[MHz]	Result [dBm/500KHz]	Limit[dBm/500KHz]	Verdict
11A	Ant1	5745	1.17	≤30.00	PASS
11A	Ant2	5745	1.91	≤30.00	PASS
11A	Ant1	5785	1.29	≤30.00	PASS
11A	Ant2	5785	1.12	≤30.00	PASS
11A	Ant1	5825	1.01	≤30.00	PASS
11A	Ant2	5825	0.99	≤30.00	PASS
11N20MIMO	Ant1	5745	1.20	≤28.62	PASS
11N20MIMO	Ant2	5745	1.72	≤28.62	PASS
11N20MIMO	total	5745	4.48	≤28.62	PASS
11N20MIMO	Ant1	5785	1.24	≤28.62	PASS
11N20MIMO	Ant2	5785	1.12	≤28.62	PASS
11N20MIMO	total	5785	4.19	≤28.62	PASS
11N20MIMO	Ant1	5825	0.75	≤28.62	PASS
11N20MIMO	Ant2	5825	1.31	≤28.62	PASS
11N20MIMO	total	5825	4.05	≤28.62	PASS
11N40MIMO	Ant1	5755	-1.66	≤28.62	PASS
11N40MIMO	Ant2	5755	-1.49	≤28.62	PASS
11N40MIMO	total	5755	1.44	≤28.62	PASS
11N40MIMO	Ant1	5795	-1.33	≤28.62	PASS
11N40MIMO	Ant2	5795	-1.35	≤28.62	PASS
11N40MIMO	total	5795	1.67	≤28.62	PASS
11AC20MIMO	Ant1	5745	0.86	≤28.62	PASS
11AC20MIMO	Ant2	5745	0.94	≤28.62	PASS
11AC20MIMO	total	5745	3.91	≤28.62	PASS
11AC20MIMO	Ant1	5785	0.85	≤28.62	PASS
11AC20MIMO	Ant2	5785	0.74	≤28.62	PASS
11AC20MIMO	total	5785	3.81	≤28.62	PASS
11AC20MIMO	Ant1	5825	0.78	≤28.62	PASS
11AC20MIMO	Ant2	5825	1.17	≤28.62	PASS
11AC20MIMO	total	5825	3.99	≤28.62	PASS
11AC40MIMO	Ant1	5755	-1.86	≤28.62	PASS
11AC40MIMO	Ant2	5755	-1.82	≤28.62	PASS
11AC40MIMO	total	5755	1.17	≤28.62	PASS
11AC40MIMO	Ant1	5795	-1.96	≤28.62	PASS
11AC40MIMO	Ant2	5795	-1.63	≤28.62	PASS
11AC40MIMO	total	5795	1.22	≤28.62	PASS
11AC80MIMO	Ant1	5775	-5.19	≤28.62	PASS
11AC80MIMO	Ant2	5775	-5.33	≤28.62	PASS
11AC80MIMO	total	5775	-2.25	≤28.62	PASS


Note: 1.The cable loss are compensated in the graph.

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test Graphs B1



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com







Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5240-PASS




11N20MIMO-Ant2-5240-PASS



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11AC20MIMO-Ant1-5180-PASS




11AC20MIMO-Ant2-5180-PASS




11AC20MIMO-Ant1-5200-PASS



11AC20MIMO-Ant2-5200-PASS



11AC20MIMO-Ant1-5240-PASS




11AC20MIMO-Ant2-5240-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11AC40MIMO-Ant1-5190-PASS




11AC40MIMO-Ant2-5190-PASS




11AC40MIMO-Ant1-5230-PASS



11AC40MIMO-Ant2-5230-PASS




11AC80MIMO-Ant1-5210-PASS



11AC80MIMO-Ant2-5210-PASS


Test Graphs B4



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11N20MIMO-Ant1-5745-PASS




11N20MIMO-Ant2-5745-PASS







11N20MIMO-Ant1-5825-PASS




11N20MIMO-Ant2-5825-PASS



11N40MIMO-Ant1-5755-PASS




11N40MIMO-Ant2-5755-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11AC20MIMO-Ant1-5745-PASS




11AC20MIMO-Ant2-5745-PASS




11AC20MIMO-Ant1-5785-PASS




11AC20MIMO-Ant2-5785-PASS




11AC20MIMO-Ant1-5825-PASS




11AC20MIMO-Ant2-5825-PASS




11AC40MIMO-Ant1-5755-PASS




11AC40MIMO-Ant2-5755-PASS




11AC40MIMO-Ant1-5795-PASS



11AC40MIMO-Ant2-5795-PASS



11AC80MIMO-Ant1-5775-PASS



11AC80MIMO-Ant2-5775-PASS

Appendix E: Band edge measurements

Test Result B1

Test Mode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5180	-35.79	≤-27	PASS
11A	Ant2	Low	5180	-34.67	≤-27	PASS
11A	Ant1	High	5240	-44.56	≤-27	PASS
11A	Ant2	High	5240	-42.74	≤-27	PASS
11N20MIMO	Ant1	Low	5180	-35.06	≤-27	PASS
11N20MIMO	Ant2	Low	5180	-33.96	≤-27	PASS
11N20MIMO	Ant1	High	5240	-44.37	≤-27	PASS
11N20MIMO	Ant2	High	5240	-42.82	≤-27	PASS
11N40MIMO	Ant1	Low	5190	-35.41	≤-27	PASS
11N40MIMO	Ant2	Low	5190	-33.99	≤-27	PASS
11N40MIMO	Ant1	High	5230	-41.54	≤-27	PASS
11N40MIMO	Ant2	High	5230	-42.69	≤-27	PASS
11AC20MIMO	Ant1	Low	5180	-35.70	≤-27	PASS
11AC20MIMO	Ant2	Low	5180	-33.74	≤-27	PASS
11AC20MIMO	Ant1	High	5240	-44.34	≤-27	PASS
11AC20MIMO	Ant2	High	5240	-42.80	≤-27	PASS
11AC40MIMO	Ant1	Low	5190	-35.86	≤-27	PASS
11AC40MIMO	Ant2	Low	5190	-34.61	≤-27	PASS
11AC40MIMO	Ant1	High	5230	-44.28	≤-27	PASS
11AC40MIMO	Ant2	High	5230	-43.09	≤-27	PASS
11AC80MIMO	Ant2	High	5210	-42.28	≤-27	PASS
11AC80MIMO	Ant1	Low	5210	-33.71	≤-27	PASS
11AC80MIMO	Ant1	High	5210	-43.82	≤-27	PASS
11AC80MIMO	Ant2	Low	5210	-32.22	≤-27	PASS

Note: 1.The Antenna gain and cable loss are compensated in the graph.

Test Result B4

Test Mode	Antenna	Ch. Name	Frequency[MHz]	FreqRange [MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	Low	5745	5720~5725	-40.01	≤16.36	PASS
11A	Ant1	Low	5745	5700~5720	-39.01	≤10.28	PASS
11A	Ant1	Low	5745	5650~5700	-43.30	≤-26.75	PASS
11A	Ant1	Low	5745	5645~5650	-43.23	≤-27	PASS
11A	Ant2	Low	5745	5720~5725	-43.53	≤15.98	PASS
11A	Ant2	Low	5745	5700~5720	-42.08	≤10.84	PASS
11A	Ant2	Low	5745	5650~5700	-45.41	≤-26.26	PASS
11A	Ant2	Low	5745	5645~5650	-46.01	≤-27	PASS
11A	Ant1	High	5825	5850~5855	-41.79	≤15.65	PASS
11A	Ant1	High	5825	5855~5875	-41.56	≤10.13	PASS
11A	Ant1	High	5825	5875~5925	-43.77	≤-26.87	PASS
11A	Ant1	High	5825	5925~5935	-42.56	≤-27	PASS
11A	Ant2	High	5825	5850~5855	-42.54	≤15.65	PASS
11A	Ant2	High	5825	5855~5875	-43.09	≤10.57	PASS
11A	Ant2	High	5825	5875~5925	-46.00	≤-26.87	PASS
11A	Ant2	High	5825	5925~5935	-44.21	≤-27	PASS
11N20MI MO	Ant1	Low	5745	5720~5725	-33.67	≤15.98	PASS
11N20MI MO	Ant1	Low	5745	5700~5720	-37.22	≤11.26	PASS
11N20MI MO	Ant1	Low	5745	5650~5700	-42.20	≤-25.52	PASS
11N20MI MO	Ant1	Low	5745	5645~5650	-43.31	≤-27	PASS
11N20MI MO	Ant2	Low	5745	5720~5725	-37.20	≤15.98	PASS
11N20MI MO	Ant2	Low	5745	5700~5720	-35.85	≤14.99	PASS
11N20MI MO	Ant2	Low	5745	5650~5700	-46.11	≤-26.63	PASS
11N20MI MO	Ant2	Low	5745	5645~5650	-45.38	≤-27	PASS
11N20MI MO	Ant1	High	5825	5850~5855	-42.02	≤15.65	PASS
11N20MI MO	Ant1	High	5825	5855~5875	-41.02	≤10.79	PASS
11N20MI MO	Ant1	High	5825	5875~5925	-41.51	≤-26.15	PASS
11N20MI	Ant1	High	5825	5925~5935	-41.48	≤-27	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

MO							
11N20MI MO	Ant2	High	5825	5850~5855	-43.74	≤15.65	PASS
11N20MI MO	Ant2	High	5825	5855~5875	-44.16	≤10.68	PASS
11N20MI MO	Ant2	High	5825	5875~5925	-46.29	≤-26.87	PASS
11N20MI MO	Ant2	High	5825	5925~5935	-45.17	≤-27	PASS
11N40MI MO	Ant1	Low	5755	5720~5725	-32.72	≤15.90	PASS
11N40MI MO	Ant1	Low	5755	5700~5720	-32.67	≤14.87	PASS
11N40MI MO	Ant1	Low	5755	5650~5700	-42.92	≤-25.92	PASS
11N40MI MO	Ant1	Low	5755	5645~5650	-40.62	≤-27	PASS
11N40MI MO	Ant2	Low	5755	5720~5725	-37.05	≤15.90	PASS
11N40MI MO	Ant2	Low	5755	5700~5720	-35.87	≤14.76	PASS
11N40MI MO	Ant2	Low	5755	5650~5700	-44.21	≤-26.21	PASS
11N40MI MO	Ant2	Low	5755	5645~5650	-44.62	≤-27	PASS
11N40MI MO	Ant1	High	5795	5850~5855	-40.19	≤15.85	PASS
11N40MI MO	Ant1	High	5795	5855~5875	-40.10	≤11.14	PASS
11N40MI MO	Ant1	High	5795	5875~5925	-42.31	≤-26.97	PASS
11N40MI MO	Ant1	High	5795	5925~5935	-42.05	≤-27	PASS
11N40MI MO	Ant2	High	5795	5850~5855	-42.07	≤18.03	PASS
11N40MI MO	Ant2	High	5795	5855~5875	-43.17	≤11.08	PASS
11N40MI MO	Ant2	High	5795	5875~5925	-45.90	≤-26.61	PASS
11N40MI MO	Ant2	High	5795	5925~5935	-45.83	≤-27	PASS
11AC20M IMO	Ant1	Low	5745	5720~5725	-36.09	≤17.12	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC20M IMO	Ant1	Low	5745	5700~5720	-39.65	≤12.19	PASS
11AC20M IMO	Ant1	Low	5745	5650~5700	-43.35	≤-26.88	PASS
11AC20M IMO	Ant1	Low	5745	5645~5650	-43.14	≤-27	PASS
11AC20M IMO	Ant2	Low	5745	5720~5725	-40.79	≤15.98	PASS
11AC20M IMO	Ant2	Low	5745	5700~5720	-41.51	≤12.24	PASS
11AC20M IMO	Ant2	Low	5745	5650~5700	-44.29	≤-25.89	PASS
11AC20M IMO	Ant2	Low	5745	5645~5650	-46.12	≤-27	PASS
11AC20M IMO	Ant2	High	5825	5855~5875	-43.60	≤10.73	PASS
11AC20M IMO	Ant2	High	5825	5875~5925	-46.57	≤-26.87	PASS
11AC20M IMO	Ant2	High	5825	5925~5935	-45.47	≤-27	PASS
11AC20M IMO	Ant1	High	5825	5850~5855	-40.84	≤16.54	PASS
11AC20M IMO	Ant1	High	5825	5855~5875	-41.7	≤10.13	PASS
11AC20M IMO	Ant1	High	5825	5875~5925	-41.79	≤-24.84	PASS
11AC20M IMO	Ant1	High	5825	5925~5935	-42.04	≤-27	PASS
11AC20M IMO	Ant2	High	5825	5850~5855	-44.04	≤15.65	PASS
11AC40M IMO	Ant1	Low	5755	5720~5725	-34.38	≤15.90	PASS
11AC40M IMO	Ant1	Low	5755	5700~5720	-33.6	≤14.54	PASS
11AC40M IMO	Ant1	Low	5755	5650~5700	-41.02	≤-26.21	PASS
11AC40M IMO	Ant1	Low	5755	5645~5650	-42.24	≤-27	PASS
11AC40M IMO	Ant2	Low	5755	5720~5725	-35.29	≤16.79	PASS
11AC40M IMO	Ant2	Low	5755	5700~5720	-34.99	≤15.25	PASS
11AC40M	Ant2	Low	5755	5650~5700	-46.83	≤-26.94	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

IMO							
11AC40M IMO	Ant2	Low	5755	5645~5650	-45.01	≤-27	PASS
11AC40M IMO	Ant1	High	5795	5850~5855	-42.15	≤15.85	PASS
11AC40M IMO	Ant1	High	5795	5855~5875	-39.66	≤11.88	PASS
11AC40M IMO	Ant2	High	5795	5850~5855	-44.47	≤15.85	PASS
11AC40M IMO	Ant2	High	5795	5855~5875	-43.3	≤10.81	PASS
11AC40M IMO	Ant2	High	5795	5875~5925	-45.74	≤-26.97	PASS
11AC40M IMO	Ant2	High	5795	5925~5935	-44.64	≤-27	PASS
11AC40M IMO	Ant1	High	5795	5875~5925	-42.19	≤-25.91	PASS
11AC40M IMO	Ant1	High	5795	5925~5935	-41.34	≤-27	PASS
11AC80M IMO	Ant1	Low	5775	5720~5725	-30.82	≤15.67	PASS
11AC80M IMO	Ant1	Low	5775	5700~5720	-32.76	≤10.76	PASS
11AC80M IMO	Ant1	Low	5775	5650~5700	-43.26	≤-26.38	PASS
11AC80M IMO	Ant1	Low	5775	5645~5650	-39.34	≤-27	PASS
11AC80M IMO	Ant1	High	5775	5850~5855	-36.64	≤15.98	PASS
11AC80M IMO	Ant1	High	5775	5855~5875	-39.08	≤10.62	PASS
11AC80M IMO	Ant1	High	5775	5875~5925	-43.42	≤-26.86	PASS
11AC80M IMO	Ant1	High	5775	5925~5935	-41.71	≤-27	PASS
11AC80M IMO	Ant2	Low	5775	5720~5725	-34.15	≤16.69	PASS
11AC80M IMO	Ant2	Low	5775	5700~5720	-36.63	≤10.95	PASS
11AC80M IMO	Ant2	Low	5775	5650~5700	-46.35	≤-26.05	PASS
11AC80M IMO	Ant2	Low	5775	5645~5650	-45.18	≤-27	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC80M IMO	Ant2	High	5775	5850~5855	-42.1	≤15.98	PASS
11AC80M IMO	Ant2	High	5775	5855~5875	-41.92	≤10.69	PASS
11AC80M IMO	Ant2	High	5775	5875~5925	-45.38	≤-26.86	PASS
11AC80M IMO	Ant2	High	5775	5925~5935	-43.44	≤-27	PASS


Note: 1.The Antenna gain and cable loss are compensated in the graph.

Test Graphs B1








11A-Ant1-5240-PASS




11A-Ant2-5240-PASS












11N40MIMO-Ant1-5230-PASS




11N40MIMO-Ant2-5230-PASS







11AC20MIMO-Ant1-5240-PASS



11AC20MIMO-Ant2-5240-PASS







11AC40MIMO-Ant1-5230-PASS




11AC40MIMO-Ant2-5230-PASS




11AC80MIMO-Ant2-5210-PASS



11AC80MIMO-Ant1-5210-PASS





11AC80MIMO-Ant1-5210-PASS





11AC80MIMO-Ant2-5210-PASS


Test Graphs B4
































---End---