





Annex B

Internal Photo

Report No.: HK2411086605-E

Page 1 of 3





Antenna

