




Annex B



Internal Photo

Report No.: HK2411086605-E

Page 1 of 4







Antenna

