



5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:03:04

5MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:03:17

5MHz_High_QPSK_1@0(15GHz~25.675GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:03:33

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:05:44

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:05:58

10MHz_Low_QPSK_1@0(15GHz~25.05GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:06:11

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:08:23

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:08:36

10MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:08:49

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:11:01

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:11:14

10MHz_High_QPSK_1@0(15GHz~25.65GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:11:27

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:14:43

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:14:56

15MHz_Low_QPSK_1@0(15GHz~25.075GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:15:08

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:17:22

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:17:35

15MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:17:50

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:20:02

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:20:16

15MHz_High_QPSK_1@0(15GHz~25.625GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:20:28

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:23:11

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:23:25

20MHz_Low_QPSK_1@0(15GHz~25.1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:23:37

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:25:51

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:26:04

20MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:26:17

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:28:29

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:28:42


20MHz_High_QPSK_1@0(15GHz~25.6GHz)



ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 8.AUG.2026 16:28:55


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:44:24

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:45:01

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:45:36

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:46:27

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:47:02

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Testers:Braylon Ma
Date: 10.AUG.2026 09:47:36

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:48:27

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:49:01

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:49:35

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:51:10

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:52:19

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:53:28

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:54:40

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:55:50

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:57:00

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:58:11

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 09:59:20

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2607S18217E-RF Tester:Braylon Ma
Date: 10.AUG.2026 10:00:30