






Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>

Appendix F: Frequency Stability

Test Result

Voltage										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band38	5MHz	QPSK	37775	25RB#0	VN	NT	-2110.00	-0.820214	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	VL	NT	50.00	0.019436	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	VH	NT	-260.00	-0.101069	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	VN	NT	-3200.00	-1.243926	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	VL	NT	-2710.00	-1.053450	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	VH	NT	-3100.00	-1.205053	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	VN	NT	3570.00	1.375723	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	VL	NT	2100.00	0.809249	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	VH	NT	2050.00	0.789981	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	VN	NT	4460.00	1.718690	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	VL	NT	4740.00	1.826590	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	VH	NT	4550.00	1.753372	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	VN	NT	420.00	0.160458	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	VL	NT	-3580.00	-1.367717	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	VH	NT	-5240.00	-2.001910	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	VN	NT	2100.00	0.802292	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	VL	NT	1770.00	0.676218	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	VH	NT	2640.00	1.008596	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	VN	NT	-5080.00	-1.972816	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	VL	NT	-3170.00	-1.231068	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	VH	NT	-3110.00	-1.207767	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	VN	NT	-30.00	-0.011650	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	VL	NT	1060.00	0.411650	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	VH	NT	-180.00	-0.069903	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	VN	NT	6930.00	2.670520	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	VL	NT	5130.00	1.976879	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	VH	NT	6430.00	2.477842	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	VN	NT	2550.00	0.982659	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	VL	NT	1470.00	0.566474	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	VH	NT	960.00	0.369942	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	VN	NT	-3130.00	-1.196941	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	VL	NT	-2470.00	-0.944551	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	10MHz	QPSK	38200	50RB#0	VH	NT	-4370.00	-1.671128	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	VN	NT	6140.00	2.347992	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	VL	NT	6910.00	2.642447	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	VH	NT	2760.00	1.055449	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	VN	NT	4330.00	1.679922	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	VL	NT	4930.00	1.912706	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	VH	NT	1890.00	0.733269	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	VN	NT	-2300.00	-0.892338	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	VL	NT	760.00	0.294859	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	VH	NT	670.00	0.259942	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	VN	NT	6170.00	2.377649	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	VL	NT	3740.00	1.441233	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	VH	NT	490.00	0.188825	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	VN	NT	650.00	0.250482	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	VL	NT	-9160.00	-3.529865	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	VH	NT	-1530.00	-0.589595	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	VN	NT	-12030.00	-4.604785	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	VL	NT	-13640.00	-5.221053	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	VH	NT	-8300.00	-3.177033	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	VN	NT	-10130.00	-3.877512	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	VL	NT	-16610.00	-6.357895	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	VH	NT	-18040.00	-6.905263	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	VN	NT	8300.00	3.217054	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	VL	NT	-1230.00	-0.476744	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	VH	NT	3720.00	1.441860	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	VN	NT	-2840.00	-1.100775	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	VL	NT	190.00	0.073643	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	VH	NT	-6460.00	-2.503876	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	VN	NT	-9120.00	-3.514451	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	VL	NT	-3040.00	-1.171484	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	VH	NT	-6060.00	-2.335260	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	VN	NT	-11290.00	-4.350674	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	VL	NT	-14010.00	-5.398844	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	VH	NT	-15660.00	-6.034682	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	VN	NT	-12840.00	-4.919540	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	VL	NT	-2820.00	-1.080460	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	VH	NT	-4640.00	-1.777778	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	VN	NT	9450.00	3.620690	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	20MHz	16QAM	38150	100RB#0	VL	NT	12870.00	4.931034	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	VH	NT	6670.00	2.555556	NA	PASS

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band38	5MHz	QPSK	37775	25RB#0	NV	-30	-120.00	-0.046647	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	-20	-2750.00	-1.068999	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	-10	-860.00	-0.334305	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	0	730.00	0.283771	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	10	-1470.00	-0.571429	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	20	-2980.00	-1.158406	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	30	-1360.00	-0.528669	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	40	-710.00	-0.275996	NA	PASS
Band38	5MHz	QPSK	37775	25RB#0	NV	50	-800.00	-0.310982	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	-30	-2770.00	-1.076774	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	-20	-2590.00	-1.006803	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	-10	-3680.00	-1.430515	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	0	-2320.00	-0.901846	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	10	-2620.00	-1.018465	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	20	-2310.00	-0.897959	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	30	-3830.00	-1.488824	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	40	-3740.00	-1.453839	NA	PASS
Band38	5MHz	16QAM	37775	25RB#0	NV	50	-3920.00	-1.523810	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	-30	2900.00	1.117534	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	-20	1650.00	0.635838	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	-10	650.00	0.250482	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	0	1560.00	0.601156	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	10	2200.00	0.847784	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	20	2770.00	1.067437	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	30	2630.00	1.013487	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	40	2400.00	0.924855	NA	PASS
Band38	5MHz	QPSK	38000	25RB#0	NV	50	2190.00	0.843931	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	-30	3610.00	1.391137	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	-20	5100.00	1.965318	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	-10	5480.00	2.111753	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	0	5320.00	2.050096	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	10	4510.00	1.737958	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	20	3970.00	1.529865	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd

Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd

Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: http://www.agccert.com/

Band38	5MHz	16QAM	38000	25RB#0	NV	30	3230.00	1.244701	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	40	5090.00	1.961464	NA	PASS
Band38	5MHz	16QAM	38000	25RB#0	NV	50	4930.00	1.899807	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	-30	-140.00	-0.053486	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	-20	-3470.00	-1.325692	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	-10	-4400.00	-1.680993	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	0	-1650.00	-0.630372	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	10	-1900.00	-0.725883	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	20	-4250.00	-1.623687	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	30	-5440.00	-2.078319	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	40	-1600.00	-0.611270	NA	PASS
Band38	5MHz	QPSK	38225	25RB#0	NV	50	-3170.00	-1.211079	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	-30	680.00	0.259790	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	-20	100.00	0.038204	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	-10	1230.00	0.469914	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	0	2550.00	0.974212	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	10	2410.00	0.920726	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	20	2590.00	0.989494	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	30	2240.00	0.855778	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	40	3560.00	1.360076	NA	PASS
Band38	5MHz	16QAM	38225	25RB#0	NV	50	3510.00	1.340974	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	-30	-710.00	-0.275728	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	-20	-3990.00	-1.549515	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	-10	-4730.00	-1.836893	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	0	-1780.00	-0.691262	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	10	-2490.00	-0.966990	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	20	-3930.00	-1.526214	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	30	-1700.00	-0.660194	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	40	-3340.00	-1.297087	NA	PASS
Band38	10MHz	QPSK	37800	50RB#0	NV	50	10.00	0.003883	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	-30	-4350.00	-1.689320	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	-20	-1140.00	-0.442718	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	-10	-570.00	-0.221359	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	0	-720.00	-0.279612	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	10	-3630.00	-1.409709	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	20	-910.00	-0.353398	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	30	-4720.00	-1.833010	NA	PASS
Band38	10MHz	16QAM	37800	50RB#0	NV	40	-1290.00	-0.500971	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	10MHz	16QAM	37800	50RB#0	NV	50	-1800.00	-0.699029	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	-30	6110.00	2.354528	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	-20	6300.00	2.427746	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	-10	5160.00	1.988439	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	0	5910.00	2.277457	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	10	4190.00	1.614644	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	20	6400.00	2.466281	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	30	6060.00	2.335260	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	40	5610.00	2.161850	NA	PASS
Band38	10MHz	QPSK	38000	50RB#0	NV	50	6910.00	2.662813	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	-30	-720.00	-0.277457	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	-20	2760.00	1.063584	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	-10	780.00	0.300578	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	0	3760.00	1.448940	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	10	280.00	0.107900	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	20	-1930.00	-0.743738	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	30	610.00	0.235067	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	40	-2210.00	-0.851638	NA	PASS
Band38	10MHz	16QAM	38000	50RB#0	NV	50	-2780.00	-1.071291	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	-30	-8320.00	-3.181644	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	-20	-3110.00	-1.189293	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	-10	-1580.00	-0.604207	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	0	-1720.00	-0.657744	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	10	-6700.00	-2.562141	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	20	-4820.00	-1.843212	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	30	-5560.00	-2.126195	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	40	-4520.00	-1.728489	NA	PASS
Band38	10MHz	QPSK	38200	50RB#0	NV	50	-3830.00	-1.464627	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	-30	4170.00	1.594646	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	-20	3590.00	1.372849	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	-10	5730.00	2.191205	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	0	3670.00	1.403442	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	10	1970.00	0.753346	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	20	3830.00	1.464627	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	30	3540.00	1.353728	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	40	4000.00	1.529637	NA	PASS
Band38	10MHz	16QAM	38200	50RB#0	NV	50	3620.00	1.384321	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	-30	5880.00	2.281280	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	15MHz	QPSK	37825	75RB#0	NV	-20	8200.00	3.181377	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	-10	4290.00	1.664403	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	0	5220.00	2.025218	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	10	5090.00	1.974782	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	20	6050.00	2.347236	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	30	9260.00	3.592629	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	40	4180.00	1.621726	NA	PASS
Band38	15MHz	QPSK	37825	75RB#0	NV	50	4000.00	1.551891	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	-30	-580.00	-0.225024	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	-20	-4770.00	-1.850630	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	-10	-930.00	-0.360815	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	0	-1520.00	-0.589719	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	10	-3700.00	-1.435500	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	20	140.00	0.054316	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	30	1860.00	0.721629	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	40	-3070.00	-1.191077	NA	PASS
Band38	15MHz	16QAM	37825	75RB#0	NV	50	-3190.00	-1.237633	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	-30	4470.00	1.722543	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	-20	-120.00	-0.046243	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	-10	3180.00	1.225434	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	0	2400.00	0.924855	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	10	4060.00	1.564547	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	20	750.00	0.289017	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	30	-580.00	-0.223507	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	40	1070.00	0.412331	NA	PASS
Band38	15MHz	QPSK	38000	75RB#0	NV	50	2230.00	0.859345	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	-30	-6420.00	-2.473988	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	-20	-5540.00	-2.134875	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	-10	-6910.00	-2.662813	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	0	-5560.00	-2.142582	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	10	-4280.00	-1.649326	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	20	-7560.00	-2.913295	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	30	-4080.00	-1.572254	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	40	-2750.00	-1.059730	NA	PASS
Band38	15MHz	16QAM	38000	75RB#0	NV	50	-7080.00	-2.728324	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	-30	-10950.00	-4.191388	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	-20	-7160.00	-2.740670	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	-10	-6280.00	-2.403828	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	15MHz	QPSK	38175	75RB#0	NV	0	-11810.00	-4.520574	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	10	-1430.00	-0.547368	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	20	-3960.00	-1.515789	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	30	-11460.00	-4.386603	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	40	-8930.00	-3.418182	NA	PASS
Band38	15MHz	QPSK	38175	75RB#0	NV	50	-9620.00	-3.682297	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	-30	-20360.00	-7.793301	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	-20	-17520.00	-6.706220	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	-10	-7350.00	-2.813397	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	0	-10840.00	-4.149282	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	10	-20440.00	-7.823923	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	20	-15700.00	-6.009569	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	30	-13910.00	-5.324402	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	40	-11210.00	-4.290909	NA	PASS
Band38	15MHz	16QAM	38175	75RB#0	NV	50	-13350.00	-5.110048	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	-30	4210.00	1.631783	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	-20	9750.00	3.779070	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	-10	1790.00	0.693798	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	0	5640.00	2.186047	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	10	-2260.00	-0.875969	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	20	6280.00	2.434109	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	30	3960.00	1.534884	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	40	4390.00	1.701550	NA	PASS
Band38	20MHz	QPSK	37850	100RB#0	NV	50	1480.00	0.573643	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	-30	1090.00	0.422481	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	-20	4800.00	1.860465	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	-10	-3600.00	-1.395349	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	0	-6870.00	-2.662791	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	10	4310.00	1.670543	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	20	-4330.00	-1.678295	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	30	-4800.00	-1.860465	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	40	660.00	0.255814	NA	PASS
Band38	20MHz	16QAM	37850	100RB#0	NV	50	6170.00	2.391473	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	-30	-5000.00	-1.926782	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	-20	2090.00	0.805395	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	-10	-11310.00	-4.358382	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	0	-1350.00	-0.520231	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	10	-9410.00	-3.626204	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd

Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd

Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: http://www.agccert.com/

Band38	20MHz	QPSK	38000	100RB#0	NV	20	-4840.00	-1.865125	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	30	-8470.00	-3.263969	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	40	-3630.00	-1.398844	NA	PASS
Band38	20MHz	QPSK	38000	100RB#0	NV	50	-11400.00	-4.393064	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	-30	-8020.00	-3.090559	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	-20	-14820.00	-5.710983	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	-10	-13180.00	-5.078998	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	0	-18170.00	-7.001927	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	10	-12230.00	-4.712909	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	20	-11710.00	-4.512524	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	30	-14840.00	-5.718690	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	40	-9430.00	-3.633911	NA	PASS
Band38	20MHz	16QAM	38000	100RB#0	NV	50	-15530.00	-5.984586	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	-30	-1800.00	-0.689655	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	-20	-7240.00	-2.773946	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	-10	-5160.00	-1.977011	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	0	-10130.00	-3.881226	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	10	-3630.00	-1.390805	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	20	-4550.00	-1.743295	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	30	-4680.00	-1.793103	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	40	-9740.00	-3.731801	NA	PASS
Band38	20MHz	QPSK	38150	100RB#0	NV	50	-5730.00	-2.195402	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	-30	9790.00	3.750958	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	-20	5500.00	2.107280	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	-10	10580.00	4.053640	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	0	10400.00	3.984674	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	10	12570.00	4.816092	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	20	13300.00	5.095785	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	30	6310.00	2.417625	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	40	8600.00	3.295019	NA	PASS
Band38	20MHz	16QAM	38150	100RB#0	NV	50	10500.00	4.022989	NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.