



CA_7C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM_CC2:16QAM_CC1:2527.5 CC2:2542.5MHz_CC1: 75@0 CC2:
75@0




CA_7C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM_CC2:16QAM_CC1:2547.5 CC2:2562.5MHz_CC1: 75@0 CC2:
75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_7C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2507.5 CC2:2522.5MHz_CC1: 75@0 CC2: 75@0




CA_7C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2527.5 CC2:2542.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_7C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2547.5 CC2:2562.5MHz_CC1: 75@0 CC2: 75@0




CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2507.5 CC2:2524.6MHz_CC1: 75@0 CC2: 100@0



CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2525.2 CC2:2542.3MHz_CC1: 75@0 CC2:
100@0




CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2542.9 CC2:2560MHz_CC1: 75@0 CC2:
100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2507.5 CC2:2524.6MHz_CC1: 75@0 CC2: 100@0




CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2525.2 CC2:2542.3MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2542.9 CC2:2560MHz_CC1: 75@0 CC2: 100@0




CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2507.5 CC2:2524.6MHz_CC1: 75@0 CC2: 100@0



CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2525.2 CC2:2542.3MHz_CC1: 75@0 CC2: 100@0




CA_7C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2542.9 CC2:2560MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2510 CC2:2524.4MHz_CC1: 100@0 CC2: 50@0



CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2530.3 CC2:2544.7MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2550.6 CC2:2565MHz_CC1: 100@0 CC2: 50@0




CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2510 CC2:2524.4MHz_CC1: 100@0 CC2: 50@0



CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2530.3 CC2:2544.7MHz_CC1: 100@0 CC2: 50@0



CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2550.6 CC2:2565MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2510 CC2:2524.4MHz_CC1: 100@0 CC2: 50@0




CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2530.3 CC2:2544.7MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_7C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2550.6 CC2:2565MHz_CC1: 100@0 CC2: 50@0




CA_7C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2510 CC2:2527.1MHz_CC1: 100@0 CC2: 75@0



CA_7C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2527.7 CC2:2544.8MHz_CC1: 100@0 CC2: 75@0



CA_7C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2545.4 CC2:2562.5MHz_CC1: 100@0 CC2: 75@0



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694