



CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2515.5MHz_CC1: 75@0 CC2: 50@0



CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2588.3 CC2:2600.3MHz_CC1: 75@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2673 CC2:2685MHz_CC1: 75@0 CC2: 50@0




CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2515.5MHz_CC1: 75@0 CC2: 50@0



CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2588.3 CC2:2600.3MHz_CC1: 75@0 CC2:
50@0




CA_41C_SISO_NTNV_CC1:15 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2673 CC2:2685MHz_CC1: 75@0 CC2:
50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2585.5 CC2:2600.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2585.5 CC2:2600.5MHz_CC1: 75@0 CC2:
75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2585.5 CC2:2600.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2583.2 CC2:2600.3MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2583.2 CC2:2600.3MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2583.2 CC2:2600.3MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2590.9 CC2:2602.6MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2590.9 CC2:2602.6MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2590.9 CC2:2602.6MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0



CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2588.3 CC2:2602.7MHz_CC1: 100@0 CC2: 50@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2670.6 CC2:2685MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2588.3 CC2:2602.7MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:2670.6 CC2:2685MHz_CC1: 100@0 CC2: 50@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0



CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2588.3 CC2:2602.7MHz_CC1: 100@0
CC2: 50@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:2670.6 CC2:2685MHz_CC1: 100@0 CC2:
50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2523.1MHz_CC1: 100@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2585.7 CC2:2602.8MHz_CC1: 100@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2665.4 CC2:2682.5MHz_CC1: 100@0 CC2:
75@0




CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2523.1MHz_CC1: 100@0 CC2:
75@0



CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2585.7 CC2:2602.8MHz_CC1: 100@0
CC2: 75@0




CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2665.4 CC2:2682.5MHz_CC1: 100@0
CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2523.1MHz_CC1: 100@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2585.7 CC2:2602.8MHz_CC1: 100@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2665.4 CC2:2682.5MHz_CC1: 100@0
CC2: 75@0




CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2525.8MHz_CC1: 100@0 CC2:
100@0



CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2583.1 CC2:2602.9MHz_CC1: 100@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2660.2 CC2:2680MHz_CC1: 100@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2525.8MHz_CC1: 100@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2583.1 CC2:2602.9MHz_CC1: 100@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2660.2 CC2:2680MHz_CC1: 100@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2525.8MHz_CC1: 100@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2583.1 CC2:2602.9MHz_CC1: 100@0
CC2: 100@0



CA_41C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2660.2 CC2:2680MHz_CC1: 100@0 CC2:
100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

2.2.2 CA_41C_NTNV_XDB

CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2498.5 CC2:2510.2MHz_CC1: 25@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2583.4 CC2:2595.1MHz_CC1: 25@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2668.3 CC2:2680MHz_CC1: 25@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2498.5 CC2:2510.2MHz_CC1: 25@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2583.4 CC2:2595.1MHz_CC1: 25@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2668.3 CC2:2680MHz_CC1: 25@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2498.5 CC2:2510.2MHz_CC1: 25@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2583.4 CC2:2595.1MHz_CC1: 25@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2668.3 CC2:2680MHz_CC1: 25@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:10 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2501 CC2:2513MHz_CC1: 50@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:10 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2585.8 CC2:2597.8MHz_CC1: 50@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:10 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2670.5 CC2:2682.5MHz_CC1: 50@0 CC2: 75@0



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694