



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 1@74 CC2:
1@74




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2660	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.015	-43.26	-10	Pass
2691	2695	1	CHP	2	2691.500	-36.81	-10	Pass
2695	2719.683	1	CHP	3	2704.010	-17.01	-13	Pass
2719.683	2725	1	CHP	4	2719.685	-31.85	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:QPSK CC2:QPSK_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2:
75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2:
75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@74 CC2:
1@74




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2660	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.030	-43.91	-10	Pass
2691	2695	1	CHP	2	2691.500	-36.96	-10	Pass
2695	2719.02	1	CHP	3	2704.005	-16.45	-13	Pass
2719.02	2725	1	CHP	4	2719.170	-29.15	-25	Pass

Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0



Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2660	2690	0.1	/	/	/	/	/	/
2690	2691	0.592	CHP	1	2690.450	-32.81	-10	Pass
2691	2695	1	CHP	2	2691.700	-30.16	-10	Pass
2695	2719.608	1	CHP	3	2695.050	-31.72	-13	Pass
2719.608	2725	1	CHP	4	2720.800	-38.17	-25	Pass


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2518.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 1@74 CC2: 1@74




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2660	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.020	-41.67	-10	Pass
2691	2695	1	CHP	2	2691.515	-36.72	-10	Pass
2695	2719.021	1	CHP	3	2704.005	-16.18	-13	Pass
2719.021	2725	1	CHP	4	2719.080	-29.24	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2: 75@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0



CA_41C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:2667.5 CC2:2682.5MHz_CC1: 75@0 CC2:
75@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0



Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2485	2490.5	1	CHP	1	2490.500	-46.61	-25	Pass
2490.5	2495	1	CHP	2	2494.500	-40.56	-13	Pass
2495	2496	0.01	/	3	2495.990	-42.91	-13	Pass
2496	2530.8	0.01	/	/	/	/	/	/


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15_CC2:20MHz_CC1:QPSK_CC2:QPSK_CC1:2662.9_CC2:2680MHz_CC1: 1@0_CC2: 1@0



CA_41C_SISO_NTNV_CC1:15_CC2:20MHz_CC1:QPSK_CC2:QPSK_CC1:2662.9_CC2:2680MHz_CC1: 1@0_CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 1@74 CC2: 1@99




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2655.2	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.150	-45.92	-10	Pass
2691	2695	1	CHP	2	2691.700	-37.43	-10	Pass
2695	2728.078	1	CHP	3	2708.080	-19.47	-13	Pass
2728.078	2730	1	CHP	4	2728.080	-38.59	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0



Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0



Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2485	2490.5	1	CHP	1	2489.672	-32.63	-25	Pass
2490.5	2495	1	CHP	2	2493.290	-31.93	-13	Pass
2495	2496	0.354	CHP	3	2495.168	-34.16	-13	Pass
2496	2530.8	0.354	CHP	/	/	/	/	/

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2:
1@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2:
1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@74 CC2:
1@99




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2655.2	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.135	-44.22	-10	Pass
2691	2695	1	CHP	2	2691.500	-41.98	-10	Pass
2695	2725.88	1	CHP	3	2708.090	-18.70	-13	Pass
2725.88	2730	1	CHP	4	2727.715	-44.42	-25	Pass

Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694