



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2503.5 CC2:2520.6MHz_CC1: 75@0 CC2:
100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2:
1@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 1@74 CC2: 1@99




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2655.2	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.010	-45.41	-10	Pass
2691	2695	1	CHP	2	2691.500	-41.55	-10	Pass
2695	2727.754	1	CHP	3	2708.130	-20.10	-13	Pass
2727.754	2730	1	CHP	4	2727.755	-45.59	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0




CA_41C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:2662.9 CC2:2680MHz_CC1: 75@0 CC2: 100@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz CC1:QPSK CC2:QPSK CC1:2506 CC2:2517.7MHz CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz CC1:QPSK CC2:QPSK CC1:2506 CC2:2517.7MHz CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20_CC2:5MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2517.7MHz_CC1: 1@0_CC2: 1@0



CA_41C_SISO_NTNV_CC1:20_CC2:5MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2517.7MHz_CC1: 1@0_CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2485	2490.5	1	CHP	1	2490.482	-30.86	-25	Pass
2490.5	2495	1	CHP	2	2493.936	-27.49	-13	Pass
2495	2496	0.24	CHP	3	2495.858	-33.04	-13	Pass
2496	2520.6	0.24	CHP	/	/	/	/	/


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2:
25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2:
25@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20_CC2:5MHz_CC1:QPSK_CC2:QPSK_CC1:2675.8_CC2:2687.5MHz_CC1: 1@0_CC2: 1@0




CA_41C_SISO_NTNV_CC1:20_CC2:5MHz_CC1:QPSK_CC2:QPSK_CC1:2675.8_CC2:2687.5MHz_CC1: 1@0_CC2: 1@0



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 1@99 CC2: 1@24




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2665.4	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.010	-35.05	-10	Pass
2691	2695	1	CHP	2	2694.475	-15.03	-10	Pass
2695	2714.023	1	CHP	3	2695.005	-15.91	-13	Pass
2714.023	2720	1	CHP	4	2714.415	-47.22	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2:
25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2:
25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2485	2490.5	1	CHP	1	2489.320	-38.71	-25	Pass
2490.5	2495	1	CHP	2	2494.500	-38.10	-13	Pass
2495	2496	0.01	/	3	2495.965	-49.35	-13	Pass
2496	2520.6	0.01	/	/	/	/	/	/


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2:
1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@99 CC2:
1@24




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2665.4	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.010	-35.30	-10	Pass
2691	2695	1	CHP	2	2694.465	-16.90	-10	Pass
2695	2713.984	1	CHP	3	2695.005	-17.79	-13	Pass
2713.984	2720	1	CHP	4	2714.415	-46.98	-25	Pass


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0



Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2485	2490.5	1	CHP	1	2490.482	-33.24	-25	Pass
2490.5	2495	1	CHP	2	2493.295	-32.35	-13	Pass
2495	2496	0.241	CHP	3	2495.431	-38.11	-13	Pass
2496	2520.6	0.241	CHP	/	/	/	/	/


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2:
25@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2506 CC2:2517.7MHz_CC1: 100@0 CC2:
25@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@0 CC2: 1@0



CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 1@99 CC2: 1@24




Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2665.4	2690	0.02	CHP	/	/	/	/	/
2690	2691	0.02	CHP	1	2690.040	-35.73	-10	Pass
2691	2695	1	CHP	2	2694.520	-16.12	-10	Pass
2695	2713.997	1	CHP	3	2695.005	-16.84	-13	Pass
2713.997	2720	1	CHP	4	2714.415	-47.02	-25	Pass

Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0



Start (MHz)	Stop (MHz)	RBW (MHz)	Method	Marker No.	Freq (MHz)	Level (dBm)	Limit (dBm)	Result
2665.4	2690	0.1	/	/	/	/	/	/
2690	2691	0.477	CHP	1	2690.250	-31.43	-10	Pass
2691	2695	1	CHP	2	2693.250	-34.45	-10	Pass
2695	2713.87	1	CHP	3	2696.900	-35.36	-13	Pass
2713.87	2720	1	CHP	4	2715.500	-42.24	-25	Pass


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0




CA_41C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:2675.8 CC2:2687.5MHz_CC1: 100@0 CC2: 25@0



CA_41C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2520.4MHz_CC1: 1@0_CC2: 1@0



CA_41C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2520.4MHz_CC1: 1@0_CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2520.4MHz_CC1: 1@0_CC2: 1@0



CA_41C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:2506_CC2:2520.4MHz_CC1: 1@0_CC2: 1@0




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0




CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0



CA_41C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK_CC1:2506 CC2:2520.4MHz_CC1: 100@0 CC2: 50@0



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694