



n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_2674.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_2511MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_2674.98MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_2511MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_2674.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_2511MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM 256 QAM 2674.98MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK 2511MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_2674.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_2511MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_2674.98MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_2511MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_2674.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_2511MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_2670MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_2516.01MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_2592.99MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_2670MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_2516.01MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_2670MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_2516.01MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_2670MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_2516.01MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256 QAM_2670MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_2516.01MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_2670MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_2516.01MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_2670MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_2516.01MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant1



n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_2670MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n41_30kHz_SISO_NTNV_40MHz_CP-OFDM 256 QAM 2516.01MHz_Outer_Full_Ant1




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM 256 QAM 2592.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694



3.2.5 30_S_50M_NTNV



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694