



n77a_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_3969.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_3710.01MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_3969.99MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3710.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3969.99MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3710.01MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3969.99MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3710.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3969.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3710.01MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3840MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

4.2.3 30_S_30M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_PI/2_BPSK_3964.98MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3964.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3840MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3964.98MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3964.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3840MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3964.98MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3964.98MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3840MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3964.98MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3715.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3964.98MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3715.02MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3840MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


4.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3720MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3720MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3840MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3720MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3720MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3840MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3720MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3720MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3840MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM 16 QAM 3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM 3720MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3960MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3720MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3840MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3960MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


4.2.5 30_S_50M_NTNV



n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_PI/2_BPSK_3954.99MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3725.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3954.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3725.01MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3954.99MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3725.01MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3954.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3725.01MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3954.99MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3725.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3954.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3725.01MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3954.99MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3725.01MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3840MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3954.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3725.01MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3840MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

4.2.6 30_S_60M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_PI/2_BPSK_3949.98MHz_Outer_Full_Ant1




n77a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3730.02MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3840MHz_Outer_Full_Ant1



n77a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3949.98MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694