




n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3769.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3730.02MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.7 30_S_70M_NTNV



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM PI/2 BPSK_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM QPSK_3735MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3765MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3735MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3735MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3735MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3735MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3735MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM 16 QAM 3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM 64 QAM 3735MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3765MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

3.2.8 30_S_80M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3759.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3740.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3759.99MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3740.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3759.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3740.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3759.99MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3740.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3759.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694