



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM PI/2 BPSK_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM QPSK_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3534.99MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM 16 QAM 3534.99MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM 64 QAM 3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.4 30_S_40M_NTNV



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3470.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3470.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3470.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1

