




n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3519.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3480MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.7 30_S_70M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM PI/2 BPSK_3514.98MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM QPSK_3485.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3514.98MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3485.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3485.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3485.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3485.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3485.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16 QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64 QAM_3485.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3514.98MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

3.2.8 30_S_80M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM PI/2 BPSK_3510MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM QPSK_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3510MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3510MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3510MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3490.02MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3510MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3510MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694