




n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3540MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3460.02MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3540MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3460.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3540MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3460.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3540MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


4.2.3 30_S_30M_NTNV



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM PI/2 BPSK_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM QPSK_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3534.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3534.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3534.99MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3534.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3534.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3534.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3465MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

4.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3529.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3529.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3470.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694




4.2.5 30_S_50M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_PI/2_BPSK_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3475.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3475.02MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3475.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3525MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3475.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3525MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


4.2.6 30_S_60M_NTNV



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM PI/2 BPSK_3519.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM QPSK_3480MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3519.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3480MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3519.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3480MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3519.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3480MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3519.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3480MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3519.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3480MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3519.99MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3480MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3519.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3480MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

4.2.7 30_S_70M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM PI/2 BPSK_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM QPSK_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3485.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3514.98MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3485.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3514.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3485.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694




4.2.8 30_S_80M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM PI/2 BPSK_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM QPSK_3490.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3490.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3490.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3490.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3510MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3490.02MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3510MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


4.2.9 30_S_90M_NTNV



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM PI/2 BPSK_3504.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM QPSK_3495MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_QPSK_3504.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3495MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3504.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3495MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3504.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3495MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3504.99MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3495MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3504.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3495MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3500.01MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3504.99MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3495MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3500.01MHz_Outer_Full_Ant1




n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3504.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_256_QAM_3495MHz_Outer_Full_Ant1



n78e_30kHz_SISO_NTNV_90MHz_CP-OFDM_256_QAM_3500.01MHz_Outer_Full_Ant1





Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694