



n78f_30kHz_SISO_NTNV_10MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_10MHz_CP-OFDM_64_QAM_3795MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_10MHz_CP-OFDM 256 QAM 3455.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_10MHz_CP-OFDM 256 QAM 3624.99MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694




3.2.2 30_S_20M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_PI/2_BPSK_3789.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3460.02MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_QPSK_3789.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_16_QAM_3460.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_16_QAM_3789.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_3460.02MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_3789.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_3460.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM 256 QAM_3789.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK_3460.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK 3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM QPSK 3789.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3460.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3789.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3460.02MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3789.99MHz_Outer_Full_Ant1



**Radiolink Testing (Shenzhen) Co., Ltd.**


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.3 30_S_30M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_PI/2_BPSK_3784.98MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3465MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3784.98MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3784.98MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3465MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3465MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM 256 QAM_3784.98MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK_3465MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK 3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK 3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3465MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3784.98MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3465MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3465MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1





Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694