


3.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3780MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3470.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3780MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3780MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3780MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM 256 QAM_3470.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM 256 QAM_3624.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM 256 QAM_3780MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3470.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK 3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK 3780MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3470.01MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3780MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3470.01MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3780MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_256 QAM_3470.01MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_40MHz_CP-OFDM_256 QAM_3624.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694




3.2.5 30_S_50M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_PI/2_BPSK_3774.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3774.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3475.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3774.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694



n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM 256 QAM_3475.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM 256 QAM_3624.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM 256 QAM_3774.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM QPSK_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694



n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3475.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3774.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3475.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3774.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM 256 QAM_3475.02MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_50MHz_CP-OFDM 256 QAM_3624.99MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.6 30_S_60M_NTNV



n78f_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_PI/2_BPSK_3769.98MHz_Outer_Full_Ant1




n78f_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3480MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78f_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1



n78f_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3769.98MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694