





FCC ID: 2BGUG-RDKX5HM
CMIIT ID: 25J81983C402



RDKX5HMD108064

VDD_1V2
R1980000


ATTENTION

R1980000
VDD_1V2

R22574179
VDD_1V2

GND

GND



GND



N19800509
VDD_CPU_0V6



FCC ID: 2BGUG-RDKX5HM
CMIIT ID: 25J81983C402


H22574179
VDD_1V2

GND

RDKX5HMD104016

VDD_CPU_0V6
N1980199

ATTENTION



GND



N19800509

VDD_CPU_1M

CUK



FCC ID: 2BGUG-RDKX5HM

CMIIT ID: 25J81983C402

N22574179

VDD_1V2



GND

RDXX5HMD104032

VDD_CPU_1M

N1980109

ATTENTION



N19800009
VDD_CPU_0M

UKCA
CE
FCC

FCC ID: 2BGUG-RDKX5HM
CMIIT ID: 25J81983C402


R22574179
VDD_1V2

GND

RDKX5HMD108000

VDD_CPU_0M
N19800009

ATTENTION



CE FCC

FCC ID: 2BGUG-RDKX5HM

CMIIT ID: 25J81983C402

GND

N19800509
VDD_CPU_0M

H22574179
VDD_1V2

GND

RDKX5HMD108016

VDD_CPU_0M
H22574179

ATTENTION

