

HONG KONG RINGCHAN TECHNOLOGY LIMITED

SHOP A4, G/F, WAH HOI MANSION NO.254-280 ELECTRIC RD NORTH POINT HONG KONG

Date: 2024-6-12

To:

Federal Communications Commission
Authorization and Evaluation Division
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern,

Original FCC ID: 2BAYP-SC-R10; Model Number: APE700, SC-R10, APE6600, APE6800, APE6900, APE9300, APE9500, APE1200, APE1300, APE2000, APE2300, SC-R15, APE8000, SC-T180, SC-T190, SC-R16, APE8800, SC-R50, APE6100, APE6700, SC-R60, SC-R70, SC-R80, APE560, APE830, APE510, APE100, APE160, APE310, APE320, APE330, APE350, APE520, APE80, APE130, APE150, APE500, APE950, APE930, APE730, APE750, APE630, SC-R19, SC-R18, APE590, APE170, APE180, APE210, APE220, APE230

New FCC ID: 2BGVF-RC-R10; Model Number: RC-R10, RC-E700, RC-P7, RC-P8, RC-P9, RC-P17, RC-P18, RC-P19, RC-P27, RC-P28, RC-P29, RC-P37, RC-P38, RC-P39, RC-M6374, RC-M7374, RC-M8374, RC-M9374, RC-R13, RC-R15, RC-R23, RC-R25, RC-R33, RC-R35, RC-R53, RC-R55, RC-R57, RC-R63, RC-R65, RC-R67, RC-E57, RC-E58, RC-E17, RC-E18, RC-E27, RC-E28, RC-E37, RC-E38, RC-E12, RC-E22, RC-E32, RC-E52, RC-E16, RC-E26, RC-E36, RC-E56, RC-E610, RC-E620, RC-E630, RC-E650, RC-E660, RC-E670

This is to advise and officially, that we, **HONG KONG RINGCHAN TECHNOLOGY LIMITED** hereby declare that the product name is same and only FCC ID and model number difference as market requirement;

The original test results continue to be representative of and applicable to the equipment of the new FCC ID;

If you have any query, please feel free to contact me.

Sincerely,

Lingxian Xu

Client's name / title : Lingxian Xu/Project manager

Company: HONG KONG RINGCHAN TECHNOLOGY LIMITED

address : SHOP A4, G/F, WAH HOI MANSION NO.254-280 ELECTRIC RD NORTH POINT
HONG KONG

Tel: +8615381773715

Email: lingxianxu@hotmail.com