



10MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:45:13

10MHz_Low_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:46:17

10MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:47:22

10MHz_Low_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:48:27

10MHz_High_QPSK_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:49:30

10MHz_High_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 21:50:35

10MHz_High_16QAM_1@49




10MHz_High_16QAM_50@0




LTE Band 38, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0



5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:23:51

5MHz_High_QPSK_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:24:43

5MHz_High_16QAM_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:25:36

5MHz_High_16QAM_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:26:28

10MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:28:18

10MHz_Low_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:29:02

10MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:29:46

10MHz_Low_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:30:30

10MHz_High_QPSK_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:31:23

10MHz_High_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:32:15

10MHz_High_16QAM_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:33:09

10MHz_High_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:34:02

15MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:35:47

15MHz_Low_QPSK_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:36:36

15MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:37:22

15MHz_Low_16QAM_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:38:07

15MHz_High_QPSK_1@74




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:39:01

15MHz_High_QPSK_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:39:56

15MHz_High_16QAM_1@74




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:40:50

15MHz_High_16QAM_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:41:44

20MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:43:35

20MHz_Low_QPSK_100@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:44:25

20MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:45:15

20MHz_Low_16QAM_100@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25 JUN.2026 23:46:05

20MHz_High_QPSK_1@99




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:47:06

20MHz_High_QPSK_100@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:48:04

20MHz_High_16QAM_1@99



ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:49:02


20MHz_High_16QAM_100@0



ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:50:00


LTE Band 66, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:27:14

1.4MHz_Low_QPSK_6@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:27:46

1.4MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:28:18

1.4MHz_Low_16QAM_6@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:28:48

1.4MHz_High_QPSK_1@5




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:29:16

1.4MHz_High_QPSK_6@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:29:44

1.4MHz_High_16QAM_1@5




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:30:12

1.4MHz_High_16QAM_6@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:30:40

3MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 27.JUN.2026 17:12:20

3MHz_Low_QPSK_15@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 27.JUN.2026 17:13:12

3MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:32:50

3MHz_Low_16QAM_15@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 27.JUN.2026 17:13:34

3MHz_High_QPSK_1@14



ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:33:50


3MHz_High_QPSK_15@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:34:15

3MHz_High_16QAM_1@14

3MHz_High_16QAM_15@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:34:47




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:35:10

5MHz_Low_QPSK_1@0

5MHz_Low_QPSK_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:36:18




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 27.JUN.2026 17:16:35

5MHz_Low_16QAM_1@0

5MHz_Low_16QAM_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:37:07




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:37:29

5MHz_High_QPSK_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:37:58

5MHz_High_QPSK_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:38:19

5MHz_High_16QAM_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:38:48

5MHz_High_16QAM_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:39:12

10MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:40:40

10MHz_Low_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:41:05

10MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:41:38

10MHz_Low_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:42:02

10MHz_High_QPSK_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:42:34

10MHz_High_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:42:55

10MHz_High_16QAM_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:43:25

10MHz_High_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:43:48

15MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:45:12

15MHz_Low_QPSK_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:45:35

15MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:46:09

15MHz_Low_16QAM_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:46:34

15MHz_High_QPSK_1@74




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:47:08

15MHz_High_QPSK_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:47:30

15MHz_High_16QAM_1@74




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:48:02

15MHz_High_16QAM_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:48:24

20MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:49:26

20MHz_Low_QPSK_100@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:49:50

20MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:50:21

20MHz_Low_16QAM_100@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 20:50:43


20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99




20MHz_High_16QAM_100@0




LTE B41_2, Normal


5MHz_Low_QPSK_1@0



5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:52:43

5MHz_Low_16QAM_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:53:31

5MHz_High_QPSK_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:54:19

5MHz_High_QPSK_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:55:07

5MHz_High_16QAM_1@24




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:55:57

5MHz_High_16QAM_25@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:56:46

10MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:58:33

10MHz_Low_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 25.JUN.2026 23:59:22

10MHz_Low_16QAM_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:00:16

10MHz_Low_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:01:04

10MHz_High_QPSK_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:01:50

10MHz_High_QPSK_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:02:36

10MHz_High_16QAM_1@49




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:03:22

10MHz_High_16QAM_50@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:04:10

15MHz_Low_QPSK_1@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:05:57

15MHz_Low_QPSK_75@0




ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:06:44

15MHz_Low_16QAM_1@0



ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:07:31

15MHz_Low_16QAM_75@0



ProjectNo.:2602U62039E-RF Tester:Loge Long
Date: 26.JUN.2026 00:08:19