





Restrict Band NVNT ac20 5260MHz Ant1 Peak



Restrict Band NVNT ac20 5260MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant1 Peak



Restrict Band NVNT ac20 5320MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant1 Peak



Restrict Band NVNT ac40 5270MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant1 Peak



Restrict Band NVNT ac40 5310MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant1 Peak



Restrict Band NVNT ac80 5290MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant1 Peak



Restrict Band NVNT ac80 5290MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant2	4500	-51.41	2.57	-	46.39	Peak	68.2	Pass
NVNT	a	5260	Ant2	4500	-59.21	2.57	0.24	38.83	Average	54	Pass
NVNT	a	5260	Ant2	5055.36	-46.85	2.57	-	50.95	Peak	68.2	Pass
NVNT	a	5260	Ant2	5109.18	-56.43	2.57	0.24	41.61	Average	54	Pass
NVNT	a	5260	Ant2	5150	-48.91	2.57	-	48.89	Peak	68.2	Pass
NVNT	a	5260	Ant2	5150	-56.77	2.57	0.24	41.27	Average	54	Pass
NVNT	a	5320	Ant2	5350	-48.3	2.57	-	49.50	Peak	68.2	Pass
NVNT	a	5320	Ant2	5350	-56.87	2.57	0.24	41.17	Average	54	Pass
NVNT	a	5320	Ant2	5353.4	-46.19	2.57	-	51.61	Peak	68.2	Pass
NVNT	a	5320	Ant2	5350.4	-55.67	2.57	0.24	42.37	Average	54	Pass
NVNT	a	5320	Ant2	5460	-50.67	2.57	-	47.13	Peak	68.2	Pass
NVNT	a	5320	Ant2	5460	-57.67	2.57	0.24	40.37	Average	54	Pass
NVNT	n20	5260	Ant2	4500	-50.46	2.57	-	47.34	Peak	68.2	Pass
NVNT	n20	5260	Ant2	4500	-58.98	2.57	0.12	38.94	Average	54	Pass
NVNT	n20	5260	Ant2	5108.4	-46.32	2.57	-	51.48	Peak	68.2	Pass
NVNT	n20	5260	Ant2	5144.28	-56.6	2.57	0.12	41.32	Average	54	Pass
NVNT	n20	5260	Ant2	5150	-47.92	2.57	-	49.88	Peak	68.2	Pass
NVNT	n20	5260	Ant2	5150	-56.87	2.57	0.12	41.05	Average	54	Pass
NVNT	n20	5320	Ant2	5350	-45.82	2.57	-	51.98	Peak	68.2	Pass
NVNT	n20	5320	Ant2	5350	-55.31	2.57	0.12	42.61	Average	54	Pass
NVNT	n20	5320	Ant2	5350.4	-42.71	2.57	-	55.09	Peak	68.2	Pass
NVNT	n20	5320	Ant2	5350	-55.31	2.57	0.12	42.61	Average	54	Pass
NVNT	n20	5320	Ant2	5460	-49.37	2.57	-	48.43	Peak	68.2	Pass
NVNT	n20	5320	Ant2	5460	-57.84	2.57	0.12	40.08	Average	54	Pass
NVNT	n40	5270	Ant2	4500	-50.57	2.57	-	47.23	Peak	68.2	Pass
NVNT	n40	5270	Ant2	4500	-58.5	2.57	0.24	39.54	Average	54	Pass
NVNT	n40	5270	Ant2	5032.17	-46.14	2.57	-	51.66	Peak	68.2	Pass
NVNT	n40	5270	Ant2	5121.27	-56.42	2.57	0.24	41.62	Average	54	Pass
NVNT	n40	5270	Ant2	5150	-49.9	2.57	-	47.90	Peak	68.2	Pass
NVNT	n40	5270	Ant2	5150	-57.08	2.57	0.24	40.96	Average	54	Pass
NVNT	n40	5310	Ant2	5350	-43.8	2.57	-	54.00	Peak	68.2	Pass
NVNT	n40	5310	Ant2	5350	-55.35	2.57	0.23	42.68	Average	54	Pass
NVNT	n40	5310	Ant2	5460	-50.14	2.57	-	47.66	Peak	68.2	Pass
NVNT	n40	5310	Ant2	5460	-57.47	2.57	0.23	40.56	Average	54	Pass
NVNT	n40	5310	Ant2	5460	-50.14	2.57	-	47.66	Peak	68.2	Pass
NVNT	n40	5310	Ant2	5460	-57.47	2.57	0.23	40.56	Average	54	Pass
NVNT	ac20	5260	Ant2	4500	-48.35	2.57	-	49.45	Peak	68.2	Pass
NVNT	ac20	5260	Ant2	4500	-58.51	2.57	0.12	39.41	Average	54	Pass
NVNT	ac20	5260	Ant2	5085.78	-46.31	2.57	-	51.49	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5260	Ant2	5079.54	-56.58	2.57	0.12	41.34	Average	54	Pass
NVNT	ac20	5260	Ant2	5150	-48.31	2.57	-	49.49	Peak	68.2	Pass
NVNT	ac20	5260	Ant2	5150	-57.18	2.57	0.12	40.74	Average	54	Pass
NVNT	ac20	5320	Ant2	5350	-46.6	2.57	-	51.20	Peak	68.2	Pass
NVNT	ac20	5320	Ant2	5350	-56.26	2.57	0.12	41.66	Average	54	Pass
NVNT	ac20	5320	Ant2	5352.2	-42.04	2.57	-	55.76	Peak	68.2	Pass
NVNT	ac20	5320	Ant2	5350.4	-55.24	2.57	0.12	42.68	Average	54	Pass
NVNT	ac20	5320	Ant2	5460	-49.04	2.57	-	48.76	Peak	68.2	Pass
NVNT	ac20	5320	Ant2	5460	-57.37	2.57	0.12	40.55	Average	54	Pass
NVNT	ac40	5270	Ant2	4500	-48.76	2.57	-	49.04	Peak	68.2	Pass
NVNT	ac40	5270	Ant2	4500	-58.34	2.57	0.24	39.70	Average	54	Pass
NVNT	ac40	5270	Ant2	5092.92	-46.34	2.57	-	51.46	Peak	68.2	Pass
NVNT	ac40	5270	Ant2	5045.94	-56.58	2.57	0.24	41.46	Average	54	Pass
NVNT	ac40	5270	Ant2	5150	-49.04	2.57	-	48.76	Peak	68.2	Pass
NVNT	ac40	5270	Ant2	5150	-57	2.57	0.24	41.04	Average	54	Pass
NVNT	ac40	5310	Ant2	5350	-45.95	2.57	-	51.85	Peak	68.2	Pass
NVNT	ac40	5310	Ant2	5350	-55.79	2.57	0.24	42.25	Average	54	Pass
NVNT	ac40	5310	Ant2	5351	-43.59	2.57	-	54.21	Peak	68.2	Pass
NVNT	ac40	5310	Ant2	5351.2	-55.36	2.57	0.24	42.68	Average	54	Pass
NVNT	ac40	5310	Ant2	5460	-48.01	2.57	-	49.79	Peak	68.2	Pass
NVNT	ac40	5310	Ant2	5460	-57.2	2.57	0.24	40.84	Average	54	Pass
NVNT	ac80	5290	Ant2	4500	-48.7	2.57	-	49.10	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	4500	-58.61	2.57	0.47	39.66	Average	54	Pass
NVNT	ac80	5290	Ant2	5105.52	-45.34	2.57	-	52.46	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	5142.93	-55.34	2.57	0.47	42.93	Average	54	Pass
NVNT	ac80	5290	Ant2	5150	-46.93	2.57	-	50.87	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	5150	-55.59	2.57	0.47	42.68	Average	54	Pass
NVNT	ac80	5290	Ant2	5350	-47.11	2.57	-	50.69	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	5350	-55.38	2.57	0.47	42.89	Average	54	Pass
NVNT	ac80	5290	Ant2	5350.25	-43.74	2.57	-	54.06	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	5350.25	-54.86	2.57	0.47	43.41	Average	54	Pass
NVNT	ac80	5290	Ant2	5460	-49.82	2.57	-	47.98	Peak	68.2	Pass
NVNT	ac80	5290	Ant2	5460	-57.72	2.57	0.47	40.55	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5260MHz Ant2 Peak



Restrict Band NVNT a 5260MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant2 Peak



Restrict Band NVNT a 5320MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant2 Peak



Restrict Band NVNT n20 5260MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant2 Peak



Restrict Band NVNT n20 5320MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz Ant2 Peak



Restrict Band NVNT n40 5270MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5310MHz Ant2 Peak



Restrict Band NVNT n40 5310MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz Ant2 Peak



Restrict Band NVNT ac20 5260MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant2 Peak



Restrict Band NVNT ac20 5320MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant2 Peak



Restrict Band NVNT ac40 5270MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant2 Peak



Restrict Band NVNT ac40 5310MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant2 Peak



Restrict Band NVNT ac80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant2 Peak



Restrict Band NVNT ac80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Ant1 Power (dBm)	Ant2 Power (dBm)	Gain (dBi)	Total E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5260	-51.02	-50.46	5.58	53.09	Peak	68.2	Pass
NVNT	n20	5260	-58.35	-58.98	5.58	45.16	Average	54	Pass
NVNT	n20	5260	-46.44	-46.32	5.58	57.44	Peak	68.2	Pass
NVNT	n20	5260	-56.51	-56.6	5.58	47.26	Average	54	Pass
NVNT	n20	5260	-49.5	-47.92	5.58	55.18	Peak	68.2	Pass
NVNT	n20	5260	-57.03	-56.87	5.58	46.87	Average	54	Pass
NVNT	n20	5320	-44.04	-45.82	5.58	58.98	Peak	68.2	Pass
NVNT	n20	5320	-56.07	-55.31	5.58	48.14	Average	54	Pass
NVNT	n20	5320	-44.04	-42.71	5.58	60.49	Peak	68.2	Pass
NVNT	n20	5320	-55.54	-55.31	5.58	48.39	Average	54	Pass
NVNT	n20	5320	-48.67	-49.37	5.58	54.81	Peak	68.2	Pass
NVNT	n20	5320	-57.69	-57.84	5.58	46.05	Average	54	Pass
NVNT	n40	5270	-51.48	-50.57	5.58	52.82	Peak	68.2	Pass
NVNT	n40	5270	-58.59	-58.5	5.58	45.27	Average	54	Pass
NVNT	n40	5270	-46.72	-46.14	5.58	57.40	Peak	68.2	Pass
NVNT	n40	5270	-56.4	-56.42	5.58	47.41	Average	54	Pass
NVNT	n40	5270	-47.89	-49.9	5.58	55.04	Peak	68.2	Pass
NVNT	n40	5270	-57.25	-57.08	5.58	46.65	Average	54	Pass
NVNT	n40	5310	-47.01	-43.8	5.58	58.70	Peak	68.2	Pass
NVNT	n40	5310	-56.1	-55.35	5.58	48.11	Average	54	Pass
NVNT	n40	5310	-40.3	-50.14	5.58	60.94	Peak	68.2	Pass
NVNT	n40	5310	-55.61	-57.47	5.58	47.38	Average	54	Pass
NVNT	n40	5310	-49.95	-50.14	5.58	53.77	Peak	68.2	Pass
NVNT	n40	5310	-57.67	-57.47	5.58	46.25	Average	54	Pass
NVNT	ac20	5260	-49.8	-48.35	5.58	54.80	Peak	68.2	Pass
NVNT	ac20	5260	-58.46	-58.51	5.58	45.33	Average	54	Pass
NVNT	ac20	5260	-46.34	-46.31	5.58	57.49	Peak	68.2	Pass
NVNT	ac20	5260	-56.69	-56.58	5.58	47.18	Average	54	Pass
NVNT	ac20	5260	-47.75	-48.31	5.58	55.80	Peak	68.2	Pass
NVNT	ac20	5260	-57.06	-57.18	5.58	46.70	Average	54	Pass
NVNT	ac20	5320	-47.4	-46.6	5.58	56.84	Peak	68.2	Pass
NVNT	ac20	5320	-54.87	-56.26	5.58	48.31	Average	54	Pass
NVNT	ac20	5320	-43.15	-42.04	5.58	61.26	Peak	68.2	Pass
NVNT	ac20	5320	-54.87	-55.24	5.58	48.77	Average	54	Pass
NVNT	ac20	5320	-49.61	-49.04	5.58	54.50	Peak	68.2	Pass
NVNT	ac20	5320	-57.77	-57.37	5.58	46.25	Average	54	Pass
NVNT	ac40	5270	-49.78	-48.76	5.58	54.58	Peak	68.2	Pass
NVNT	ac40	5270	-58.45	-58.34	5.58	45.42	Average	54	Pass
NVNT	ac40	5270	-45.58	-46.34	5.58	57.87	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5270	-56.63	-56.58	5.58	47.21	Average	54	Pass
NVNT	ac40	5270	-49.18	-49.04	5.58	54.71	Peak	68.2	Pass
NVNT	ac40	5270	-57.83	-57	5.58	46.42	Average	54	Pass
NVNT	ac40	5310	-41.96	-45.95	5.58	60.31	Peak	68.2	Pass
NVNT	ac40	5310	-56.15	-55.79	5.58	47.85	Average	54	Pass
NVNT	ac40	5310	-40.33	-43.59	5.58	62.16	Peak	68.2	Pass
NVNT	ac40	5310	-55.57	-55.36	5.58	48.35	Average	54	Pass
NVNT	ac40	5310	-50.11	-48.01	5.58	54.88	Peak	68.2	Pass
NVNT	ac40	5310	-57.83	-57.2	5.58	46.31	Average	54	Pass
NVNT	ac80	5290	-49.87	-48.7	5.58	54.57	Peak	68.2	Pass
NVNT	ac80	5290	-58.3	-58.61	5.58	45.37	Average	54	Pass
NVNT	ac80	5290	-45.52	-45.34	5.58	58.39	Peak	68.2	Pass
NVNT	ac80	5290	-55.15	-55.34	5.58	48.57	Average	54	Pass
NVNT	ac80	5290	-48.16	-46.93	5.58	56.32	Peak	68.2	Pass
NVNT	ac80	5290	-55.9	-55.59	5.58	48.08	Average	54	Pass
NVNT	ac80	5290	-47.27	-47.11	5.58	56.63	Peak	68.2	Pass
NVNT	ac80	5290	-56.09	-55.38	5.58	48.10	Average	54	Pass
NVNT	ac80	5290	-43.21	-43.74	5.58	60.35	Peak	68.2	Pass
NVNT	ac80	5290	-55.45	-54.86	5.58	48.67	Average	54	Pass
NVNT	ac80	5290	-49.04	-49.82	5.58	54.41	Peak	68.2	Pass
NVNT	ac80	5290	-57.48	-57.72	5.58	46.22	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant3	4500	-50.06	5.1	-	50.27	Peak	68.2	Pass
NVNT	a	5260	Ant3	4500	-58.78	5.1	0.24	41.79	Average	54	Pass
NVNT	a	5260	Ant3	5127.12	-46.38	5.1	-	53.95	Peak	68.2	Pass
NVNT	a	5260	Ant3	5079.54	-56.55	5.1	0.24	44.02	Average	54	Pass
NVNT	a	5260	Ant3	5150	-47.71	5.1	-	52.62	Peak	68.2	Pass
NVNT	a	5260	Ant3	5150	-56.71	5.1	0.24	43.86	Average	54	Pass
NVNT	a	5320	Ant3	5350	-47.58	5.1	-	52.75	Peak	68.2	Pass
NVNT	a	5320	Ant3	5350	-56.54	5.1	0.24	44.03	Average	54	Pass
NVNT	a	5320	Ant3	5354.2	-45.69	5.1	-	54.64	Peak	68.2	Pass
NVNT	a	5320	Ant3	5350.6	-56.46	5.1	0.24	44.11	Average	54	Pass
NVNT	a	5320	Ant3	5460	-49.14	5.1	-	51.19	Peak	68.2	Pass
NVNT	a	5320	Ant3	5460	-57.91	5.1	0.24	42.66	Average	54	Pass
NVNT	n20	5260	Ant3	4500	-50.03	5.1	-	50.30	Peak	68.2	Pass
NVNT	n20	5260	Ant3	4500	-58.82	5.1	0.12	41.63	Average	54	Pass
NVNT	n20	5260	Ant3	5031.96	-46.51	5.1	-	53.82	Peak	68.2	Pass
NVNT	n20	5260	Ant3	5034.3	-56.62	5.1	0.12	43.83	Average	54	Pass
NVNT	n20	5260	Ant3	5150	-49.19	5.1	-	51.14	Peak	68.2	Pass
NVNT	n20	5260	Ant3	5150	-57.31	5.1	0.12	43.14	Average	54	Pass
NVNT	n20	5320	Ant3	5350	-46.33	5.1	-	54.00	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5350	-56.02	5.1	0.12	44.43	Average	54	Pass
NVNT	n20	5320	Ant3	5354.8	-45.17	5.1	-	55.16	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5350.2	-55.67	5.1	0.12	44.78	Average	54	Pass
NVNT	n20	5320	Ant3	5460	-49.8	5.1	-	50.53	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5460	-57.86	5.1	0.12	42.59	Average	54	Pass
NVNT	n40	5270	Ant3	4500	-50.6	5.1	-	49.73	Peak	68.2	Pass
NVNT	n40	5270	Ant3	4500	-58.87	5.1	0.24	41.70	Average	54	Pass
NVNT	n40	5270	Ant3	5085.63	-46.37	5.1	-	53.96	Peak	68.2	Pass
NVNT	n40	5270	Ant3	5105.07	-56.59	5.1	0.24	43.98	Average	54	Pass
NVNT	n40	5270	Ant3	5150	-48.87	5.1	-	51.46	Peak	68.2	Pass
NVNT	n40	5270	Ant3	5150	-57.33	5.1	0.24	43.24	Average	54	Pass
NVNT	n40	5310	Ant3	5350	-46.1	5.1	-	54.23	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5350	-55.79	5.1	0.24	44.78	Average	54	Pass
NVNT	n40	5310	Ant3	5352.4	-44.99	5.1	-	55.34	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5350	-55.79	5.1	0.24	44.78	Average	54	Pass
NVNT	n40	5310	Ant3	5460	-51.33	5.1	-	49.00	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5460	-57.7	5.1	0.24	42.87	Average	54	Pass
NVNT	ac20	5260	Ant3	4500	-50.91	5.1	-	49.42	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	4500	-58.98	5.1	0.12	41.47	Average	54	Pass
NVNT	ac20	5260	Ant3	5131.8	-46.1	5.1	-	54.23	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	5124	-56.25	5.1	0.12	44.20	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5260	Ant3	5150	-49.41	5.1	-	50.92	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	5150	-57.38	5.1	0.12	43.07	Average	54	Pass
NVNT	ac20	5320	Ant3	5350	-43.5	5.1	-	56.83	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5350	-56.32	5.1	0.12	44.13	Average	54	Pass
NVNT	ac20	5320	Ant3	5350.2	-42.07	5.1	-	58.26	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5350.4	-55.87	5.1	0.12	44.58	Average	54	Pass
NVNT	ac20	5320	Ant3	5460	-50.8	5.1	-	49.53	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5460	-57.43	5.1	0.12	43.02	Average	54	Pass
NVNT	ac40	5270	Ant3	4500	-50.28	5.1	-	50.05	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	4500	-58.87	5.1	0.24	41.70	Average	54	Pass
NVNT	ac40	5270	Ant3	5044.32	-46.59	5.1	-	53.74	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	5109.93	-56.68	5.1	0.24	43.89	Average	54	Pass
NVNT	ac40	5270	Ant3	5150	-48.8	5.1	-	51.53	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	5150	-57.62	5.1	0.24	42.95	Average	54	Pass
NVNT	ac40	5310	Ant3	5350	-44.71	5.1	-	55.62	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5350	-54.66	5.1	0.24	45.91	Average	54	Pass
NVNT	ac40	5310	Ant3	5354	-42.67	5.1	-	57.66	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5350	-54.66	5.1	0.24	45.91	Average	54	Pass
NVNT	ac40	5310	Ant3	5460	-50.7	5.1	-	49.63	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5460	-57.81	5.1	0.24	42.76	Average	54	Pass
NVNT	ac80	5290	Ant3	4500	-51.01	5.1	-	49.32	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	4500	-57.98	5.1	0.47	42.82	Average	54	Pass
NVNT	ac80	5290	Ant3	5119.44	-45.98	5.1	-	54.35	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5149.89	-55.37	5.1	0.47	45.43	Average	54	Pass
NVNT	ac80	5290	Ant3	5150	-47.48	5.1	-	52.85	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5150	-55.37	5.1	0.47	45.43	Average	54	Pass
NVNT	ac80	5290	Ant3	5350	-48.28	5.1	-	52.05	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5350	-55.78	5.1	0.47	45.02	Average	54	Pass
NVNT	ac80	5290	Ant3	5350.25	-45.07	5.1	-	55.26	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5350.75	-55.73	5.1	0.47	45.07	Average	54	Pass
NVNT	ac80	5290	Ant3	5460	-49.43	5.1	-	50.90	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5460	-57.67	5.1	0.47	43.13	Average	54	Pass
NVNT	ax20	5260	Ant3	4500	-50.78	5.1	-	49.55	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	4500	-58.95	5.1	0.12	41.50	Average	54	Pass
NVNT	ax20	5260	Ant3	4992.18	-46.85	5.1	-	53.48	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	5107.62	-56.64	5.1	0.12	43.81	Average	54	Pass
NVNT	ax20	5260	Ant3	5150	-48.79	5.1	-	51.54	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	5150	-57.44	5.1	0.12	43.01	Average	54	Pass
NVNT	ax20	5320	Ant3	5350	-45.99	5.1	-	54.34	Peak	68.2	Pass
NVNT	ax20	5320	Ant3	5350	-55.58	5.1	0.12	44.87	Average	54	Pass
NVNT	ax20	5320	Ant3	5351	-43.96	5.1	-	56.37	Peak	68.2	Pass
NVNT	ax20	5320	Ant3	5350.2	-55.52	5.1	0.12	44.93	Average	54	Pass
NVNT	ax20	5320	Ant3	5460	-49.37	5.1	-	50.96	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax20	5320	Ant3	5460	-57.71	5.1	0.12	42.74	Average	54	Pass
NVNT	ax40	5270	Ant3	4500	-50.98	5.1	-	49.35	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	4500	-58.78	5.1	0.24	41.79	Average	54	Pass
NVNT	ax40	5270	Ant3	4738.14	-46.24	5.1	-	54.09	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	4773.78	-56.57	5.1	0.24	44.00	Average	54	Pass
NVNT	ax40	5270	Ant3	5150	-48.69	5.1	-	51.64	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	5150	-57.16	5.1	0.24	43.41	Average	54	Pass
NVNT	ax40	5310	Ant3	5350	-46.75	5.1	-	53.58	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5350	-56.64	5.1	0.24	43.93	Average	54	Pass
NVNT	ax40	5310	Ant3	5352.2	-42.31	5.1	-	58.02	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5352.4	-55.83	5.1	0.24	44.74	Average	54	Pass
NVNT	ax40	5310	Ant3	5460	-49.02	5.1	-	51.31	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5460	-57.29	5.1	0.24	43.28	Average	54	Pass
NVNT	ax80	5290	Ant3	5350	-45.7	5.1	-	54.63	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5350	-55.69	5.1	0.47	45.11	Average	54	Pass
NVNT	ax80	5290	Ant3	5354	-44.52	5.1	-	55.81	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5350	-55.69	5.1	0.47	45.11	Average	54	Pass
NVNT	ax80	5290	Ant3	5460	-49.63	5.1	-	50.70	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5460	-57.55	5.1	0.47	43.25	Average	54	Pass
NVNT	ax80	5290	Ant3	4500	-49.72	5.1	-	50.61	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	4500	-58.1	5.1	0.47	42.70	Average	54	Pass
NVNT	ax80	5290	Ant3	4992.42	-45.23	5.1	-	55.10	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5149.02	-55.63	5.1	0.47	45.17	Average	54	Pass
NVNT	ax80	5290	Ant3	5150	-47.54	5.1	-	52.79	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5150	-55.82	5.1	0.47	44.98	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5260MHz Ant3 Peak



Restrict Band NVNT a 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant3 Peak



Restrict Band NVNT a 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant3 Peak



Restrict Band NVNT n20 5260MHz An3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant3 Peak



Restrict Band NVNT n20 5320MHz An3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz Ant3 Peak



Restrict Band NVNT n40 5270MHz Ant3 Average





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz Ant3 Peak



Restrict Band NVNT ac20 5260MHz An3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant3 Peak



Restrict Band NVNT ac20 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant3 Peak



Restrict Band NVNT ac40 5270MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant3 Peak



Restrict Band NVNT ac40 5310MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant3 Peak



Restrict Band NVNT ac80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant3 Peak



Restrict Band NVNT ac80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5260MHz Ant3 Peak



Restrict Band NVNT ax20 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant3 Peak



Restrict Band NVNT ax20 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant3 Peak



Restrict Band NVNT ax40 5270MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5310MHz Ant3 Peak



Restrict Band NVNT ax40 5310MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant3 Peak



Restrict Band NVNT ax80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant3 Peak



Restrict Band NVNT ax80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant4	4500	-50.77	5.1	-	49.56	Peak	68.2	Pass
NVNT	a	5260	Ant4	4500	-58.89	5.1	0.24	41.68	Average	54	Pass
NVNT	a	5260	Ant4	5149.74	-45.17	5.1	-	55.16	Peak	68.2	Pass
NVNT	a	5260	Ant4	4787.04	-55.17	5.1	0.24	45.40	Average	54	Pass
NVNT	a	5260	Ant4	5150	-45.17	5.1	-	55.16	Peak	68.2	Pass
NVNT	a	5260	Ant4	5150	-56.12	5.1	0.24	44.45	Average	54	Pass
NVNT	a	5320	Ant4	5350	-44.19	5.1	-	56.14	Peak	68.2	Pass
NVNT	a	5320	Ant4	5350	-56.07	5.1	0.24	44.50	Average	54	Pass
NVNT	a	5320	Ant4	5351	-42.64	5.1	-	57.69	Peak	68.2	Pass
NVNT	a	5320	Ant4	5351.6	-55.82	5.1	0.24	44.75	Average	54	Pass
NVNT	a	5320	Ant4	5460	-49.32	5.1	-	51.01	Peak	68.2	Pass
NVNT	a	5320	Ant4	5460	-57.61	5.1	0.24	42.96	Average	54	Pass
NVNT	n20	5260	Ant4	4500	-49.72	5.1	-	50.61	Peak	68.2	Pass
NVNT	n20	5260	Ant4	4500	-58.35	5.1	0.12	42.10	Average	54	Pass
NVNT	n20	5260	Ant4	4599.06	-45.58	5.1	-	54.75	Peak	68.2	Pass
NVNT	n20	5260	Ant4	5126.34	-56.48	5.1	0.12	43.97	Average	54	Pass
NVNT	n20	5260	Ant4	5150	-49.15	5.1	-	51.18	Peak	68.2	Pass
NVNT	n20	5260	Ant4	5150	-57.5	5.1	0.12	42.95	Average	54	Pass
NVNT	n20	5320	Ant4	5350	-43.77	5.1	-	56.56	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5350	-56.12	5.1	0.12	44.33	Average	54	Pass
NVNT	n20	5320	Ant4	5350.4	-42.89	5.1	-	57.44	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5352.2	-55.65	5.1	0.12	44.80	Average	54	Pass
NVNT	n20	5320	Ant4	5460	-49.74	5.1	-	50.59	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5460	-57.41	5.1	0.12	43.04	Average	54	Pass
NVNT	n40	5270	Ant4	4500	-50.18	5.1	-	50.15	Peak	68.2	Pass
NVNT	n40	5270	Ant4	4500	-58.68	5.1	0.23	41.88	Average	54	Pass
NVNT	n40	5270	Ant4	5037.03	-45.3	5.1	-	55.03	Peak	68.2	Pass
NVNT	n40	5270	Ant4	5079.96	-56.45	5.1	0.23	44.11	Average	54	Pass
NVNT	n40	5270	Ant4	5150	-48.52	5.1	-	51.81	Peak	68.2	Pass
NVNT	n40	5270	Ant4	5150	-57.66	5.1	0.23	42.90	Average	54	Pass
NVNT	n40	5310	Ant4	5350	-45.58	5.1	-	54.75	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5350	-55.56	5.1	0.24	45.01	Average	54	Pass
NVNT	n40	5310	Ant4	5350.2	-41.41	5.1	-	58.92	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5350.2	-55.46	5.1	0.24	45.11	Average	54	Pass
NVNT	n40	5310	Ant4	5460	-50.47	5.1	-	49.86	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5460	-57.68	5.1	0.24	42.89	Average	54	Pass
NVNT	ac20	5260	Ant4	4500	-51.57	5.1	-	48.76	Peak	68.2	Pass
NVNT	ac20	5260	Ant4	4500	-58.65	5.1	0.12	41.80	Average	54	Pass
NVNT	ac20	5260	Ant4	4919.64	-46.47	5.1	-	53.86	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5260	Ant4	5096.7	-56.68	5.1	0.12	43.77	Average	54	Pass
NVNT	ac20	5260	Ant4	5150	-48.1	5.1	-	52.23	Peak	68.2	Pass
NVNT	ac20	5260	Ant4	5150	-57.4	5.1	0.12	43.05	Average	54	Pass
NVNT	ac20	5320	Ant4	5350	-42.37	5.1	-	57.96	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5350	-56	5.1	0.12	44.45	Average	54	Pass
NVNT	ac20	5320	Ant4	5350	-42.37	5.1	-	57.96	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5350.4	-55.63	5.1	0.12	44.82	Average	54	Pass
NVNT	ac20	5320	Ant4	5460	-50.22	5.1	-	50.11	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5460	-57.26	5.1	0.12	43.19	Average	54	Pass
NVNT	ac40	5270	Ant4	4500	-50.85	5.1	-	49.48	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	4500	-58.86	5.1	0.23	41.70	Average	54	Pass
NVNT	ac40	5270	Ant4	5084.01	-46.43	5.1	-	53.90	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	5091.3	-56.68	5.1	0.23	43.88	Average	54	Pass
NVNT	ac40	5270	Ant4	5150	-49.01	5.1	-	51.32	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	5150	-57.19	5.1	0.23	43.37	Average	54	Pass
NVNT	ac40	5310	Ant4	5350	-43.34	5.1	-	56.99	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5350	-56.13	5.1	0.24	44.44	Average	54	Pass
NVNT	ac40	5310	Ant4	5350.8	-40.11	5.1	-	60.22	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5351	-56.01	5.1	0.24	44.56	Average	54	Pass
NVNT	ac40	5310	Ant4	5460	-49.77	5.1	-	50.56	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5460	-58.06	5.1	0.24	42.51	Average	54	Pass
NVNT	ac80	5290	Ant4	4500	-47.8	5.1	-	52.53	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	4500	-58.49	5.1	0.47	42.31	Average	54	Pass
NVNT	ac80	5290	Ant4	5144.67	-45.63	5.1	-	54.70	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5149.89	-55.56	5.1	0.47	45.24	Average	54	Pass
NVNT	ac80	5290	Ant4	5150	-46.74	5.1	-	53.59	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5150	-55.56	5.1	0.47	45.24	Average	54	Pass
NVNT	ac80	5290	Ant4	5350	-47.17	5.1	-	53.16	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5350	-55.51	5.1	0.47	45.29	Average	54	Pass
NVNT	ac80	5290	Ant4	5351.75	-43.9	5.1	-	56.43	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5352	-55.43	5.1	0.47	45.37	Average	54	Pass
NVNT	ac80	5290	Ant4	5460	-49.64	5.1	-	50.69	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5460	-57.47	5.1	0.47	43.33	Average	54	Pass
NVNT	ax20	5260	Ant4	4500	-49.43	5.1	-	50.90	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	4500	-58.8	5.1	0.12	41.65	Average	54	Pass
NVNT	ax20	5260	Ant4	5010.9	-45.31	5.1	-	55.02	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	5048.34	-56.62	5.1	0.12	43.83	Average	54	Pass
NVNT	ax20	5260	Ant4	5150	-49.45	5.1	-	50.88	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	5150	-57.05	5.1	0.12	43.40	Average	54	Pass
NVNT	ax20	5320	Ant4	5350	-40.36	5.1	-	59.97	Peak	68.2	Pass
NVNT	ax20	5320	Ant4	5350	-56.19	5.1	0.12	44.26	Average	54	Pass
NVNT	ax20	5320	Ant4	5350	-40.36	5.1	-	59.97	Peak	68.2	Pass
NVNT	ax20	5320	Ant4	5351.8	-55.62	5.1	0.12	44.83	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax20	5320	Ant4	5460	-49.81	5.1	-	50.52	Peak	68.2	Pass
NVNT	ax20	5320	Ant4	5460	-57.75	5.1	0.12	42.70	Average	54	Pass
NVNT	ax40	5270	Ant4	4500	-50.04	5.1	-	50.29	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	4500	-58.66	5.1	0.24	41.91	Average	54	Pass
NVNT	ax40	5270	Ant4	4926.87	-46.37	5.1	-	53.96	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	5115.6	-56.64	5.1	0.24	43.93	Average	54	Pass
NVNT	ax40	5270	Ant4	5150	-49.86	5.1	-	50.47	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	5150	-56.79	5.1	0.24	43.78	Average	54	Pass
NVNT	ax40	5310	Ant4	5350	-39.66	5.1	-	60.67	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5350	-55.88	5.1	0.24	44.69	Average	54	Pass
NVNT	ax40	5310	Ant4	5350	-39.66	5.1	-	60.67	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5351	-55.49	5.1	0.24	45.08	Average	54	Pass
NVNT	ax40	5310	Ant4	5460	-49.67	5.1	-	50.66	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5460	-57.73	5.1	0.24	42.84	Average	54	Pass
NVNT	ax80	5290	Ant4	5350	-44.26	5.1	-	56.07	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5350	-55.61	5.1	0.47	45.19	Average	54	Pass
NVNT	ax80	5290	Ant4	5352.75	-43.8	5.1	-	56.53	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5350.75	-55.5	5.1	0.47	45.30	Average	54	Pass
NVNT	ax80	5290	Ant4	5460	-49.79	5.1	-	50.54	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5460	-58.11	5.1	0.47	42.69	Average	54	Pass
NVNT	ax80	5290	Ant4	4500	-50.46	5.1	-	49.87	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	4500	-58.95	5.1	0.47	41.85	Average	54	Pass
NVNT	ax80	5290	Ant4	5122.05	-45.43	5.1	-	54.90	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5146.41	-55.42	5.1	0.47	45.38	Average	54	Pass
NVNT	ax80	5290	Ant4	5150	-46.98	5.1	-	53.35	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5150	-55.63	5.1	0.47	45.17	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5260MHz Ant4 Peak



Restrict Band NVNT a 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant4 Peak



Restrict Band NVNT a 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant4 Peak



Restrict Band NVNT n20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant4 Peak



Restrict Band NVNT n20 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz Ant4 Peak



Restrict Band NVNT n40 5270MHz An4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5310MHz Ant4 Peak



Restrict Band NVNT n40 5310MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz Ant4 Peak



Restrict Band NVNT ac20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant4 Peak



Restrict Band NVNT ac20 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant4 Peak



Restrict Band NVNT ac40 5270MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant4 Peak



Restrict Band NVNT ac40 5310MHz Ant4 Average





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.


Address: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant4 Peak



Restrict Band NVNT ac80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5260MHz Ant4 Peak



Restrict Band NVNT ax20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant4 Peak



Restrict Band NVNT ax20 5320MHz An4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant4 Peak



Restrict Band NVNT ax40 5270MHz Ant4 Average





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant4 Peak



Restrict Band NVNT ax80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant4 Peak



Restrict Band NVNT ax80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Ant3 Power (dBm)	Ant4 Power (dBm)	Gain (dBi)	Total E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5260	-50.03	-49.72	8.11	56.48	Peak	68.2	Pass
NVNT	n20	5260	-58.82	-58.35	8.11	47.77	Average	54	Pass
NVNT	n20	5260	-46.51	-45.58	8.11	60.33	Peak	68.2	Pass
NVNT	n20	5260	-56.62	-56.48	8.11	49.80	Average	54	Pass
NVNT	n20	5260	-49.19	-49.15	8.11	57.18	Peak	68.2	Pass
NVNT	n20	5260	-57.31	-57.5	8.11	48.94	Average	54	Pass
NVNT	n20	5320	-46.33	-43.77	8.11	61.48	Peak	68.2	Pass
NVNT	n20	5320	-56.02	-56.12	8.11	50.28	Average	54	Pass
NVNT	n20	5320	-45.17	-42.89	8.11	62.47	Peak	68.2	Pass
NVNT	n20	5320	-55.67	-55.65	8.11	50.69	Average	54	Pass
NVNT	n20	5320	-49.8	-49.74	8.11	56.58	Peak	68.2	Pass
NVNT	n20	5320	-57.86	-57.41	8.11	48.72	Average	54	Pass
NVNT	n40	5270	-50.6	-50.18	8.11	55.96	Peak	68.2	Pass
NVNT	n40	5270	-58.87	-58.68	8.11	47.57	Average	54	Pass
NVNT	n40	5270	-46.37	-45.3	8.11	60.55	Peak	68.2	Pass
NVNT	n40	5270	-56.59	-56.45	8.11	49.83	Average	54	Pass
NVNT	n40	5270	-48.87	-48.52	8.11	57.66	Peak	68.2	Pass
NVNT	n40	5270	-57.33	-57.66	8.11	48.86	Average	54	Pass
NVNT	n40	5310	-46.1	-45.58	8.11	60.52	Peak	68.2	Pass
NVNT	n40	5310	-55.79	-55.56	8.11	50.67	Average	54	Pass
NVNT	n40	5310	-44.99	-41.41	8.11	63.51	Peak	68.2	Pass
NVNT	n40	5310	-55.79	-55.46	8.11	50.73	Average	54	Pass
NVNT	n40	5310	-51.33	-50.47	8.11	55.47	Peak	68.2	Pass
NVNT	n40	5310	-57.7	-57.68	8.11	48.66	Average	54	Pass
NVNT	ac20	5260	-50.91	-51.57	8.11	55.12	Peak	68.2	Pass
NVNT	ac20	5260	-58.98	-58.65	8.11	47.54	Average	54	Pass
NVNT	ac20	5260	-46.1	-46.47	8.11	60.07	Peak	68.2	Pass
NVNT	ac20	5260	-56.25	-56.68	8.11	49.89	Average	54	Pass
NVNT	ac20	5260	-49.41	-48.1	8.11	57.64	Peak	68.2	Pass
NVNT	ac20	5260	-57.38	-57.4	8.11	48.96	Average	54	Pass
NVNT	ac20	5320	-43.5	-42.37	8.11	63.45	Peak	68.2	Pass
NVNT	ac20	5320	-56.32	-56	8.11	50.19	Average	54	Pass
NVNT	ac20	5320	-42.07	-42.37	8.11	64.13	Peak	68.2	Pass
NVNT	ac20	5320	-55.87	-55.63	8.11	50.60	Average	54	Pass
NVNT	ac20	5320	-50.8	-50.22	8.11	55.85	Peak	68.2	Pass
NVNT	ac20	5320	-57.43	-57.26	8.11	49.00	Average	54	Pass
NVNT	ac40	5270	-50.28	-50.85	8.11	55.79	Peak	68.2	Pass
NVNT	ac40	5270	-58.87	-58.86	8.11	47.48	Average	54	Pass
NVNT	ac40	5270	-46.59	-46.43	8.11	59.84	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5270	-56.68	-56.68	8.11	49.67	Average	54	Pass
NVNT	ac40	5270	-48.8	-49.01	8.11	57.44	Peak	68.2	Pass
NVNT	ac40	5270	-57.62	-57.19	8.11	48.95	Average	54	Pass
NVNT	ac40	5310	-44.71	-43.34	8.11	62.38	Peak	68.2	Pass
NVNT	ac40	5310	-54.66	-56.13	8.11	51.01	Average	54	Pass
NVNT	ac40	5310	-42.67	-40.11	8.11	65.14	Peak	68.2	Pass
NVNT	ac40	5310	-54.66	-56.01	8.11	51.07	Average	54	Pass
NVNT	ac40	5310	-50.7	-49.77	8.11	56.14	Peak	68.2	Pass
NVNT	ac40	5310	-57.81	-58.06	8.11	48.41	Average	54	Pass
NVNT	ac80	5290	-51.01	-47.8	8.11	57.23	Peak	68.2	Pass
NVNT	ac80	5290	-57.98	-58.49	8.11	48.12	Average	54	Pass
NVNT	ac80	5290	-45.98	-45.63	8.11	60.55	Peak	68.2	Pass
NVNT	ac80	5290	-55.37	-55.56	8.11	50.88	Average	54	Pass
NVNT	ac80	5290	-47.48	-46.74	8.11	59.25	Peak	68.2	Pass
NVNT	ac80	5290	-55.37	-55.56	8.11	50.88	Average	54	Pass
NVNT	ac80	5290	-48.28	-47.17	8.11	58.66	Peak	68.2	Pass
NVNT	ac80	5290	-55.78	-55.51	8.11	50.70	Average	54	Pass
NVNT	ac80	5290	-45.07	-43.9	8.11	61.90	Peak	68.2	Pass
NVNT	ac80	5290	-55.73	-55.43	8.11	50.77	Average	54	Pass
NVNT	ac80	5290	-49.43	-49.64	8.11	56.81	Peak	68.2	Pass
NVNT	ac80	5290	-57.67	-57.47	8.11	48.78	Average	54	Pass
NVNT	ax20	5260	-50.78	-49.43	8.11	56.30	Peak	68.2	Pass
NVNT	ax20	5260	-58.95	-58.8	8.11	47.47	Average	54	Pass
NVNT	ax20	5260	-46.85	-45.31	8.11	60.34	Peak	68.2	Pass
NVNT	ax20	5260	-56.64	-56.62	8.11	49.72	Average	54	Pass
NVNT	ax20	5260	-48.79	-49.45	8.11	57.24	Peak	68.2	Pass
NVNT	ax20	5260	-57.44	-57.05	8.11	49.11	Average	54	Pass
NVNT	ax20	5320	-45.99	-40.36	8.11	64.03	Peak	68.2	Pass
NVNT	ax20	5320	-55.58	-56.19	8.11	50.47	Average	54	Pass
NVNT	ax20	5320	-43.96	-40.36	8.11	64.55	Peak	68.2	Pass
NVNT	ax20	5320	-55.52	-55.62	8.11	50.78	Average	54	Pass
NVNT	ax20	5320	-49.37	-49.81	8.11	56.76	Peak	68.2	Pass
NVNT	ax20	5320	-57.71	-57.75	8.11	48.62	Average	54	Pass
NVNT	ax40	5270	-50.98	-50.04	8.11	55.86	Peak	68.2	Pass
NVNT	ax40	5270	-58.78	-58.66	8.11	47.63	Average	54	Pass
NVNT	ax40	5270	-46.24	-46.37	8.11	60.04	Peak	68.2	Pass
NVNT	ax40	5270	-56.57	-56.64	8.11	49.74	Average	54	Pass
NVNT	ax40	5270	-48.69	-49.86	8.11	57.11	Peak	68.2	Pass
NVNT	ax40	5270	-57.16	-56.79	8.11	49.38	Average	54	Pass
NVNT	ax40	5310	-46.75	-39.66	8.11	64.45	Peak	68.2	Pass
NVNT	ax40	5310	-56.64	-55.88	8.11	50.10	Average	54	Pass
NVNT	ax40	5310	-42.31	-39.66	8.11	65.56	Peak	68.2	Pass
NVNT	ax40	5310	-55.83	-55.49	8.11	50.69	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax40	5310	-49.02	-49.67	8.11	57.02	Peak	68.2	Pass
NVNT	ax40	5310	-57.29	-57.73	8.11	48.84	Average	54	Pass
NVNT	ax80	5290	-45.7	-44.26	8.11	61.43	Peak	68.2	Pass
NVNT	ax80	5290	-55.69	-55.61	8.11	50.70	Average	54	Pass
NVNT	ax80	5290	-44.52	-43.8	8.11	62.20	Peak	68.2	Pass
NVNT	ax80	5290	-55.69	-55.5	8.11	50.75	Average	54	Pass
NVNT	ax80	5290	-49.63	-49.79	8.11	56.64	Peak	68.2	Pass
NVNT	ax80	5290	-57.55	-58.11	8.11	48.53	Average	54	Pass
NVNT	ax80	5290	-49.72	-50.46	8.11	56.27	Peak	68.2	Pass
NVNT	ax80	5290	-58.1	-58.95	8.11	47.84	Average	54	Pass
NVNT	ax80	5290	-45.23	-45.43	8.11	61.02	Peak	68.2	Pass
NVNT	ax80	5290	-55.63	-55.42	8.11	50.82	Average	54	Pass
NVNT	ax80	5290	-47.54	-46.98	8.11	59.10	Peak	68.2	Pass
NVNT	ax80	5290	-55.82	-55.63	8.11	50.62	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Test Model: E1M-L159Y

Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	An1	4500	-52.16	5.1	-	48.17	Peak	68.2	Pass
NVNT	a	5260	An1	4500	-59.21	5.1	0.24	41.36	Average	54	Pass
NVNT	a	5260	An1	5118.54	-46.48	5.1	-	53.85	Peak	68.2	Pass
NVNT	a	5260	An1	5120.88	-57	5.1	0.24	43.57	Average	54	Pass
NVNT	a	5260	An1	5150	-48.64	5.1	-	51.69	Peak	68.2	Pass
NVNT	a	5260	An1	5150	-57.81	5.1	0.24	42.76	Average	54	Pass
NVNT	a	5320	An1	5350	-48.34	5.1	-	51.99	Peak	68.2	Pass
NVNT	a	5320	An1	5350	-56.84	5.1	0.24	43.73	Average	54	Pass
NVNT	a	5320	An1	5350.2	-44.76	5.1	-	55.57	Peak	68.2	Pass
NVNT	a	5320	An1	5350.4	-56.5	5.1	0.24	44.07	Average	54	Pass
NVNT	a	5320	An1	5460	-49.29	5.1	-	51.04	Peak	68.2	Pass
NVNT	a	5320	An1	5460	-58.09	5.1	0.24	42.48	Average	54	Pass
NVNT	n20	5260	An1	4500	-50.04	5.1	-	50.29	Peak	68.2	Pass
NVNT	n20	5260	An1	4500	-59.14	5.1	0.12	41.31	Average	54	Pass
NVNT	n20	5260	An1	5110.74	-46.31	5.1	-	54.02	Peak	68.2	Pass
NVNT	n20	5260	An1	5080.32	-56.91	5.1	0.12	43.54	Average	54	Pass
NVNT	n20	5260	An1	5150	-48.45	5.1	-	51.88	Peak	68.2	Pass
NVNT	n20	5260	An1	5150	-57.42	5.1	0.12	43.03	Average	54	Pass
NVNT	n20	5320	An1	5350	-47.57	5.1	-	52.76	Peak	68.2	Pass
NVNT	n20	5320	An1	5350	-55.75	5.1	0.12	44.70	Average	54	Pass
NVNT	n20	5320	An1	5350.4	-42.01	5.1	-	58.32	Peak	68.2	Pass
NVNT	n20	5320	An1	5350	-55.75	5.1	0.12	44.70	Average	54	Pass
NVNT	n20	5320	An1	5460	-51.31	5.1	-	49.02	Peak	68.2	Pass
NVNT	n20	5320	An1	5460	-58.29	5.1	0.12	42.16	Average	54	Pass
NVNT	n40	5270	An1	4500	-50.42	5.1	-	49.91	Peak	68.2	Pass
NVNT	n40	5270	An1	4500	-59.49	5.1	0.23	41.07	Average	54	Pass
NVNT	n40	5270	An1	5132.61	-46.74	5.1	-	53.59	Peak	68.2	Pass
NVNT	n40	5270	An1	5045.94	-57.08	5.1	0.23	43.48	Average	54	Pass
NVNT	n40	5270	An1	5150	-50	5.1	-	50.33	Peak	68.2	Pass
NVNT	n40	5270	An1	5150	-57.3	5.1	0.23	43.26	Average	54	Pass
NVNT	n40	5310	An1	5350	-45.99	5.1	-	54.34	Peak	68.2	Pass
NVNT	n40	5310	An1	5350	-56.68	5.1	0.24	43.89	Average	54	Pass
NVNT	n40	5310	An1	5350.6	-44.79	5.1	-	55.54	Peak	68.2	Pass
NVNT	n40	5310	An1	5351	-56.15	5.1	0.24	44.42	Average	54	Pass
NVNT	n40	5310	An1	5460	-49.57	5.1	-	50.76	Peak	68.2	Pass
NVNT	n40	5310	An1	5460	-58.01	5.1	0.24	42.56	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5260	An1	4500	-51.66	5.1	-	48.67	Peak	68.2	Pass
NVNT	ac20	5260	An1	4500	-58.55	5.1	0.12	41.90	Average	54	Pass
NVNT	ac20	5260	An1	5071.74	-46.77	5.1	-	53.56	Peak	68.2	Pass
NVNT	ac20	5260	An1	5124	-57.08	5.1	0.12	43.37	Average	54	Pass
NVNT	ac20	5260	An1	5150	-48	5.1	-	52.33	Peak	68.2	Pass
NVNT	ac20	5260	An1	5150	-58.29	5.1	0.12	42.16	Average	54	Pass
NVNT	ac20	5320	An1	5350	-46.79	5.1	-	53.54	Peak	68.2	Pass
NVNT	ac20	5320	An1	5350	-56.41	5.1	0.12	44.04	Average	54	Pass
NVNT	ac20	5320	An1	5351.6	-39.23	5.1	-	61.10	Peak	68.2	Pass
NVNT	ac20	5320	An1	5352	-56.1	5.1	0.12	44.35	Average	54	Pass
NVNT	ac20	5320	An1	5460	-50.36	5.1	-	49.97	Peak	68.2	Pass
NVNT	ac20	5320	An1	5460	-58.17	5.1	0.12	42.28	Average	54	Pass
NVNT	ac40	5270	An1	4500	-50.35	5.1	-	49.98	Peak	68.2	Pass
NVNT	ac40	5270	An1	4500	-59.49	5.1	0.24	41.08	Average	54	Pass
NVNT	ac40	5270	An1	4955.22	-46.77	5.1	-	53.56	Peak	68.2	Pass
NVNT	ac40	5270	An1	4805.37	-57	5.1	0.24	43.57	Average	54	Pass
NVNT	ac40	5270	An1	5150	-49.47	5.1	-	50.86	Peak	68.2	Pass
NVNT	ac40	5270	An1	5150	-57.76	5.1	0.24	42.81	Average	54	Pass
NVNT	ac40	5310	An1	5350	-43.27	5.1	-	57.06	Peak	68.2	Pass
NVNT	ac40	5310	An1	5350	-56.41	5.1	0.24	44.16	Average	54	Pass
NVNT	ac40	5310	An1	5350.2	-43.16	5.1	-	57.17	Peak	68.2	Pass
NVNT	ac40	5310	An1	5350.2	-55.83	5.1	0.24	44.74	Average	54	Pass
NVNT	ac40	5310	An1	5460	-51.01	5.1	-	49.32	Peak	68.2	Pass
NVNT	ac40	5310	An1	5460	-58.13	5.1	0.24	42.44	Average	54	Pass
NVNT	ac80	5290	An1	4500	-50.56	5.1	-	49.77	Peak	68.2	Pass
NVNT	ac80	5290	An1	4500	-58.87	5.1	0.47	41.93	Average	54	Pass
NVNT	ac80	5290	An1	5148.15	-46.39	5.1	-	53.94	Peak	68.2	Pass
NVNT	ac80	5290	An1	5149.89	-55.98	5.1	0.47	44.82	Average	54	Pass
NVNT	ac80	5290	An1	5150	-47.84	5.1	-	52.49	Peak	68.2	Pass
NVNT	ac80	5290	An1	5150	-55.98	5.1	0.47	44.82	Average	54	Pass
NVNT	ac80	5290	An1	5350	-45.57	5.1	-	54.76	Peak	68.2	Pass
NVNT	ac80	5290	An1	5350	-56.12	5.1	0.47	44.68	Average	54	Pass
NVNT	ac80	5290	An1	5353.5	-45.23	5.1	-	55.10	Peak	68.2	Pass
NVNT	ac80	5290	An1	5350	-56.12	5.1	0.47	44.68	Average	54	Pass
NVNT	ac80	5290	An1	5460	-50.21	5.1	-	50.12	Peak	68.2	Pass
NVNT	ac80	5290	An1	5460	-58.41	5.1	0.47	42.39	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5260MHz An1 Peak



Restrict Band NVNT a 5260MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz An1 Peak



Restrict Band NVNT a 5320MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz An1 Peak



Restrict Band NVNT n20 5260MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz An1 Peak



Restrict Band NVNT n20 5320MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz An1 Peak



Restrict Band NVNT n40 5270MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5310MHz An1 Peak



Restrict Band NVNT n40 5310MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz An1 Peak



Restrict Band NVNT ac20 5260MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz An1 Peak



Restrict Band NVNT ac20 5320MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz An1 Peak



Restrict Band NVNT ac40 5270MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz An1 Peak



Restrict Band NVNT ac40 5310MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz An1 Peak



Restrict Band NVNT ac80 5290MHz An1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity