



5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:01:17

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:01:58

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:02:38

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:03:33

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:04:56

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:06:24

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:07:52

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:09:15

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:10:39

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:12:04

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:13:29


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:14:55


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:52:16

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:53:09

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:54:02

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:55:09

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:56:54

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19244E-RF Testers: Baylon Ma
Date: 28_SEP, 2025 14:58:45


15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




15MHz_High_QPSK_1@0(30MHz~26.7GHz)




20MHz_Low_QPSK_1@0(30MHz~26.7GHz)



20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




20MHz_High_QPSK_1@0(30MHz~26.7GHz)




Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:27:48

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:28:41

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:29:26

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:30:14

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:31:00

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Testert:Braylon Ma
Date: 28_SEP,2025 14:31:45

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:33:36

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:34:22

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:35:07

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:35:58

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:37:29

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Braylon Ma
Date: 28.SEP.2025 14:39:03

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:41:49

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:43:30

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:45:05

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:46:43

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:48:18

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X19244E-RF Tester: Berylon Ma
Date: 28. SEP. 2025 14:49:54