



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:16:00

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:17:59

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:20:00

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:22:21

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:24:19


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2507X19931E-RF Tester:Braylon Ma
Date: 27.OCT.2025 12:26:20


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 10:55:43

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 10:56:42

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 10:57:42

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 11:01:17

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 11:03:20

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 11:05:30

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:08:00

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:10:10

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:12:21

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:15:03

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:17:16


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 11:19:28


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:43:42

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:44:41

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:45:40

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:46:41

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:47:41

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Testers: Baylon Ma
Date: 27.OCT.2025 12:48:39

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:49:39

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:50:39

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:51:37

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:52:52

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:55:00

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Braylon Ma
Date: 27.OCT.2025 12:56:58

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 12:59:16

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 13:01:15

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 13:03:13

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 13:05:53

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 13:07:58

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X19931E-RF Tester: Baylon Ma
Date: 27.OCT.2025 13:10:03