External Photos





STOP
REAR
FRONT
DRYER
TEMP

STOP
REAR
FRONT
DRYER
TEMP

NOTICE
Built in strong magnet, equipped with cardiac pacemaker and other auxiliary medical equipment, do not use in close proximity.
FCC ID:2BLWUT181923100A
This device complies with Part 15 of the FCC Rules
The operation needs to meet the following two conditions:
(1)This device may not cause harmful interference.
(2)This device must accept any interference received, including interference that may cause undesired operation.
UVC STERILIZATION
NOZZLE CLEANING
ECO
SEAT TEMP

TEMP
DRYER
FRONT
REAR
STOP

HEELLIGHT
HOME
CONTROL
SYSTEM
ON
ADJUSTMENT
DOCK

STOP
REAR
FRONT
DRYER
TEMP

NOTICE
UVC STERILIZATION
NOZZLE CLEANING
SAVE TEMP