













Appendix F: Frequency Stability

Test Result

Voltage										
Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage [Vdc]	Temperature (°C)	FL (MHz)	FH (MHz)	Limit (MHz)	Verdict
Band 4	1.4MHz	QPSK	19957	6RB#0	VN	NT	1710.15747	1711.23787	1710-1755	PASS
Band 4	1.4MHz	QPSK	19957	6RB#0	VL	NT	1710.15955	1711.23785	1710-1755	PASS
Band 4	1.4MHz	QPSK	19957	6RB#0	VH	NT	1710.15907	1711.23777	1710-1755	PASS
Band 4	1.4MHz	16QAM	19957	6RB#0	VN	NT	1710.15774	1711.23874	1710-1755	PASS
Band 4	1.4MHz	16QAM	19957	6RB#0	VL	NT	1710.15519	1711.23809	1710-1755	PASS
Band 4	1.4MHz	16QAM	19957	6RB#0	VH	NT	1710.15534	1711.23854	1710-1755	PASS
Band 4	1.4MHz	QPSK	20175	6RB#0	VN	NT	1731.95821	1733.03791	1710-1755	PASS
Band 4	1.4MHz	QPSK	20175	6RB#0	VL	NT	1731.95821	1733.03931	1710-1755	PASS
Band 4	1.4MHz	QPSK	20175	6RB#0	VH	NT	1731.95787	1733.03887	1710-1755	PASS
Band 4	1.4MHz	16QAM	20175	6RB#0	VN	NT	1731.95866	1733.03876	1710-1755	PASS
Band 4	1.4MHz	16QAM	20175	6RB#0	VL	NT	1731.9606	1733.0397	1710-1755	PASS
Band 4	1.4MHz	16QAM	20175	6RB#0	VH	NT	1731.96011	1733.03861	1710-1755	PASS
Band 4	1.4MHz	QPSK	20393	6RB#0	VN	NT	1753.75669	1754.84039	1710-1755	PASS
Band 4	1.4MHz	QPSK	20393	6RB#0	VL	NT	1753.75714	1754.84004	1710-1755	PASS
Band 4	1.4MHz	QPSK	20393	6RB#0	VH	NT	1753.75757	1754.83987	1710-1755	PASS
Band 4	1.4MHz	16QAM	20393	6RB#0	VN	NT	1753.75914	1754.83654	1710-1755	PASS
Band 4	1.4MHz	16QAM	20393	6RB#0	VL	NT	1753.75893	1754.83643	1710-1755	PASS
Band 4	1.4MHz	16QAM	20393	6RB#0	VH	NT	1753.75858	1754.83598	1710-1755	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	3MHz	QPSK	1996 5	15RB# 0	VN	NT	1710.15 875	1712.83 665	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	VL	NT	1710.15 84	1712.83 98	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	VH	NT	1710.16 098	1712.83 868	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	VN	NT	1710.16 172	1712.83 462	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	VL	NT	1710.16 173	1712.82 903	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	VH	NT	1710.16 087	1712.83 217	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	VN	NT	1731.16 44	1733.84 41	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	VL	NT	1731.16 571	1733.83 761	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	VH	NT	1731.16 523	1733.83 963	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	VN	NT	1731.16 764	1733.83 744	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	VL	NT	1731.16 569	1733.83 079	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	VH	NT	1731.16 305	1733.84 025	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	VN	NT	1752.16 047	1754.83 517	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	VL	NT	1752.15 847	1754.83 937	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	VH	NT	1752.16 185	1754.83 395	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	VN	NT	1752.16 071	1754.83 251	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	VL	NT	1752.16 28	1754.83 53	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	VH	NT	1752.16 107	1754.83 277	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	VN	NT	1710.26 108	1714.73 828	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	VL	NT	1710.26 076	1714.73 366	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	VH	NT	1710.25 799	1714.73 589	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	5MHz	QPSK	2017 5	25RB# 0	VN	NT	1730.26 352	1734.73 742	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	VL	NT	1730.26 152	1734.73 912	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	VH	NT	1730.26 703	1734.73 623	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	VN	NT	1730.26 401	1734.73 861	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	VL	NT	1730.26 909	1734.74 139	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	VH	NT	1730.26 55	1734.73 43	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	VN	NT	1750.25 633	1754.73 073	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	VL	NT	1750.25 714	1754.73 634	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	VH	NT	1750.26 71	1754.73 79	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	VN	NT	1750.25 912	1754.73 452	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	VL	NT	1750.25 968	1754.73 418	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	VH	NT	1750.25 8	1754.73	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	VN	NT	1710.53 286	1719.45 846	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	VL	NT	1710.53 352	1719.45 002	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	VH	NT	1710.53 517	1719.45 757	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	VN	NT	1710.54 024	1719.45 444	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	VL	NT	1710.53 558	1719.45 278	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	VH	NT	1710.53 277	1719.45 747	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	VN	NT	1728.04 062	1736.96 232	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	VL	NT	1728.03 436	1736.97 136	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	VH	NT	1728.05 24	1736.97 63	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	10MH z	16QA M	2017 5	50RB# 0	VN	NT	1728.04 272	1736.96 762	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	VL	NT	1728.04 462	1736.96 882	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	VH	NT	1728.04 123	1736.97 123	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	VN	NT	1745.52 905	1754.46 745	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	VL	NT	1745.53 123	1754.45 473	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	VH	NT	1745.51 208	1754.45 258	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	VN	NT	1745.52 681	1754.45 491	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	VL	NT	1745.53 044	1754.45 404	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	VH	NT	1745.52 448	1754.46 268	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	VN	NT	1710.80 436	1724.18 836	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	VL	NT	1710.78 183	1724.18 783	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	VH	NT	1710.79 833	1724.18 833	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	VN	NT	1710.80 128	1724.18 028	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	VL	NT	1710.80 038	1724.18 738	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	VH	NT	1710.80 522	1724.17 922	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	VN	NT	1725.82 355	1739.18 755	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	VL	NT	1725.82 929	1739.20 429	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	VH	NT	1725.82 73	1739.19 83	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	VN	NT	1725.83 338	1739.19 138	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	VL	NT	1725.83 702	1739.19 502	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	VH	NT	1725.82 713	1739.18 813	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	15MH z	QPSK	2032 5	75RB# 0	VN	NT	1740.80 543	1754.17 643	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	VL	NT	1740.78 832	1754.18 432	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	VH	NT	1740.79 767	1754.16 667	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	VN	NT	1740.81 228	1754.19 028	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	VL	NT	1740.79 697	1754.17 997	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	VH	NT	1740.80 371	1754.16 371	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	VN	NT	1711.08 067	1728.93 567	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	VL	NT	1711.07 426	1728.94 626	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	VH	NT	1711.09 61	1728.91 71	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	VN	NT	1711.09 005	1728.92 605	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	VL	NT	1711.07 751	1728.92 051	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	VH	NT	1711.09 406	1728.93 506	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	VN	NT	1723.61 046	1741.43 746	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	VL	NT	1723.62 542	1741.41 642	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	VH	NT	1723.62 684	1741.42 384	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	VN	NT	1723.62 191	1741.43 891	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	VL	NT	1723.62 558	1741.42 058	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	VH	NT	1723.61 924	1741.43 224	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	VN	NT	1736.08 196	1753.88 396	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	VL	NT	1736.07 92	1753.88 72	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	VH	NT	1736.09 494	1753.90 694	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	20MH z	16QA M	2030 0	100RB #0	VN	NT	1736.05 803	1753.89 703	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	VL	NT	1736.08 076	1753.88 576	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	VH	NT	1736.06 016	1753.88 916	1710-1 755	PAS S

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage [Vdc]	Temperature (°C)	FL (MHz)	FH (MHz)	Limit (MHz)	Verdict
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	-30	1710.15 556	1711.23 876	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	-20	1710.15 604	1711.23 824	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	-10	1710.15 732	1711.23 802	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	0	1710.15 753	1711.23 793	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	10	1710.15 695	1711.23 675	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	20	1710.15 739	1711.23 789	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	30	1710.15 607	1711.23 747	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	40	1710.15 776	1711.23 776	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	1995 7	6RB#0	NV	50	1710.15 668	1711.23 718	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	-30	1710.15 497	1711.23 757	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	-20	1710.15 853	1711.23 763	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	-10	1710.15 517	1711.23 717	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	0	1710.15 616	1711.23 776	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	10	1710.15 464	1711.23 834	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	20	1710.15 679	1711.23 879	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	30	1710.15 559	1711.23 709	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	40	1710.15 674	1711.23 864	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	1995 7	6RB#0	NV	50	1710.15 509	1711.23 719	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	-30	1731.95 716	1733.03 896	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	-20	1731.95 807	1733.03 857	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	-10	1731.95 905	1733.03 825	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	0	1731.95 79	1733.03 85	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	10	1731.95 823	1733.03 743	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	20	1731.95 834	1733.03 984	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	30	1731.95 781	1733.03 791	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	40	1731.95 7	1733.03 94	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2017 5	6RB#0	NV	50	1731.95 833	1733.04 003	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	-30	1731.95 614	1733.03 814	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	-20	1731.95 807	1733.03 817	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	-10	1731.95 801	1733.03 881	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	0	1731.96 111	1733.03 791	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	10	1731.96 174	1733.03 924	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	20	1731.96 179	1733.03 909	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	30	1731.96 058	1733.03 938	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	40	1731.95 712	1733.03 882	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2017 5	6RB#0	NV	50	1731.95 987	1733.03 907	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	-30	1753.75 719	1754.83 759	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	-20	1753.75 882	1754.83 992	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	-10	1753.75 802	1754.83 892	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	0	1753.75 733	1754.83 793	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	10	1753.75 657	1754.84 017	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	20	1753.75 876	1754.84 036	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	30	1753.75 776	1754.83 916	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	40	1753.75 675	1754.83 745	1710-1 755	PAS S
Ban d4	1.4MH z	QPSK	2039 3	6RB#0	NV	50	1753.75 682	1754.83 892	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	-30	1753.75 836	1754.83 466	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	-20	1753.75 862	1754.83 702	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	-10	1753.75 845	1754.83 685	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	0	1753.75 925	1754.83 595	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	10	1753.75 938	1754.83 598	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	20	1753.75 888	1754.83 718	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	30	1753.75 918	1754.83 748	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	40	1753.75 86	1754.83 76	1710-1 755	PAS S
Ban d4	1.4MH z	16QA M	2039 3	6RB#0	NV	50	1753.75 96	1754.83 62	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	-30	1710.16 216	1712.84 096	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	-20	1710.16 112	1712.84 362	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	-10	1710.16 143	1712.84 033	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	0	1710.15 983	1712.83 223	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	10	1710.16 145	1712.84 065	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	20	1710.16 212	1712.83 722	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	30	1710.16 129	1712.83 499	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	40	1710.16 129	1712.84 079	1710-1 755	PAS S
Ban d4	3MHz	QPSK	1996 5	15RB# 0	NV	50	1710.16 187	1712.84 297	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	-30	1710.16 204	1712.83 374	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	-20	1710.16 173	1712.83 243	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	-10	1710.16 318	1712.83 168	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	0	1710.16 23	1712.83 41	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	10	1710.16 308	1712.82 908	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	20	1710.16 064	1712.83 324	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	30	1710.16 152	1712.83 382	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	40	1710.16 242	1712.83 162	1710-1 755	PAS S
Ban d4	3MHz	16QA M	1996 5	15RB# 0	NV	50	1710.16 093	1712.82 713	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	-30	1731.16 507	1733.83 787	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	-20	1731.16 548	1733.84 368	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	-10	1731.16 471	1733.84 121	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	0	1731.16 534	1733.83 584	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	10	1731.16 43	1733.84 34	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	20	1731.16 357	1733.84 247	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	30	1731.16 53	1733.84 35	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	40	1731.16 482	1733.84 452	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2017 5	15RB# 0	NV	50	1731.16 56	1733.84 01	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	-30	1731.16 738	1733.83 108	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	-20	1731.16 56	1733.83 74	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	-10	1731.16 389	1733.83 669	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	0	1731.16 504	1733.83 434	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	10	1731.16 616	1733.83 236	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	20	1731.16 528	1733.83 688	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	30	1731.16 47	1733.83 6	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	40	1731.16 549	1733.83 289	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2017 5	15RB# 0	NV	50	1731.16 652	1733.83 562	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	-30	1752.16 162	1754.83 592	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	-20	1752.16 284	1754.83 814	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	-10	1752.15 99	1754.83 54	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	0	1752.15 97	1754.83 39	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	10	1752.15 821	1754.83 651	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	20	1752.15 816	1754.83 476	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	30	1752.16 04	1754.83 41	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	40	1752.16 069	1754.83 249	1710-1 755	PAS S
Ban d4	3MHz	QPSK	2038 5	15RB# 0	NV	50	1752.15 824	1754.83 674	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	-30	1752.15 983	1754.83 273	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	-20	1752.16 438	1754.83 298	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	-10	1752.16 104	1754.83 504	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	0	1752.15 968	1754.83 128	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	10	1752.15 907	1754.83 487	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	20	1752.16 416	1754.83 346	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	30	1752.16 131	1754.83 471	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	40	1752.15 864	1754.83 464	1710-1 755	PAS S
Ban d4	3MHz	16QA M	2038 5	15RB# 0	NV	50	1752.16 056	1754.83 486	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	-30	1710.26 584	1714.73 074	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	-20	1710.25 624	1714.73 714	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	-10	1710.25 928	1714.73 258	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	0	1710.26 166	1714.73 256	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	10	1710.25 73	1714.72 76	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	20	1710.26 142	1714.73 802	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	30	1710.25 815	1714.73 425	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	40	1710.26 123	1714.73 943	1710-1 755	PAS S
Ban d4	5MHz	16QA M	1997 5	25RB# 0	NV	50	1710.26 362	1714.73 842	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	-30	1730.25 772	1734.73 942	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	-20	1730.26 556	1734.74 186	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	-10	1730.26 719	1734.73 779	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	0	1730.26 216	1734.73 676	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	10	1730.26 35	1734.74 04	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	20	1730.26 782	1734.73 512	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	30	1730.26 647	1734.73 567	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	40	1730.26 583	1734.73 563	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2017 5	25RB# 0	NV	50	1730.25 707	1734.73 967	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	-30	1730.25 785	1734.74 355	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	-20	1730.26 205	1734.73 495	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	-10	1730.26 87	1734.73 86	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	0	1730.26 467	1734.73 867	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	10	1730.26 233	1734.73 513	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	20	1730.26 747	1734.73 437	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	30	1730.26 544	1734.74 084	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	40	1730.26 123	1734.73 493	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2017 5	25RB# 0	NV	50	1730.25 369	1734.73 569	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	-30	1750.26 121	1754.73 851	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	-20	1750.26 257	1754.73 407	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	-10	1750.25 445	1754.73 135	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	0	1750.26 258	1754.73 228	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	10	1750.25 932	1754.73 402	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	20	1750.26 077	1754.73 617	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	30	1750.26 352	1754.74 092	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	40	1750.26 388	1754.73 568	1710-1 755	PAS S
Ban d4	5MHz	QPSK	2037 5	25RB# 0	NV	50	1750.25 713	1754.73 943	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	-30	1750.25 849	1754.73 889	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	-20	1750.25 731	1754.72 881	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	-10	1750.25 958	1754.73 058	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	0	1750.26 105	1754.73 515	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	10	1750.25 831	1754.73 061	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	20	1750.26 131	1754.73 851	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	30	1750.26 169	1754.73 409	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	40	1750.25 896	1754.73 356	1710-1 755	PAS S
Ban d4	5MHz	16QA M	2037 5	25RB# 0	NV	50	1750.26 336	1754.73 326	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	-30	1710.53 491	1719.44 851	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	-20	1710.52 971	1719.46 061	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	-10	1710.53 276	1719.45 396	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	0	1710.53 016	1719.45 416	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	10	1710.53 727	1719.45 427	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	20	1710.53 72	1719.45 3	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	30	1710.53 148	1719.45 528	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	40	1710.53 437	1719.44 907	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2000 0	50RB# 0	NV	50	1710.53 241	1719.45 541	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	-30	1710.52 946	1719.45 526	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	-20	1710.53 005	1719.45 975	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	-10	1710.53 564	1719.45 154	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	0	1710.52 891	1719.44 931	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	10	1710.53 239	1719.45 579	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	20	1710.53 739	1719.45 869	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	30	1710.53 835	1719.45 755	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	40	1710.53 573	1719.45 153	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2000 0	50RB# 0	NV	50	1710.52 903	1719.45 663	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	-30	1728.04 119	1736.96 209	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	-20	1728.04 491	1736.96 491	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	-10	1728.04 662	1736.96 522	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	0	1728.04 042	1736.96 282	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	10	1728.04 162	1736.96 792	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	20	1728.04 463	1736.96 063	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	30	1728.04 943	1736.96 253	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	40	1728.05 378	1736.96 358	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2017 5	50RB# 0	NV	50	1728.03 954	1736.97 454	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	-30	1728.04 181	1736.96 271	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	-20	1728.05 563	1736.96 883	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	-10	1728.05 068	1736.96 538	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	0	1728.04 669	1736.96 749	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	10	1728.04 32	1736.96 67	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	20	1728.03 685	1736.96 855	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	30	1728.03 735	1736.96 585	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	40	1728.04 746	1736.96 896	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2017 5	50RB# 0	NV	50	1728.05 439	1736.96 409	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	-30	1745.53 03	1754.45 68	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	-20	1745.52 91	1754.46 75	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	-10	1745.53 389	1754.45 459	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	0	1745.53 184	1754.45 334	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	10	1745.52 617	1754.46 037	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	20	1745.52 116	1754.44 936	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	30	1745.51 996	1754.46 026	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	40	1745.52 878	1754.46 278	1710-1 755	PAS S
Ban d4	10MH z	QPSK	2035 0	50RB# 0	NV	50	1745.52 994	1754.46 574	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	-30	1745.52 875	1754.45 765	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	-20	1745.53 051	1754.45 251	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	-10	1745.53 744	1754.46 324	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	0	1745.53 086	1754.44 976	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	10	1745.53 467	1754.45 567	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	20	1745.53 684	1754.46 874	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	30	1745.53 442	1754.45 442	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	40	1745.53 042	1754.46 302	1710-1 755	PAS S
Ban d4	10MH z	16QA M	2035 0	50RB# 0	NV	50	1745.52 022	1754.45 982	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	-30	1710.80 797	1724.19 197	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	-20	1710.79 289	1724.18 489	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	-10	1710.79 888	1724.19 488	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	0	1710.80 381	1724.20 381	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	10	1710.80 033	1724.18 033	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	20	1710.80 124	1724.18 424	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	30	1710.80 759	1724.17 759	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	40	1710.79 375	1724.17 875	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2002 5	75RB# 0	NV	50	1710.80 073	1724.19 273	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	-30	1710.81 12	1724.18 92	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	-20	1710.80 067	1724.19 167	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	-10	1710.80 763	1724.17 463	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	0	1710.80 767	1724.17 367	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	10	1710.79 278	1724.18 378	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	20	1710.79 07	1724.19 17	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	30	1710.80 796	1724.17 496	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	40	1710.80 887	1724.19 287	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2002 5	75RB# 0	NV	50	1710.80 039	1724.18 039	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	-30	1725.82 347	1739.19 847	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	-20	1725.82 863	1739.19 863	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	-10	1725.82 879	1739.20 079	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	0	1725.83 641	1739.18 341	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	10	1725.83 794	1739.19 694	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	20	1725.82 824	1739.19 824	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	30	1725.82 673	1739.20 373	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	40	1725.82 409	1739.19 609	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2017 5	75RB# 0	NV	50	1725.81 548	1739.21 048	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	-30	1725.83 913	1739.20 113	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	-20	1725.81 584	1739.20 584	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	-10	1725.82 87	1739.19 07	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	0	1725.83 776	1739.20 176	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	10	1725.81 962	1739.19 662	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	20	1725.83 619	1739.20 119	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	30	1725.82 772	1739.18 772	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	40	1725.82 834	1739.19 934	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2017 5	75RB# 0	NV	50	1725.82 062	1739.20 562	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	-30	1740.80 595	1754.18 295	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	-20	1740.78 325	1754.16 725	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	-10	1740.79 925	1754.17 125	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	0	1740.80 489	1754.18 789	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	10	1740.79 857	1754.17 457	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	20	1740.80 747	1754.15 747	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	30	1740.79 343	1754.18 343	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	40	1740.79 765	1754.18 465	1710-1 755	PAS S
Ban d4	15MH z	QPSK	2032 5	75RB# 0	NV	50	1740.80 213	1754.18 113	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	-30	1740.80 133	1754.17 333	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	-20	1740.79 58	1754.16 78	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	-10	1740.79 529	1754.16 729	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	0	1740.78 574	1754.19 474	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	10	1740.79 748	1754.17 748	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	20	1740.79 992	1754.17 192	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	30	1740.80 022	1754.18 722	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	40	1740.79 963	1754.16 463	1710-1 755	PAS S
Ban d4	15MH z	16QA M	2032 5	75RB# 0	NV	50	1740.78 881	1754.17 481	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	-30	1711.09 282	1728.92 582	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	-20	1711.06 795	1728.91 795	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	-10	1711.08 617	1728.91 517	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	0	1711.08 618	1728.96 618	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	10	1711.08 354	1728.93 754	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	20	1711.09 123	1728.93 223	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	30	1711.08 265	1728.91 965	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	40	1711.06 924	1728.91 924	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2005 0	100RB #0	NV	50	1711.07 54	1728.92 94	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	-30	1711.07 227	1728.92 927	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	-20	1711.07 566	1728.94 266	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	-10	1711.07 327	1728.92 827	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	0	1711.07 736	1728.92 336	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	10	1711.08 119	1728.92 519	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	20	1711.08 027	1728.91 527	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	30	1711.07 87	1728.93 57	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	40	1711.09 137	1728.92 037	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2005 0	100RB #0	NV	50	1711.08 232	1728.94 932	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	-30	1723.65 2	1741.41 7	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	-20	1723.63 578	1741.43 378	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	-10	1723.61 93	1741.42 43	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	0	1723.61 37	1741.42 47	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	10	1723.62 927	1741.44 527	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	20	1723.62 972	1741.41 772	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	30	1723.61 981	1741.42 481	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	40	1723.61 711	1741.42 811	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2017 5	100RB #0	NV	50	1723.63 766	1741.43 366	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	-30	1723.64 273	1741.42 373	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	-20	1723.61 892	1741.42 992	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	-10	1723.63 824	1741.42 124	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	0	1723.62 391	1741.42 391	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	10	1723.63 882	1741.42 382	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	20	1723.61 094	1741.44 094	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	30	1723.62 663	1741.42 963	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	40	1723.62 793	1741.41 493	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2017 5	100RB #0	NV	50	1723.62 071	1741.43 171	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	-30	1736.07 388	1753.90 388	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	-20	1736.07 79	1753.90 69	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	-10	1736.07 601	1753.88 501	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	0	1736.06 95	1753.88 95	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	10	1736.07 635	1753.90 435	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	20	1736.08 683	1753.88 683	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	30	1736.08 005	1753.87 305	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	40	1736.05 689	1753.89 589	1710-1 755	PAS S
Ban d4	20MH z	QPSK	2030 0	100RB #0	NV	50	1736.07 882	1753.89 682	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	-30	1736.09 039	1753.89 039	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	-20	1736.08 343	1753.89 643	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	-10	1736.07 391	1753.88 691	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	0	1736.07 248	1753.89 948	1710-1 755	PAS S

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	10	1736.07 03	1753.88 13	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	20	1736.08 518	1753.89 218	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	30	1736.08 004	1753.89 904	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	40	1736.07 731	1753.90 531	1710-1 755	PAS S
Ban d4	20MH z	16QA M	2030 0	100RB #0	NV	50	1736.09 819	1753.88 519	1710-1 755	PAS S


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test Graphs






Band4-1.4MHz-QPSK-20175-6RB#0-PASS

Band4-1.4MHz-QPSK-20175-6RB#0-PASS




Band4-1.4MHz-QPSK-20175-6RB#0-PASS

Band4-1.4MHz-16QAM-20175-6RB#0-PASS



Band4-1.4MHz-16QAM-20175-6RB#0-PASS

Band4-1.4MHz-16QAM-20175-6RB#0-PASS



Band4-1.4MHz-QPSK-20393-6RB#0-PASS

Band4-1.4MHz-QPSK-20393-6RB#0-PASS