







Band26(824-849)-3MHz-QPSK-27025-15RB#0-3000~100
00-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#0-0.009~0.1
5-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#0-0.15~30-P
ASS




Band26(824-849)-3MHz-16QAM-27025-1RB#0-30~1000-P
ASS




Band26(824-849)-3MHz-16QAM-27025-1RB#0-1000~300
0-PASS



Band26(824-849)-3MHz-16QAM-27025-1RB#0-3000~100
00-PASS



Band26(824-849)-3MHz-16QAM-27025-1RB#14-0.009~0.
15-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#14-0.15~30-
PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-3MHz-16QAM-27025-1RB#14-30~1000-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#14-1000~3000-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#14-3000~10000-PASS




Band26(824-849)-3MHz-16QAM-27025-15RB#0-0.009~0.15-PASS




Band26(824-849)-3MHz-16QAM-27025-15RB#0-0.15~30-
PASS



Band26(824-849)-3MHz-16QAM-27025-15RB#0-30~1000-
PASS



Band26(824-849)-3MHz-16QAM-27025-15RB#0-1000~30
00-PASS




Band26(824-849)-3MHz-16QAM-27025-15RB#0-3000~10
000-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-26815-1RB#0-0.009~0.15-

PASS




Band26(824-849)-5MHz-QPSK-26815-1RB#0-0.15~30-PA

SS



Band26(824-849)-5MHz-QPSK-26815-1RB#0-30~1000-PA

SS




Band26(824-849)-5MHz-QPSK-26815-1RB#0-1000~3000-

PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-26815-1RB#0-3000~1000
0-PASS




Band26(824-849)-5MHz-QPSK-26815-1RB#24-0.009~0.1
5-PASS




Band26(824-849)-5MHz-QPSK-26815-1RB#24-0.15~30-P
ASS




Band26(824-849)-5MHz-QPSK-26815-1RB#24-30~1000-P
ASS




Band26(824-849)-5MHz-QPSK-26815-1RB#24-1000~300
0-PASS




Band26(824-849)-5MHz-QPSK-26815-1RB#24-3000~100
00-PASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-0.009~0.1
5-PASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-0.15~30-P
ASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-30~1000-P
ASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-1000~300
0-PASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-3000~100
00-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#0-0.009~0.1
5-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#0-0.15~30-P
ASS




Band26(824-849)-5MHz-16QAM-26815-1RB#0-30~1000-P
ASS



Band26(824-849)-5MHz-16QAM-26815-1RB#0-1000~300
0-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#0-3000~100
00-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#24-0.009~0.

15-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#24-0.15~30-

PASS



Band26(824-849)-5MHz-16QAM-26815-1RB#24-30~1000-

PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#24-1000~30

00-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-16QAM-26815-1RB#24-3000~10
000-PASS



Band26(824-849)-5MHz-16QAM-26815-25RB#0-0.009~0.
15-PASS



Band26(824-849)-5MHz-16QAM-26815-25RB#0-0.15~30-
PASS




Band26(824-849)-5MHz-16QAM-26815-25RB#0-30~1000-
PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-16QAM-26815-25RB#0-1000~30
00-PASS



Band26(824-849)-5MHz-16QAM-26815-25RB#0-3000~10
000-PASS



Band26(824-849)-5MHz-QPSK-26915-1RB#0-0.009~0.15-
PASS




Band26(824-849)-5MHz-QPSK-26915-1RB#0-0.15~30-PA
SS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-26915-1RB#0-30~1000-PA
SS




Band26(824-849)-5MHz-QPSK-26915-1RB#0-1000~3000-
PASS



Band26(824-849)-5MHz-QPSK-26915-1RB#0-3000~1000
0-PASS




Band26(824-849)-5MHz-QPSK-26915-1RB#24-0.009~0.1
5-PASS




Band26(824-849)-5MHz-QPSK-26915-1RB#24-0.15~30-P

ASS




Band26(824-849)-5MHz-QPSK-26915-1RB#24-30~1000-P

ASS



Band26(824-849)-5MHz-QPSK-26915-1RB#24-1000~300

0-PASS




Band26(824-849)-5MHz-QPSK-26915-1RB#24-3000~100

00-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-26915-25RB#0-0.009~0.1

5-PASS




Band26(824-849)-5MHz-QPSK-26915-25RB#0-0.15~30-P

ASS




Band26(824-849)-5MHz-QPSK-26915-25RB#0-30~1000-P

ASS




Band26(824-849)-5MHz-QPSK-26915-25RB#0-1000~300


0-PASS




Band26(824-849)-5MHz-QPSK-26915-25RB#0-3000~100
00-PASS



Band26(824-849)-5MHz-16QAM-26915-1RB#0-0.009~0.1
5-PASS




Band26(824-849)-5MHz-16QAM-26915-1RB#0-0.15~30-P
ASS




Band26(824-849)-5MHz-16QAM-26915-1RB#0-30~1000-P
ASS




Band26(824-849)-5MHz-16QAM-26915-1RB#0-1000~300
0-PASS




Band26(824-849)-5MHz-16QAM-26915-1RB#0-3000~100
00-PASS




Band26(824-849)-5MHz-16QAM-26915-1RB#24-0.009~0.
15-PASS




Band26(824-849)-5MHz-16QAM-26915-1RB#24-0.15~30-
PASS




Band26(824-849)-5MHz-16QAM-26915-1RB#24-30~1000-
PASS



Band26(824-849)-5MHz-16QAM-26915-1RB#24-1000~30
00-PASS



Band26(824-849)-5MHz-16QAM-26915-1RB#24-3000~10
000-PASS




Band26(824-849)-5MHz-16QAM-26915-25RB#0-0.009~0.
15-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-27015-1RB#0-0.009~0.15-

PASS




Band26(824-849)-5MHz-QPSK-27015-1RB#0-0.15~30-PA

SS



Band26(824-849)-5MHz-QPSK-27015-1RB#0-30~1000-PA

SS




Band26(824-849)-5MHz-QPSK-27015-1RB#0-1000~3000-

PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-QPSK-27015-1RB#0-3000~1000
0-PASS



Band26(824-849)-5MHz-QPSK-27015-1RB#24-0.009~0.1
5-PASS




Band26(824-849)-5MHz-QPSK-27015-1RB#24-0.15~30-P
ASS




Band26(824-849)-5MHz-QPSK-27015-1RB#24-30~1000-P
ASS




Band26(824-849)-5MHz-QPSK-27015-1RB#24-1000~300
0-PASS




Band26(824-849)-5MHz-QPSK-27015-1RB#24-3000~100
00-PASS




Band26(824-849)-5MHz-QPSK-27015-25RB#0-0.009~0.1
5-PASS




Band26(824-849)-5MHz-QPSK-27015-25RB#0-0.15~30-P
ASS




Band26(824-849)-5MHz-QPSK-27015-25RB#0-30~1000-P
ASS




Band26(824-849)-5MHz-QPSK-27015-25RB#0-1000~300
0-PASS



Band26(824-849)-5MHz-QPSK-27015-25RB#0-3000~100
00-PASS




Band26(824-849)-5MHz-16QAM-27015-1RB#0-0.009~0.1
5-PASS




Band26(824-849)-5MHz-16QAM-27015-1RB#0-0.15~30-P

ASS




Band26(824-849)-5MHz-16QAM-27015-1RB#0-30~1000-P

ASS



Band26(824-849)-5MHz-16QAM-27015-1RB#0-1000~300

0-PASS




Band26(824-849)-5MHz-16QAM-27015-1RB#0-3000~100

00-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-16QAM-27015-1RB#24-0.009~0.
15-PASS



Band26(824-849)-5MHz-16QAM-27015-1RB#24-0.15~30-
PASS



Band26(824-849)-5MHz-16QAM-27015-1RB#24-30~1000-
PASS




Band26(824-849)-5MHz-16QAM-27015-1RB#24-1000~30
00-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-16QAM-27015-1RB#24-3000~10000-PASS



Band26(824-849)-5MHz-16QAM-27015-25RB#0-0.009~0.15-PASS



Band26(824-849)-5MHz-16QAM-27015-25RB#0-0.15~30-PASS




Band26(824-849)-5MHz-16QAM-27015-25RB#0-30~1000-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-5MHz-16QAM-27015-25RB#0-1000~30
00-PASS




Band26(824-849)-5MHz-16QAM-27015-25RB#0-3000~10
000-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-0.009~0.1
5-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-0.15~30-P
ASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-30~1000-P
ASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-1000~300
0-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-3000~100
00-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#49-0.009~0.
15-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#49-0.15~30-
PASS



Band26(824-849)-10MHz-QPSK-26840-1RB#49-30~1000-
PASS



Band26(824-849)-10MHz-QPSK-26840-1RB#49-1000~3000-
00-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#49-3000~10000-
000-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-10MHz-QPSK-26840-50RB#0-0.009~0.

15-PASS




Band26(824-849)-10MHz-QPSK-26840-50RB#0-0.15~30-

PASS




Band26(824-849)-10MHz-QPSK-26840-50RB#0-30~1000-

PASS




Band26(824-849)-10MHz-QPSK-26840-50RB#0-1000~30


00-PASS




Band26(824-849)-10MHz-QPSK-26840-50RB#0-3000~10000-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#0-0.009~0.15-PASS




Band26(824-849)-10MHz-16QAM-26840-1RB#0-0.15~30-PASS




Band26(824-849)-10MHz-16QAM-26840-1RB#0-30~1000-PASS




Band26(824-849)-10MHz-16QAM-26840-1RB#0-1000~30
00-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#0-3000~10
000-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#49-0.009~0
.15-PASS




Band26(824-849)-10MHz-16QAM-26840-1RB#49-0.15~30
-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-10MHz-16QAM-26840-1RB#49-30~100
0-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#49-1000~3
000-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#49-3000~1
0000-PASS




Band26(824-849)-10MHz-16QAM-26840-50RB#0-0.009~0
.15-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-10MHz-16QAM-26840-50RB#0-0.15~30
-PASS



Band26(824-849)-10MHz-16QAM-26840-50RB#0-30~100
0-PASS



Band26(824-849)-10MHz-16QAM-26840-50RB#0-1000~3
000-PASS




Band26(824-849)-10MHz-16QAM-26840-50RB#0-3000~1
0000-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Band26(824-849)-10MHz-QPSK-26915-1RB#0-0.009~0.1

5-PASS




Band26(824-849)-10MHz-QPSK-26915-1RB#0-0.15~30-P

ASS




Band26(824-849)-10MHz-QPSK-26915-1RB#0-30~1000-P

ASS




Band26(824-849)-10MHz-QPSK-26915-1RB#0-1000~300


0-PASS




Band26(824-849)-10MHz-QPSK-26915-1RB#0-3000~10000-PASS



Band26(824-849)-10MHz-QPSK-26915-1RB#49-0.009~0.150-PASS



Band26(824-849)-10MHz-QPSK-26915-1RB#49-0.15~30-PASS



Band26(824-849)-10MHz-QPSK-26915-1RB#49-30~1000-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




00-PASS




000-PASS




15-PASS




PASS




Band26(824-849)-10MHz-QPSK-26915-50RB#0-30~1000-PASS




Band26(824-849)-10MHz-QPSK-26915-50RB#0-1000~3000-PASS




Band26(824-849)-10MHz-QPSK-26915-50RB#0-3000~10000-PASS




Band26(824-849)-10MHz-16QAM-26915-1RB#0-0.009~0.15-PASS




Band26(824-849)-10MHz-16QAM-26915-1RB#0-0.15~30-
PASS



Band26(824-849)-10MHz-16QAM-26915-1RB#0-30~1000-
PASS



Band26(824-849)-10MHz-16QAM-26915-1RB#0-1000~30
00-PASS



Band26(824-849)-10MHz-16QAM-26915-1RB#0-3000~10
000-PASS