
































	
Band2-10MHz-16QAM-18650-50RB#0-0.15~30- PASS	Band2-10MHz-16QAM-18650-50RB#0-30~1000- PASS
	
Band2-10MHz-16QAM-18650-50RB#0-1000~30 00-PASS	Band2-10MHz-16QAM-18650-50RB#0-3000~20 000-PASS
	
Band2-10MHz-QPSK-18900-1RB#0-0.009~0.15- PASS	Band2-10MHz-QPSK-18900-1RB#0-0.15~30-PA SS












Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






















	
Band2-15MHz-16QAM-18675-1RB#0-0.009~0.1 5-PASS	Band2-15MHz-16QAM-18675-1RB#0-0.15~30-P ASS
	
Band2-15MHz-16QAM-18675-1RB#0-30~1000-P ASS	Band2-15MHz-16QAM-18675-1RB#0-1000~300 0-PASS
	
Band2-15MHz-16QAM-18675-1RB#0-3000~200 00-PASS	Band2-15MHz-16QAM-18675-1RB#74-0.009~0. 15-PASS

