

Item	Mark	Description
1	CPK	Critical dimension for in-cone quality control
2	FAT	Critical dimension for more tooling quality control