











Freq. Stability -10C 120V n20 5785MHz Ant1 0 Minutes







Date: 4.JUN.2025 13:27:12



Freq. Stability 0C 120V n20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:27:17








Freq. Stability 20C 138V n20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 13:32:11

Freq. Stability -20C 120V n20 5825MHz Ant1 0 Minutes






Date: 4.JUN.2025 13:32:16



Freq. Stability -10C 120V n20 5825MHz Ant1 0 Minutes







Freq. Stability 0C 120V n20 5825MHz Ant1 0 Minutes

































Freq. Stability -10C 120V n40 5230MHz Ant1 0 Minutes



Date: 4.JUN.2025 15:08:30

Freq. Stability 0C 120V n40 5230MHz Ant1 0 Minutes



Date: 4.JUN.2025 15:08:37

