




Freq. Stability 20C 102V ac20 5785MHz Ant1 0 Minutes



Freq. Stability 20C 120V ac20 5785MHz Ant1 0 Minutes




Freq. Stability 20C 138V ac20 5785MHz Ant1 0 Minutes





Date: 4.JUN.2025 14:13:35


Freq. Stability -20C 120V ac20 5785MHz Ant1 0 Minutes



Date: 4.JUN.2025 14:13:40




Freq. Stability 10C 120V ac20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:13:56

Freq. Stability 30C 120V ac20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:14:07

Freq. Stability 40C 120V ac20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:14:12

Freq. Stability 50C 120V ac20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:14:17

Freq. Stability 20C 102V ac20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:17:18

Freq. Stability 20C 120V ac20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:17:55

Freq. Stability 20C 138V ac20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:17:28

Freq. Stability -20C 120V ac20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:17:34


Freq. Stability -10C 120V ac20 5825MHz Ant1 0 Minutes



Freq. Stability 0C 120V ac20 5825MHz Ant1 0 Minutes




Freq. Stability 10C 120V ac20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:17:49

Freq. Stability 30C 120V ac20 5825MHz Ant1 0 Minutes






Date: 4.JUN.2025 14:18:00



Freq. Stability 40C 120V ac20 5825MHz Ant1 0 Minutes





Freq. Stability 50C 120V ac20 5825MHz Ant1 0 Minutes











Freq. Stability 10C 120V ac40 5190MHz Ant1 0 Minutes







Date: 4.JUN.2025 15:46:13

Freq. Stability 30C 120V ac40 5190MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:46:27






Freq. Stability 20C 138V ac40 5230MHz Ant1 0 Minutes







Date: 4.JUN.2025 15:49:21


Freq. Stability -20C 120V ac40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:49:28













Date: 4.JUN.2025 15:50:10







Date: 4.JUN.2025 15:50:17





















Date: 4.JUN.2025 15:56:14







Date: 4.JUN.2025 15:57:04





















Freq. Stability 10C 120V ac40 5510MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:00:25

Freq. Stability 30C 120V ac40 5510MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:00:39

