



















Freq. Stability 10C 120V ax20 5785MHz Ant1 0 Minutes





Freq. Stability 30C 120V ax20 5785MHz Ant1 0 Minutes












Freq. Stability -10C 120V ax20 5825MHz Ant1 0 Minutes



Freq. Stability 0C 120V ax20 5825MHz Ant1 0 Minutes




Freq. Stability 10C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:05

Freq. Stability 30C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:15

Freq. Stability 40C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:21

Freq. Stability 50C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:26

Freq. Stability 20C 102V ax40 5190MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:20:53

Freq. Stability 20C 120V ax40 5190MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:21:43

Freq. Stability 20C 138V ax40 5190MHz Ant1 0 Minutes





Date: 4.JUN.2025 16:21:08


Freq. Stability -20C 120V ax40 5190MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:21:15




Freq. Stability 10C 120V ax40 5190MHz Ant1 0 Minutes





Date: 4.JUN.2025 16:21:36


Freq. Stability 30C 120V ax40 5190MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:21:50




Freq. Stability 20C 102V ax40 5230MHz Ant1 0 Minutes





Date: 4.JUN.2025 16:24:36


Freq. Stability 20C 120V ax40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:25:25




Freq. Stability -10C 120V ax40 5230MHz Ant1 0 Minutes



Freq. Stability 0C 120V ax40 5230MHz Ant1 0 Minutes




Freq. Stability 10C 120V ax40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:25:18

Freq. Stability 30C 120V ax40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:25:33

Freq. Stability 40C 120V ax40 5230MHz Ant1 0 Minutes







Date: 4.JUN.2025 16:25:39

Freq. Stability 50C 120V ax40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:25:46







Freq. Stability -10C 120V ax40 5270MHz Ant1 0 Minutes



Freq. Stability 0C 120V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 10C 120V ax40 5270MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:29:19

Freq. Stability 30C 120V ax40 5270MHz Ant1 0 Minutes






Date: 4.JUN.2025 16:29:33



Freq. Stability 40C 120V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 50C 120V ax40 5270MHz Ant1 0 Minutes








Freq. Stability -10C 120V ax40 5310MHz Ant1 0 Minutes







Date: 4.JUN.2025 16:32:56

Freq. Stability 0C 120V ax40 5310MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:33:03






Freq. Stability 20C 102V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:36:58

Freq. Stability 20C 120V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:37:48

Freq. Stability 20C 138V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:37:12

Freq. Stability -20C 120V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:37:20


Freq. Stability -10C 120V ax40 5510MHz Ant1 0 Minutes



Freq. Stability 0C 120V ax40 5510MHz Ant1 0 Minutes



Freq. Stability 10C 120V ax40 5510MHz Ant1 0 Minutes



Freq. Stability 30C 120V ax40 5510MHz Ant1 0 Minutes

