





2DH5_Ant1_2441_30~1000




2DH5_Ant1_2441_1000~26500




2DH5_Ant1_2480_0~Reference




2DH5_Ant1_2480_30~1000




2DH5_Ant1_2480_1000~26500




3DH5_Ant1_2402_0~Reference



3DH5_Ant1_2402_30~1000




3DH5_Ant1_2402_1000~26500




3DH5_Ant1_2441_0~Reference




3DH5_Ant1_2441_30~1000




3DH5_Ant1_2441_1000~26500




3DH5_Ant1_2480_0~Reference



3DH5_Ant1_2480_30~1000



3DH5_Ant1_2480_1000~26500





Appendix I: Duty Cycle

Test Result


TestMode	Antenna	Freq(MHz)	ON Time [ms]	Period [ms]	DC [%]	xFactor	Limit	Verdict
DH5	Ant1	2402	2.88	3.73	77.21	1.12	---	---
		2441	2.89	3.73	77.48	1.11	---	---
		2480	2.89	3.73	77.48	1.11	---	---
2DH5	Ant1	2402	2.89	3.73	77.48	1.11	---	---
		2441	2.89	3.74	77.27	1.12	---	---
		2480	2.89	3.74	77.27	1.12	---	---
3DH5	Ant1	2402	2.89	3.74	77.27	1.12	---	---
		2441	2.89	3.74	77.27	1.12	---	---
		2480	2.89	3.74	77.27	1.12	---	---

Test Graphs







2DH5_Ant1_2402




2DH5_Ant1_2441




2DH5_Ant1_2480



3DH5_Ant1_2402



3DH5_Ant1_2441



3DH5_Ant1_2480

