# Appendix Test Data

| | | | |
|---|---|---|---|
| Report No.: | 1819C50111212501-01 | Test Sample No.: | 1-2-2 |
| Start Test Date: | 2025-10-14 | Finish Test Date: | 2025-10-14 |
| Test Engineer: | Alex Peng | Auditor: | Justin Feng |
| Temperature: | 25.4℃ | Relative Humidity: | 64% |
| Pressure: | 101kPa | | |

## Appendix A: 20dB Bandwidth

### Test Result

| Test Mode | Antenna | Frequency [MHz] | 20db EBW[MHz] | FL[MHz] | FH[MHz] | Limit[MHz] | Verdict |
|---|---|---|---|---|---|---|---|
| DH5 | Ant1 | 2402 | 0.957 | 2401.589 | 2402.546 | --- | --- |
| DH5 | Ant1 | 2441 | 0.945 | 2440.589 | 2441.534 | --- | --- |
| DH5 | Ant1 | 2480 | 0.957 | 2479.586 | 2480.543 | --- | --- |
| 2DH5 | Ant1 | 2402 | 1.284 | 2401.421 | 2402.705 | --- | --- |
| 2DH5 | Ant1 | 2441 | 1.290 | 2440.418 | 2441.708 | --- | --- |
| 2DH5 | Ant1 | 2480 | 1.281 | 2479.424 | 2480.705 | --- | --- |
| 3DH5 | Ant1 | 2402 | 1.314 | 2401.403 | 2402.717 | --- | --- |
| 3DH5 | Ant1 | 2441 | 1.299 | 2440.412 | 2441.711 | --- | --- |
| 3DH5 | Ant1 | 2480 | 1.308 | 2479.409 | 2480.717 | --- | --- |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

## Test Graphs

DH5-Ant1-2402

DH5-Ant1-2441


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

DH5-Ant1-2480

2DH5-Ant1-2402



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

2DH5-Ant1-2441

2DH5-Ant1-2480



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

3DH5-Ant1-2402

3DH5-Ant1-2441



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

3DH5-Ant1-2480



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix B: 99% Occupied Bandwidth

## Test Result

| Test Mode | Antenna | Frequency [MHz] | OCB [MHz] | FL[MHz] | FH[MHz] | Limit[MHz] | Verdict |
|---|---|---|---|---|---|---|---|
| DH5 | Ant1 | 2402 | 0.87543 | 2401.6122 | 2402.4876 | --- | --- |
| DH5 | Ant1 | 2441 | 0.88045 | 2440.6132 | 2441.4936 | --- | --- |
| DH5 | Ant1 | 2480 | 0.87439 | 2479.6157 | 2480.4900 | --- | --- |
| 2DH5 | Ant1 | 2402 | 1.1823 | 2401.4650 | 2402.6473 | --- | --- |
| 2DH5 | Ant1 | 2441 | 1.1837 | 2440.4610 | 2441.6447 | --- | --- |
| 2DH5 | Ant1 | 2480 | 1.1811 | 2479.4599 | 2480.6410 | --- | --- |
| 3DH5 | Ant1 | 2402 | 1.1981 | 2401.4521 | 2402.6502 | --- | --- |
| 3DH5 | Ant1 | 2441 | 1.1846 | 2440.4585 | 2441.6431 | --- | --- |
| 3DH5 | Ant1 | 2480 | 1.1878 | 2479.4608 | 2480.6486 | --- | --- |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

## Test Graphs

DH5-Ant1-2402




DH5-Ant1-2441


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

DH5-Ant1-2480




2DH5-Ant1-2402



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

2DH5-Ant1-2441

2DH5-Ant1-2480



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




3DH5-Ant1-2402

3DH5-Ant1-2441



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

3DH5-Ant1-2480



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix C: Maximum Conducted Output Power

## Test Result Peak

| Test Mode | Antenna | Frequency[MHz] | Conducted Peak Power[dBm] | Conducted Limit[dBm] | Verdict |
|---|---|---|---|---|---|
| DH5 | Ant1 | 2402 | 1.58 | ≤20.97 | PASS |
| DH5 | Ant1 | 2441 | 1.47 | ≤20.97 | PASS |
| DH5 | Ant1 | 2480 | 0.87 | ≤20.97 | PASS |
| 2DH5 | Ant1 | 2402 | 2.49 | ≤20.97 | PASS |
| 2DH5 | Ant1 | 2441 | 2.33 | ≤20.97 | PASS |
| 2DH5 | Ant1 | 2480 | 1.72 | ≤20.97 | PASS |
| 3DH5 | Ant1 | 2402 | **2.95** | ≤20.97 | PASS |
| 3DH5 | Ant1 | 2441 | 2.77 | ≤20.97 | PASS |
| 3DH5 | Ant1 | 2480 | 2.13 | ≤20.97 | PASS |

## Test Graphs




DH5-Ant1-2402-PASS


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




DH5-Ant1-2441-PASS




DH5-Ant1-2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




2DH5-Ant1-2402-PASS




2DH5-Ant1-2441-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




2DH5-Ant1-2480-PASS




3DH5-Ant1-2402-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-2441-PASS




3DH5-Ant1-2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

# Appendix D: Carrier frequency separation

## Test Result

| Test Mode | Antenna | Frequency [MHz] | Result [MHz] | Limit[MHz] | Verdict |
|---|---|---|---|---|---|
| DH5 | Ant1 | Hop | 0.86 | ≥0.638 | PASS |
| 2DH5 | Ant1 | Hop | 1.154 | ≥0.860 | PASS |
| 3DH5 | Ant1 | Hop | 1.202 | ≥0.876 | PASS |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

## Test Graphs

DH5-Ant1-Hop-PASS

2DH5-Ant1-Hop-PASS


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

3DH5-Ant1-Hop-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix E: Dwell Time

## Test Result

| Test Mode | Antenna | Frequency [MHz] | Burst Width [ms] | Total Hops [Num] | Result [s] | Limit [s] | Verdict |
|---|---|---|---|---|---|---|---|
| DH5 | Ant1 | Hop | 2.885 | 88 | 0.254 | ≤0.4 | PASS |
| 2DH5 | Ant1 | Hop | 2.891 | 99 | 0.286 | ≤0.4 | PASS |
| 3DH5 | Ant1 | Hop | 2.892 | 95 | 0.275 | ≤0.4 | PASS |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

## Test Graphs




DH5-Ant1-Hop-PASS





Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-Hop-PASS





Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-Hop-PASS





Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix F: Number of Hopping Channel

## Test Result

| Test Mode | Antenna | Frequency [MHz] | Result [Num] | Limit [Num] | Verdict |
|---|---|---|---|---|---|
| DH5 | Ant1 | Hop | 79 | ≥15 | PASS |
| 2DH5 | Ant1 | Hop | 79 | ≥15 | PASS |
| 3DH5 | Ant1 | Hop | 79 | ≥15 | PASS |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

## Test Graphs




DH5-Ant1-Hop-PASS




2DH5-Ant1-Hop-PASS


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-Hop-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix G: Conducted Band edge

## Test Result

| Test Mode | Antenna | Ch. Name | Frequency [MHz] | Ref. Level [dBm] | Result [dBm] | Limit [dBm] | Verdict |
|---|---|---|---|---|---|---|---|
| DH5 | Ant1 | Low | 2402 | 1.46 | -50.73 | ≤-18.54 | PASS |
| DH5 | Ant1 | High | 2480 | 0.69 | -51.49 | ≤-19.31 | PASS |
| DH5 | Ant1 | Low | Hop_2402 | 1.28 | -49.53 | ≤-18.72 | PASS |
| DH5 | Ant1 | High | Hop_2480 | 0.64 | -49.24 | ≤-19.36 | PASS |
| 2DH5 | Ant1 | Low | 2402 | 1.46 | -51.49 | ≤-18.54 | PASS |
| 2DH5 | Ant1 | High | 2480 | 0.71 | -53.18 | ≤-19.29 | PASS |
| 2DH5 | Ant1 | Low | Hop_2402 | -1.68 | -50.28 | ≤-21.68 | PASS |
| 2DH5 | Ant1 | High | Hop_2480 | 0.13 | -49.84 | ≤-19.87 | PASS |
| 3DH5 | Ant1 | Low | 2402 | 1.44 | -50.84 | ≤-18.56 | PASS |
| 3DH5 | Ant1 | High | 2480 | 0.48 | -53.62 | ≤-19.52 | PASS |
| 3DH5 | Ant1 | Low | Hop_2402 | -0.62 | -50.52 | ≤-20.62 | PASS |
| 3DH5 | Ant1 | High | Hop_2480 | 0.06 | -48.47 | ≤-19.94 | PASS |

Remark:Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose have been set in the 'offset' of the Spectrum Analyzer during the test.


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

## Test Graphs




DH5-Ant1-2402-PASS




DH5-Ant1-2480-PASS


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




DH5-Ant1-Hop_2402-PASS




DH5-Ant1-Hop_2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-2402-PASS




2DH5-Ant1-2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-Hop_2402-PASS




2DH5-Ant1-Hop_2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-2402-PASS




3DH5-Ant1-2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




3DH5-Ant1-Hop_2402-PASS




3DH5-Ant1-Hop_2480-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix H: Conducted Spurious Emission

## Test Result

| Test Mode | Antenna | Frequency[MHz] | Freq. Range [MHz] | Ref. Level [dBm] | Result [dBm] | Limit [dBm] | Verdict |
|---|---|---|---|---|---|---|---|
| DH5 | Ant1 | 2402 | 0~Reference | 0.68 | 0.68 | --- | PASS |
| DH5 | Ant1 | 2402 | 30~1000 | 0.68 | -69.57 | ≤-19.32 | PASS |
| DH5 | Ant1 | 2402 | 1000~26500 | 0.68 | -39.88 | ≤-19.32 | PASS |
| DH5 | Ant1 | 2441 | 0~Reference | 0.63 | 0.63 | --- | PASS |
| DH5 | Ant1 | 2441 | 30~1000 | 0.63 | -68.98 | ≤-19.37 | PASS |
| DH5 | Ant1 | 2441 | 1000~26500 | 0.63 | -39.98 | ≤-19.37 | PASS |
| DH5 | Ant1 | 2480 | 0~Reference | 0.30 | 0.30 | --- | PASS |
| DH5 | Ant1 | 2480 | 30~1000 | 0.30 | -68.62 | ≤-19.7 | PASS |
| DH5 | Ant1 | 2480 | 1000~26500 | 0.30 | -42.28 | ≤-19.7 | PASS |
| 2DH5 | Ant1 | 2402 | 0~Reference | -1.33 | -1.33 | --- | PASS |
| 2DH5 | Ant1 | 2402 | 30~1000 | -1.33 | -68.98 | ≤-21.33 | PASS |
| 2DH5 | Ant1 | 2402 | 1000~26500 | -1.33 | -39.49 | ≤-21.33 | PASS |
| 2DH5 | Ant1 | 2441 | 0~Reference | -0.08 | -0.08 | --- | PASS |
| 2DH5 | Ant1 | 2441 | 30~1000 | -0.08 | -68.4 | ≤-20.08 | PASS |
| 2DH5 | Ant1 | 2441 | 1000~26500 | -0.08 | -39.95 | ≤-20.08 | PASS |
| 2DH5 | Ant1 | 2480 | 0~Reference | 0.67 | 0.67 | --- | PASS |
| 2DH5 | Ant1 | 2480 | 30~1000 | 0.67 | -69.36 | ≤-19.33 | PASS |
| 2DH5 | Ant1 | 2480 | 1000~26500 | 0.67 | -42.35 | ≤-19.33 | PASS |
| 3DH5 | Ant1 | 2402 | 0~Reference | 0.72 | 0.72 | --- | PASS |
| 3DH5 | Ant1 | 2402 | 30~1000 | 0.72 | -69.17 | ≤-19.28 | PASS |
| 3DH5 | Ant1 | 2402 | 1000~26500 | 0.72 | -39.36 | ≤-19.28 | PASS |
| 3DH5 | Ant1 | 2441 | 0~Reference | -2.55 | -2.55 | --- | PASS |
| 3DH5 | Ant1 | 2441 | 30~1000 | -2.55 | -69.65 | ≤-22.55 | PASS |
| 3DH5 | Ant1 | 2441 | 1000~26500 | -2.55 | -40.27 | ≤-22.55 | PASS |
| 3DH5 | Ant1 | 2480 | 0~Reference | -0.65 | -0.65 | --- | PASS |
| 3DH5 | Ant1 | 2480 | 30~1000 | -0.65 | -68.52 | ≤-20.65 | PASS |
| 3DH5 | Ant1 | 2480 | 1000~26500 | -0.65 | -42.23 | ≤-20.65 | PASS |

Remark:Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose and attenuator factors have been set in the 'Input Correction' of the Spectrum Analyzer during the test.


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

## Test Graphs




DH5-Ant1-2402-0~Reference-PASS




DH5-Ant1-2402-30~1000-PASS


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




DH5-Ant1-2402-1000~26500-PASS

DH5-Ant1-2441-0~Reference-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




DH5-Ant1-2441-30~1000-PASS




DH5-Ant1-2441-1000~26500-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




DH5-Ant1-2480-0~Reference-PASS




DH5-Ant1-2480-30~1000-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




DH5-Ant1-2480-1000~26500-PASS




2DH5-Ant1-2402-0~Reference-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-2402-30~1000-PASS




2DH5-Ant1-2402-1000~26500-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




2DH5-Ant1-2441-0~Reference-PASS




2DH5-Ant1-2441-30~1000-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-2441-1000~26500-PASS




2DH5-Ant1-2480-0~Reference-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




2DH5-Ant1-2480-30~1000-PASS




2DH5-Ant1-2480-1000~26500-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

3DH5-Ant1-2402-0~Reference-PASS




3DH5-Ant1-2402-30~1000-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




3DH5-Ant1-2402-1000~26500-PASS




3DH5-Ant1-2441-0~Reference-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-2441-30~1000-PASS




3DH5-Ant1-2441-1000~26500-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




3DH5-Ant1-2480-0~Reference-PASS




3DH5-Ant1-2480-30~1000-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




3DH5-Ant1-2480-1000~26500-PASS



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

# Appendix I: Duty Cycle

## Test Result

| Test Mode | Antenna | Frequency[MHz] | ON Time [ms] | Period [ms] | Duty Cycle [%] | Duty Cycle Factor[dB] |
|---|---|---|---|---|---|---|
| DH5 | Ant1 | 2402 | 2.89 | 3.75 | 77.07 | 1.13 |
| DH5 | Ant1 | 2441 | 2.90 | 3.75 | 77.33 | 1.12 |
| DH5 | Ant1 | 2480 | 2.89 | 3.75 | 77.07 | 1.13 |
| 2DH5 | Ant1 | 2402 | 2.88 | 3.75 | 76.80 | 1.15 |
| 2DH5 | Ant1 | 2441 | 2.89 | 3.75 | 77.07 | 1.13 |
| 2DH5 | Ant1 | 2480 | 2.90 | 3.75 | 77.33 | 1.12 |
| 3DH5 | Ant1 | 2402 | 2.89 | 3.75 | 77.07 | 1.13 |
| 3DH5 | Ant1 | 2441 | 2.89 | 3.75 | 77.07 | 1.13 |
| 3DH5 | Ant1 | 2480 | 2.89 | 3.75 | 77.07 | 1.13 |


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

## Test Graphs




NTNV-DH5-Ant1-2402




NTNV-DH5-Ant1-2441


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




NTNV-DH5-Ant1-2480




NTNV-2DH5-Ant1-2402



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




NTNV-2DH5-Ant1-2441




NTNV-2DH5-Ant1-2480



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




NTNV-3DH5-Ant1-2402




NTNV-3DH5-Ant1-2441



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.




NTNV-3DH5-Ant1-2480

---End---



Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.