



Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:17:30

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:18:15

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:19:02

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:20:58

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:22:31

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:24:05

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:27:07

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:28:39

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:30:12

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:33:02

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:34:35


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 15:36:08

Band 66, Normal**1RB was the worst case****1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)**


ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:34:30

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:35:12

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:35:56

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)

ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:37:42


3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)

ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:38:25

3MHz_High_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:39:07

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:39:51

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:40:34

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:41:17

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:43:40

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:45:06

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester: Braylon Ma
Date: 11.FEB.2026 14:46:31

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:48:00

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:49:25

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:50:50

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:52:17

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:53:42

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607P22096E-RF Tester:Braydon Ma
Date: 11.FEB.2026 14:55:06