



Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:49:24

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:50:14

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:51:11

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:55:53

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:57:48

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Testers:Braylon Ma
Date: 26.SEP.2025 09:59:44

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:01:56

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:03:46

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:08:43

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:11:00

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:13:02


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2507W16832E-RF Tester:Braylon Ma
Date: 26.SEP.2025 10:15:00


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:11:02

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:11:45

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:12:28

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:13:55

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:14:39

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 12507W16832E-RF Testers: Baylon Ma
Date: 25.SEP.2025 18:15:25

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:16:11

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:16:56

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:17:40

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:19:59

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:21:29

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Braylon Ma
Date: 25.SEP.2025 18:22:59

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:24:56

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:26:30

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:28:01

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:30:34

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:32:09

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507W16832E-RF Tester: Breydon Ma
Date: 25-SEP-2025 18:33:41