



Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:38:11

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:38:56

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:39:41

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:41:58

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:43:29

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:45:00

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:47:57

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:49:28

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:50:58

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:52:57

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:54:28


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 09:56:01


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:39:23

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:40:04

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:40:45

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:41:34

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:42:14

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:42:55

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:43:47

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:44:28

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:45:09

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:46:04

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:47:26

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester: Braylon Ma
Date: 13.NOV.2025 07:48:47

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:50:58

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:52:18

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:53:40

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:55:05

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:56:26

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Y29590E-RF Tester:Braylon Ma
Date: 13.NOV.2025 07:57:57