



## Test Graphs



## Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)





### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)








## Appendix H: Conducted Spurious Emission

### Test Result

| Test Mode | Antenna | Frequency[MHz] | Freq. Range [MHz] | Ref. Level [dBm] | Result [dBm] | Limit [dBm] | Verdict |
|-----------|---------|----------------|-------------------|------------------|--------------|-------------|---------|
| DH5       | Ant1    | 2402           | 0~Reference       | -2.68            | -2.68        | ---         | PASS    |
| DH5       | Ant1    | 2402           | 30~1000           | -2.68            | -51.81       | ≤-22.68     | PASS    |
| DH5       | Ant1    | 2402           | 1000~26500        | -2.68            | -37.1        | ≤-22.68     | PASS    |
| DH5       | Ant1    | 2441           | 0~Reference       | -2.25            | -2.25        | ---         | PASS    |
| DH5       | Ant1    | 2441           | 30~1000           | -2.25            | -52.27       | ≤-22.25     | PASS    |
| DH5       | Ant1    | 2441           | 1000~26500        | -2.25            | -37.22       | ≤-22.25     | PASS    |
| DH5       | Ant1    | 2480           | 0~Reference       | -2.40            | -2.40        | ---         | PASS    |
| DH5       | Ant1    | 2480           | 30~1000           | -2.40            | -51.48       | ≤-22.4      | PASS    |
| DH5       | Ant1    | 2480           | 1000~26500        | -2.40            | -37.35       | ≤-22.4      | PASS    |
| 2DH5      | Ant1    | 2402           | 0~Reference       | -2.46            | -2.46        | ---         | PASS    |
| 2DH5      | Ant1    | 2402           | 30~1000           | -2.46            | -52.59       | ≤-22.46     | PASS    |
| 2DH5      | Ant1    | 2402           | 1000~26500        | -2.46            | -36.94       | ≤-22.46     | PASS    |
| 2DH5      | Ant1    | 2441           | 0~Reference       | -2.16            | -2.16        | ---         | PASS    |
| 2DH5      | Ant1    | 2441           | 30~1000           | -2.16            | -37.13       | ≤-22.16     | PASS    |
| 2DH5      | Ant1    | 2441           | 1000~26500        | -2.16            | -37.15       | ≤-22.16     | PASS    |
| 2DH5      | Ant1    | 2480           | 0~Reference       | -2.06            | -2.06        | ---         | PASS    |
| 2DH5      | Ant1    | 2480           | 30~1000           | -2.06            | -51.95       | ≤-22.06     | PASS    |
| 2DH5      | Ant1    | 2480           | 1000~26500        | -2.06            | -35.15       | ≤-22.06     | PASS    |
| 3DH5      | Ant1    | 2402           | 0~Reference       | -2.77            | -2.77        | ---         | PASS    |
| 3DH5      | Ant1    | 2402           | 30~1000           | -2.77            | -52.43       | ≤-22.77     | PASS    |
| 3DH5      | Ant1    | 2402           | 1000~26500        | -2.77            | -36.87       | ≤-22.77     | PASS    |
| 3DH5      | Ant1    | 2441           | 0~Reference       | -2.76            | -2.76        | ---         | PASS    |
| 3DH5      | Ant1    | 2441           | 30~1000           | -2.76            | -51.94       | ≤-22.76     | PASS    |
| 3DH5      | Ant1    | 2441           | 1000~26500        | -2.76            | -37.52       | ≤-22.76     | PASS    |
| 3DH5      | Ant1    | 2480           | 0~Reference       | -2.16            | -2.16        | ---         | PASS    |
| 3DH5      | Ant1    | 2480           | 30~1000           | -2.16            | -51.97       | ≤-22.16     | PASS    |
| 3DH5      | Ant1    | 2480           | 1000~26500        | -2.16            | -37.07       | ≤-22.16     | PASS    |

Remark:Regarding the spurious emissions from 30MHz to 26.5GHz, the cable loss have been set in the 'Input Correction' of the Spectrum Analyzer during the test.

## Test Graphs



## Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



**Shenzhen Anbotek Compliance Laboratory Limited**

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)

## Appendix I: Duty Cycle

### Test Result

| Test Mode | Antenna | Frequency[MHz] | ON Time<br>[ms] | Period<br>[ms] | Duty Cycle<br>[%] | Duty Cycle<br>Factor[dB] |
|-----------|---------|----------------|-----------------|----------------|-------------------|--------------------------|
| DH5       | Ant1    | 2402           | 2.88            | 3.75           | 76.80             | 1.15                     |
| DH5       | Ant1    | 2441           | 2.88            | 3.75           | 76.80             | 1.15                     |
| DH5       | Ant1    | 2480           | 2.88            | 3.75           | 76.80             | 1.15                     |
| 2DH5      | Ant1    | 2402           | 2.88            | 3.75           | 76.80             | 1.15                     |
| 2DH5      | Ant1    | 2441           | 2.89            | 3.75           | 77.07             | 1.13                     |
| 2DH5      | Ant1    | 2480           | 2.89            | 3.75           | 77.07             | 1.13                     |
| 3DH5      | Ant1    | 2402           | 2.88            | 3.75           | 76.80             | 1.15                     |
| 3DH5      | Ant1    | 2441           | 2.88            | 3.75           | 76.80             | 1.15                     |
| 3DH5      | Ant1    | 2480           | 2.89            | 3.75           | 77.07             | 1.13                     |


## Test Graphs



## Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)




#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






#### Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: [www.anbotek.com](http://www.anbotek.com) E-mail: [service@anbotek.com](mailto:service@anbotek.com)



---End---