



Shenzhen Haiyun Standard Technical CO., Ltd.

1. Did a test Firm or third party (other than the certification body and applicant) provide a list of software installed on the device and after scan results with no evidence of Kaspersky software.



2. Has other objective evidence been provided that no Kaspersky software is installed.

Shenzhen Haiyun Standard Technical CO., Ltd.



After plugging in the USB drive, the software to be installed can not appear,
so software cannot be installed via EUT USB port.

Sincerely,

Black Ding

Name / Title: Black Ding / Manager

Company Name: Shenzhen Haiyun Standard Technical CO., Ltd.

Address: 101, Building B1, Fuqiao Fourth Area, Qiaotou Community, Fuhai
Subdistrict, Baoan District, Shenzhen, Guangdong, China

Tel: 13317943906

E-Mail: dingxuanfeng@hy-lab.cn