

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)





FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Left Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)



FCC ID: 2B03PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Left Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)




FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Left Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)




FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Left Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)



FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Left Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)




FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Right Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)




FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Right Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)





FCC ID: 2B03PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Right Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)





FCC ID: 2B03PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Right Earbud

INTERTEK TESTING SERVICES

Equipment Photographs

(Internal)



FCC ID: 2BO3PGRVZ-PRO
IC: 33938-GRVZPRO
Remark: Right Earbud